



भारत सरकार
Government of India
विद्युत मंत्रालय
Ministry of Power
उत्तर क्षेत्रीय विद्युत समिति
Northern Regional Power Committee

No. उक्षेविस/प्रचालन/107/01/2018/ 13392-430

दिनांक: 29.11.2018

फैक्स संदेश / FAX MESSAGE

सेवा में : संरक्षण उप-समिति के सदस्य (सूची के अनुसार) ।

To: Members of Protection Sub-Committee (As per List)

विषय: संरक्षण उप-समिति की 36 वीं बैठक का कार्यवृत्त ।

Subject: Minutes of 36th Protection Sub-Committee Meeting.

संरक्षण उप-समिति की 36वीं बैठक, 19.09.2018 को 10:30 बजे से उ.क्षे.वि.स. सचिवालय, नई दिल्ली में आयोजित की गई थी। उक्त बैठक का कार्यवृत्त उत्तर क्षेत्रीय विद्युत् समिति की वेबसाइट (<http://www.nrpc.gov.in>) पर उपलब्ध है।

The 36th meeting of Protection Sub-Committee was held on **19th September, 2018** at **10:30 Hrs** at **NRPC Secretariat, New Delhi**. The minute of the meeting is available on NRPC website (<http://www.nrpc.gov.in>).

OK
28.11.18

(Upendra Kumar)
Superintending Engineer (P)

List of Members of PSC

S.No.	Designation	Organization	Fax No.
1	Director (P&C)	BBMB	0172-2652054
2	General Manager (SLDC)	DTL	011-23236462
3	GM (O&M)	Delhi Transco Limited	011-23236462
4	GM (T)	Common Services IPGCL	23370247
5	Chief Engineer (TS)	HVPNL	0172-2591244
6	SE (M&P)	HVPNL	0172-2540014
7	SE (SO & SLDC)	HVPNL	0172-2560622
8	SE (SLDC)	PTCUL	0135-2763570/2451160
9	SE(T&C)	PTCUL	0135-2451826
10	Chief Engineer (SLDC)	UPPTCL	0522-2287880/2288736
11	SE(Tech)	HPGCL	0172-5022436
12	SE(O&M-VI)	HPGCL	0180-2566768
13	Chief Engineer (Transmission)	HPSEB	01972-223435
14	SE (PR& ALDC)	HPSEB	0177-2837143
15	Chief Engineer (C&S Wing)	PDD	0191-2474233
16	Chief Engineer (SLDC)	PSTCL	0175-2365340
17	Chief Engineer (P&M)	PSTCL	0161-2741280/2451491
18	CE (M&P)	RRVPNL	0141-2291891
19	SE (Electrical)	RRVUNL	01509-245299
20	Chief Engineer (LD)	RRVPNL	0141-2740920
21	SE (SO&LD)	RRVPNL	0141-2740920
22	Superintending Engineer (T&C)	UPPCL	0121-2666062
23	Chief Engineer, (L-2)	UPRVUNL	0522-2287822/2287880
24	DGM (T&C)	PTCUL	0135-2760331
25	Chief Engineer (O&M)	NHPC	0129-2272413
26	GM (O&M) NR – I	PGCIL	011-26601079
27	GM (O&M), NR-II	PGCIL	01951-237186
28	Chief Manager (TS)	N.R.L.D.C	011-26852747
29	GM(OS-NR)	NTPC	0522-2305848
30	GM (OS)	NTPC Ltd	0120-2410082/2410068
31	DGM (Maintenance)	SJVNL	0177-2673283
32	DGM (O&M)	THDC India Ltd	01376-236305
33	Director (GM division)	CEA	011-26109750
34	General Manager	APCLP	01251-266326
35	Director	JPPVL	0120-4516201/4609464/4609496
36	Assistant Vice President	BRPL	39996055/39999765
37	GM (Production)	Jhajjar Power Ltd	01251-270155
38	GM(P&M)	APL	7925557176
39	Sh. Umesh Gupta, AsVP	BRPL	011-26419833
40	President (Power Systems)	LPGCL	+91-22- 22048681
41	Director (NPC)	CEA	
42	NPCIL		
	1.Maintenance Superintendent	NAPS	05734-222167
	2.Maintenance Superintendent	RAPS	01475-242060

INDEX

PART-A: NRPC

A.1. Confirmation of minutes of 35th meeting of protection sub-committee	4
A.2. Implementation of Recommendations of Task Force.....	4
A.2.1. Database of protection settings	4
A.2.2. Periodicity of Third Party Protection Audit	6
A.2.2.1 Training Programme/Workshop on Protection Audit for Protection system Engineers.....	8
A.3 Violation of Protection standard in case of Inter-Regional lines of voltage 220kV and above	8
A.4 Actions taken on the outcome of the meeting of Protection Analysis Sub Group (PSAG)	11
A.5 Grid disturbance at NAPS on 15.02.2018 due to Bus fault at 220kV Atrauli S/S (Agenda by NPCIL)	12
A.6 Final report of the group to suggest measures for bringing improvement in the field of Power System Protection among the utilities in Northern Region.....	13
A.7. Format for Detailed Analysis report.....	14
A.8. Follow up action on outstanding issues from previous meetings:	15
A.8.1. Non- availability/defective PLCC link of STU Lines terminated at POWERGRID (NR-2) substations.....	15
A.8.2. PLCC and Auto Re-closure issues related to UPPTCL	16
A.8.3. Islanding scheme for Rajasthan and Punjab	17
A.8.4 Progress of rectification of deficiencies observed/improvements suggested in Basic Protection Audit.	20
A.8.5.Third Party Protection Audit by the Protection Experts for intra-state system/ balance system not covered in Basic Protection Audit.....	20
A.8.6. Status of Bus Bar protection.....	20
A.8.7. CERC order on Petition No. 9/SM/2014 and 10/SM/2015	22
A.8.8. Submission of information in compliance to Hon'ble CERC Standards of Performance of inter-state transmission licensees Regulations, 2012:	23
A.8.9 Creation of Protection Analysis Sub-Group (PSAG):.....	24
A.8.10 General Recommendations/Best Practices in PSC meeting.....	25

PART-B: NRLDC

B.1 Tripping Events.....	26
B.2 Oscillation and SPS related agenda Points	35

Minutes of 36th meeting of Protection Sub-Committee (PSC) held on 19.09.2018 at 10:30 hrs. at NRPC Secretariat, New Delhi

PART-A: NRPC

36th meeting of Protection Sub- Committee (PSC) of NRPC was held on 19.09.2018 at NRPC Secretariat, New Delhi. The list of participants is enclosed at **Annex-I**.

A.1. Confirmation of minutes of 35th meeting of protection sub-committee

Minutes of 35th meeting of Protection Sub-committee were issued vide letter dated 10.08.2018. The Minutes are available on NRPC's website at <http://www.nrpc.gov.in>. No comments were received.

Sub-Committee confirmed the Minutes of 35th PSC meeting.

A.2. Implementation of Recommendations of Task Force

As a followup of one of the recommendations of Enquiry Committee headed by Chairperson, CEA on grid disturbances that took place on 30th and 31st July 2012, Ministry of Power had constituted a 'Task Force on Power System Analysis under Contingencies' in December 2012. The Task Force had submitted its report in August 2013. In a meeting taken by Secretary (Power), GoI on 11.03.2014, it was decided that the report be given wide circulation and its recommendations be implemented in a time bound manner. Some of the issues arising out of recommendations of the Task Force were as under:

A.2.1. Database of protection settings

Based on the recommendations of the Task Force, it was decided that data regarding settings of relays shall be compiled by the CTU and STUs in their respective network and furnished to RLDC and SLDC respectively with a copy to RPC for maintaining the database. The database was to be kept updated and verified during the audit.

A format for submission of database was finalised in 30th PSC meeting.

The issue was deliberated in 34th TCC/38th NRPC meeting held on 24th/25th October, 2016 wherein it was decided that protection setting data would be provided by all the utilities within 02 months for 400 kV and 220 kV S/S.

33rd PSC meeting on 22nd February, 2017 – During 33rd PSC meeting, it was noted that only few utilities had submitted the data. PSC advised all the utilities to submit the data in prescribed format by March, 2017. It was also opined that if data were not submitted by utilities then engagement of third party in line with ERPC and SRPC may be considered.

The issue was discussed in the 35th TCC/39th NRPC meeting held on 1st/2nd May, 2017 in which TCC expressed their concern over the non-submission of protection database by the utilities. In the meeting, it was also informed that a project of Protection *Minutes of 36th Protection Sub-Committee meeting*

Database Management System is being implemented by ERPC and SRPC by engaging 3rd party with funding through PSDF. TCC recommended and NRPC thereafter approved the proposal for engaging a third party for Protection database and authorised NRPC sectt. to take further action.

34th PSC meeting on 4th August, 2017—During the meeting, M/s PRDC gave presentation about the various provisions included in the project being implemented by them in ER. Citing the concerns of utilities, it was proposed to form a core committee to define the comprehensive Scope of the project comprising members from NRPC secretariat, NRLDC, and all the utilities of NR.

Approval of Chairperson, NRPC has been obtained authorising Member Secretary, NRPC to carry out following activities:

- i. Formation of group for finalization of detail scope of work of the Project.
- ii. Submission of proposal for financing the Project through Power System Development fund (PSDF).
- iii. Opening of a separate account in the name of 'NRPC Protection Database Fund' for receiving the grant from PSDF for the Project.
- iv. Carry out e-tendering process including tender publication, opening, evaluation etc. for selecting contractor for implementing the scheme based on scope of work of the Project finalized by the group.

Nominations for the committee for finalisation of detailed scope of work of the project were sought from the utilities and based on the nomination received a committee has been formed. The first meeting of the committee was held on 1st February 2018 at NRPC Secretariat, New Delhi. Based on the inputs received from the members, Bidding Document shall be modified and circulated for the approval of the committee in its next meeting.

NRPC Secretariat has submitted the DPR of the project for PSDF funding.

Tender shall be floated after the finalization of the Bidding Document by the committee.

38th TCC and 41st NRPC meeting on 27th and 28th February, 2018- Based on the discussions held in 34th PSC meeting, a core committee has been formed to define the comprehensive Scope of the project comprising members from the utilities of NR.

First meeting of the group for defining the scope of the project was held on 01.02.2018 and based on the inputs received from the members, Draft Bidding Document has been prepared by the NRPC Secretariat

The Draft Bidding document incorporating all the inputs given by members in the meeting was further circulated for suggestions/comments, if any. The Bid document including all the relevant suggestions/comments of the members has been finalized.

NRPC Secretariat has also submitted the DPR of the project for PSDF funding based on the draft bidding document. The proposal of NRPC was scrutinized by the Techno-Economic Sub Group and further examined by Appraisal Committee.

Appraisal Committee has recommended the proposal for the grant from PSDF
Minutes of 36th Protection Sub-Committee meeting

funding and also qualified proposal for 100% funding through PSDF. The e-tendering Creation and maintenance of web based Protection Database Management and PC based Protection setting calculation tool for Northern Region Power System Network will be initiated on the receipt of MoM of Monitoring Committee.

35th PSC meeting on 20th June 2018, it was told that the Draft Bidding document incorporating all the inputs given by members in the meeting was further circulated for suggestions/comments, if any. The Bid document including all the relevant suggestions/comments of the members has been finalized.

NRPC Secretariat has also submitted the DPR of the project for PSDF funding based on the draft bidding document. The proposal of NRPC was scrutinized by the Techno-Economic Sub Group and further examined by Appraisal Committee.

Appraisal Committee has recommended the proposal for the grant from PSDF funding and also qualified proposal for 100% funding through PSDF. The e-tendering Creation and maintenance of Web based Protection Database Management and PC based Protection setting calculation tool for Northern Region Power System Network will be initiated on the receipt of MoM of Monitoring Committee.

Regarding the protection coordination studies for proper Zone-III setting it was informed in 34th PSC meeting on 4th August, 2017 and 35th PSC meeting on 20th June, 2018 that these studies will be part of the project for maintaining database of protection setting database.

39th TCC and 42nd NRPC meeting on 27th and 28th June, 2018, it was informed that Monitoring Committee has approved the Protection Database Management System proposal and e-tendering process will be initiated on the receipt of MoM of Monitoring Committee. The project timeline is of 18 months with 5 year support period preceded with one year defect liability period. It was also told that modelling and data collection would be done up to 132 kV level for Uttarakhand, Himachal Pradesh and Jammu and Kashmir and up to 220 kV level for all other states of the region. Utilities will be provided with licenses so that studies can be carried out by them.

36th PSC meeting on 19th September, 2018 – SE(O) NRPC, informed that the bid document has been finalized incorporating comments/suggestions given by the committee. Further, the tender has been published on 30th August and the last date for the receipt of the bid is 15th October, 2018. The technical bid shall be opened on 16th October, 2018. The Bid evaluation committee has been formulated comprising members from NRPC secretariat and NRPC constituents.

A.2.2. Periodicity of Third Party Protection Audit

The enquiry committee constituted by Govt of India to enquire into grid disturbances on 30th and 31st July, 2012 has recommended a thorough third party protection audit need to be carried out in time bound manner as there is need to review the protection schemes.

In 18th PSC meeting on 03rd Sept, 2012, it was agreed that the exercise of protection audit should be carried out periodically and frequency of the same could be 2-3 years.

The following points are proposed to review the protection schemes periodically:

Minutes of 36th Protection Sub-Committee meeting

- Periodicity of Third Party Audit from CPRI.
- Periodicity of Third Party Audit from members of STUs nominated by NRPC Secretariat for Third Party Protection Audit of different STUs.
- The scope of Third Party Protection audit of STUs.
- Any other Agency other than CPRI authorized to carry out Third Party Protection Audit.

In 35th PSC meeting held on 20th June, 2018 - The need of Protection audit was emphasized and members were requested to suggest suitable periodicity for the same. It was requested that periodicity should be decided uniformly at NPC level and each RPC should give them a suggestion. Members deliberated and recommended that the exercise of third party protection audit should be carried out periodically and frequency of the same should be 5 years.

It was also stated that Third Party Protection audit can be done any reputed agency working in the field of Power System protection other than CPRI. Members were requested to send the updated nominations of the protection engineers which would be carrying out the Third Party Protection audit. The previous list was finalized in 24th PSC meeting which is attached as Annexure – II of the Minutes of 35th PSC meeting.

In 39th TCC/42nd NRPC meeting held on 27th and 28th June, 2018:- It was informed that issue of periodicity of third party protection audit was deliberated in 35th Protection Sub Committee where members recommended that Third Party Protection audit can be carried out periodically either by a team of Protection Engineers of the utilities as per the list finalized by the Protection Sub-Committee or by any reputed agency working in the field of Power System. The periodicity of the protection audit is to be 5 years as decided by 35th PSC held on 20.06.2018.

All the utilities were requested to share the feedback of the Protection audit carried out from other agencies so that agencies can be rated which will help other utilities to select the agencies for their Protection audit.

Committee was apprised that decisions of TCC/NRPC will be further communicated to NPC for the uniformity and finalization at National level. TCC recommended and NRPC further approved the periodicity of the protection audit to be 5yrs and same can be carried out by CPRI or by any other reputed agency also.

36th PSC meeting on 19th September, 2018 – SE(O), NRPC stated that on the basis of deliberations in 35th PSC meeting and 39th TCC meeting, NRPC in its 42nd meeting approved the periodicity of the protection audit to be 5yrs which can be carried out by CPRI or by any other reputed agency or by a team of Protection Engineers also. He informed the committee that agenda would be taken in the upcoming NPC meeting for uniformity at National level.

PCE – II, CEA advised that NRPC should intimate other RPCs to take up the above issue in their respective PSC/RPC meetings so that consensus amongst all the RPCs can be reached at NPC meeting. He further enquired about time required to complete the protection audit in a particular substation.

Minutes of 36th Protection Sub-Committee meeting

Representative of POWERGRID stated that 2-3 days are required to complete protection audit of entire substation. Considering the no of substations, it was recommended that CPRI or any other agency or a team of Protection Engineers of the utilities as per the list finalized by the Protection Sub-Committee would do Third Party Protection Audit.

Members were requested to send the update nominations of the protection engineers which would be carrying out the Third Party Protection audit. BBMB and PSTCL have submitted the updated nominations. The updated list is enclosed at Annexure – II.

A.2.2.1 Training Programme/Workshop on Protection Audit for Protection system Engineers

Protection is one of the key operational aspects of Power system. The revision in the protection settings/schemes after modification of network topologies is essential for reliable operations of the Grid. Hence, periodic audit of these protection schemes/settings/protection functions is essential for reliable and secure operation of the Grid.

Hence, it is important that Protection system engineers are well educated and trained to carry out the exercise of Protection Audit. Hence, it is proposed to organize Training Programme/Workshop on Protection Audit for Protection System Engineers.

Power System Division of Central Power Research Institute has submitted an offer for conducting 3 days Training Programme/Workshop on Protection Audit for Protection System Engineers which is enclosed as **Annexure – III.**

36th PSC meeting on 19th September, 2018- SE(O), NRPC briefed about the Training Programme/Workshop on Protection Audit for Protection system Engineers. He informed committee that CPRI has submitted proposal for 3 days workshop at Bangalore on Protection Audit for Protection system Engineers. Members were of view that CPRI has enough experience in carrying out Protection audit hence CPRI might be considered for such type of trainings.

Representative of LPGCL suggested that relay setting calculation module might be included. It was emphasized that Training Programme/Workshop shall be on Protection Audit. MS, NRPC stated that accommodation would be arranged by utilities on their own during the Training program.

PSC recommended that the training programme/workshop on Protection audit to be conducted by CPRI and approval of the same may be requested from NRPC.

A.3 Violation of Protection standard in case of Inter-Regional lines of voltage 220kV and above

The section 3.e of Grid Standards Regulation of CEA, 2010 states that

“Provide standard protection systems having the reliability, speed, selectivity and sensitivity to isolate the faulty equipment and protect all components from any type of
Minutes of 36th Protection Sub-Committee meeting

faults, within the specified fault clearance time and shall provide protection co-ordination as specified by the Regional Power Committee

Explanation: For purpose of this regulation “fault clearance time” means the maximum fault clearance time as specified below:

Sr. No.	Nominal System Voltage (kV rms)	Maximum Time (in msec)
1.	765 and 400	100
2.	220 and 132	160

Provided that in the event of non clearance of the fault by a circuit breaker within the limit specified in Table, the breaker fail protection shall initiate tripping of all other breakers in the concerned bus section to clear the fault in the next 200 msec. “


Such delayed clearance of faults of Inter-regional lines may prove fatal to the security of the grid. Since, tripping of Inter Regional Lines of voltage 220kV and above are matter of concern to Grid security suitable action needs to be taken. The list of inter-regional lines where delayed clearance was observed is attached as Annexure-III of 36th PSC agenda.

As per the IEGC clause 5.2.r and clause 15.3 of CEA grid standard, DR/EL of all the tripping of 220kV and above level shall be sent within 24 hours of NRLDC.


In 35th PSC meeting held on 20th June, 2018- It was stated that violation of Protection Standard should be avoided and DR/EL should be sent to NRPC/NRLDC within 24 hours as the tripping analysis for inter-regional lines is very important for safe and reliable operation of Grid. It was also informed that this was also followed up regularly in the OCC meetings.

Utilities were requested to submit the DR/EL of all the tripping of 220 kV and above level within 24 hours to NRLDC. However, most of the utilities are not submitting the DR/EL of the trippings within 24 hours. The details of the same for the months of June, Jul and Aug, 2018 are highlighted below:


IR trippings: Details received status for August, 2018 as per 151th OCC



IR trippings: Details received status for July, 2018 as per 150th OCC



IR trippings: Details received status for June, 2018 as per 149th OCC



36th PSC meeting on 19th September, 2018- Representative of NRLDC informed that agenda pertains to violation of Protection standard such as delayed clearance of fault, spurious tripping, DR/EL submission within 24hrs and other events resulting into violation of Protection standard. PCE-II, CEA advised NRLDC to segregate trippings according to different reasons resulting into violation of Protection standards. He emphasized on maintaining list of trippings in which delayed clearance of fault is observed.

Representative of NRLDC highlighted cases of delayed clearance of fault such as tripping of 400kV Bhinmal(PG)-Zerda(PG) on 9th July,2018 at 11.46hrs and 220kV Saktapura(RRVPNL)-Badod (MPPTCL) on 06th June,2018 at 04.18 hrs . Representative of POWERGRID told that fault was observed at Zerda end and detailed report has been already submitted.

SE(O), NRPC stressed on the submission of DR/EL by the utilities within 24hrs which is being regularly highlighted in the monthly OCC meeting. Representative of POWERGRID stated that details have been already submitted but it hasn't been reflected in the database.

Minutes of 36th Protection Sub-Committee meeting

Representative of NRLDC informed that data compiled on 1st of every month is being highlighted in the OCC meetings and details received thereafter would not be reflected in the OCC meeting. He advised utilities to share the data on sep-nrpc@nic.in,nrldcs02@posoco.in, nrldcs02@gmail.com,.

SE(O), NRPC informed that a whatsapp group of PSC members has been created in which information regarding tripping(name, date, time) and date & time at which details have been submitted could be shared. This would help in updating the database regularly and information could be shared amongst all. MS, NRPC advised that NRLDC should appoint nodal officer who can acknowledge the receipt of data received. Members agreed for the same.

A.4 Actions taken on the outcome of the meeting of Protection Analysis Sub Group (PSAG)

It was deliberated in the 31st PSC meeting to create a Protection Analysis Sub-Group (PSAG) for conducting a detailed discussion of grid events of greater importance requiring immediate attention on regular basis as the discussion of a large number of grid events are not possible in the regular PSC meeting.

Subsequently, in the 32nd PSC meeting the members of group were decided. The 10th PSAG meeting was held on 18.04.2018 and minutes of the same was issued vide letter dated 27.07.2018. The following trippings were discussed in the meeting. (Minutes attached as Annexure – IV of 36th PSC agenda)

Sr No	Incident Discussed	PSAG meeting held on	Utility concerned
1.	Blackout of 400kV Kishenpur substation on 12.02.2018 at 11:24hrs and 12:07hrs and 400kV GSS Wagoora substation on 10.03.2018 at 09:51hrs	18.04.2018	PGCIL, NHPC, PDD J&K

36th PSC meeting on 19th September, 2018 - SE(O) stated that 10th PSAG meeting was held on 18.04.2018 and minutes of the same was issued vide letter dated 27.07.2018. He further told that PGCIL (NR-2) has submitted the compliance report (attached as Annexure-V of the agenda of 36th PSC) on the issues raised during 10th PSAG meeting along with DEF settings at Kishenpur.

Representative of POWERGRID stated that DEF relay has been physically checked at Kishenpur end for receiving of DT command and it has been working fine. He informed that scheme for sending DT on DEF relay operation has been removed from all substation.

Representative of NRLDC informed that SPS for Kashmir valley was designed but it has not been implemented yet. SE(O) told that connectivity for valley has been

improved after commissioning of Amargarh s/s and Kishanganga HEP. He advised that SPS for Kashmir valley needs to be reviewed.

Representative of POWERGRID stated that ICT tripping was observed on over flux from BCU. However, no other flag of any was found except Master trip relay. It hinted towards the maloperation of static over flux relay. Hence, it was suggested that over flux settings in differential relay should be enabled rather than operating static relay.

A.5 Grid disturbance at NAPS on 15.02.2018 due to Bus fault at 220kV Atrauli S/S (Agenda by NPCIL)

On 15.02.2018, NAPS both units were operating smoothly at full power, Grid parameters were also maintaining normal. All 220kV lines were in service. (Enclosed as Annexure-VI of 35th PSC agenda) At 19:17:10 Hrs, voltage dip from 220 kV up to 120 kV was observed at NAPS, however NAPS both units survived. 220kV Atrauli S/S is connected only with NAPS, Narora and Harduganj TPS, both are generating stations and hence an important element of grid network. At around 19.15hrs, normalization of one ICT was in progress at Atrauli S/S. During the process, its 220kV side circuit breaker developed fault causing flashover/ damage of the CB resulting into bus fault. Atrauli S/S does not have 220kV Bus differential protection scheme hence fault propagated into remote end 220kV S/S Narora and Harduganj.

In the 35th PSC meeting held on 20.06.2018 - Representative of NPCIL told that damage of the CB resulted into bus fault at 220kV side of Atrauli S/s. He further told that Atrauli S/S does not have 220kV Bus differential protection scheme hence fault propagated into remote end 220kV S/S Narora and Harduganj, however distance relay of line protection operated and 220kV Atrauli-Narora, Atrauli - Harduganj lines tripped in zone -4 at Atrauli end. The fault duration was 250 msec. It was informed that it is mandatory for all 220kV and above S/s to have bus differential protection as per the CEA regulations. He further told that lines were charged after the incidence without informing either Narora or Harduganj end.

Representative of UPPTCL informed that bus differential protection at Atrauli s/s is to be commissioned by the end of July. He also informed that zone-4 setting has been changed to 160 msec.

Representative of NPCIL also told that there is no bus differential scheme at 220kV Sambhal s/s and 220 kV Simbhaoli s/s. Representative of UPPTCL assured to look into matter and expedite the installation of bus differential scheme.

36th PSC meeting on 19th September, 2018 – Representative of UPPTCL stated that panels were delivered but installation and commissioning has not been completed. He further told that SEL has been awarded with the work.

SE(O) stated that implementation of bus bar is long pending issue. He further informed about the Central Electricity Authority (Measures relating to Safety and Electric Supply) Regulations, 2010 which states as followed:

“High speed bus bar differential protection along with local breaker back up protection shall be commissioned and shall always be available at all 132 kV and above voltage sub-stations and switching stations and generating stations connected with the grid: Provided that in respect of existing 132 kV sub-stations and switching stations having more than one incoming feeders, the high speed bus bar differential protection along with local breaker back up protection, shall be commissioned and shall always be available”

In view of the above, it is mandatory to have operational bus bar protection at all 132 kV and above substation. Representative of UPPTCL stated an example of 400kV Sultanpur s/s which took 1 year for installation and commissioning of bus bar differential protection considering limitations at substation. He further told that bus bar protection is expected to be operational by Nov,2018.

Representative of NRLDC highlighted that installed bus bar protection shall be operational as it has been observed many times that bus bar protection was disabled even in 400kV substations. This leads to complete blackout of substations in case of any bus bar faults. He insisted that bus bar protection should be operational being important for safe and secure operation of the Grid.

A.6 Final report of the group to suggest measures for bringing improvement in the field of Power System Protection among the utilities in Northern Region

A group was constituted by Member Secretary, NRPC vide letter No. NRPC/OPR/107/06/ 2015/ dated: 26.08.2015 to suggest measures for bringing improvement in the field of Power System Protection among the utilities in Northern Region. The report was submitted in 34th TCC/38th NRPC meeting held on 24th /25th October, 2016 wherein the report was accepted for implementation. It was also agreed in the NRPC meeting that each utility would immediately start working to develop training module for Basic Training on Protection System for Sub-Station Engineers (Level -1) and start training programs within 6 months. The issue was also discussed in 32nd PSC meeting wherein utilities were requested to organize Level-1 training and would submit the details.

BBMB, POWERGRID NR-I and PITCUL are conducting the training on Protection System (Level - I) at regular intervals.

First training programme of Level-2 was conducted successfully from 21st-25th November, 2016 for 25 nos. of participants through POWERGRID. 35th TCC/39th NRPC meeting held on 1st/2nd May, 2017 - Advised to conduct more such programmes including Level-3 for Protection System Engineers.

Protection training for level -3 was conducted successfully from 19th-23rd March, 2018 at Udaipur for 25 nos. of participants through POWERGRID.

In 35th PSC meeting held on 20.06.2018 - Members were informed that 1 batch of level - 2 and level – 3 training was completed and another batch for training is to be taken up shortly. Utilities were requested to share the details regarding content, no. of days of *Minutes of 36th Protection Sub-Committee meeting*

level-1 training arranged by them.

Representative of RRVPNL and DTL told that training is being arranged by them and details will be shared. Other utilities were also requested to share the details at the earliest.

Rajasthan has submitted the details of the level – I training.

In 39th TCC and 42nd NRPC meeting on 27th and 28th June, 2018 – It was told that NRPC Sectt has conducted Level-3 training for Protection System Engineers from 19th to 23rd March, 2018 with this the first batch for Level-2 and level-3 training has been successfully completed. It was also informed that NRPC Secretariat would be going for another batch of Protection System Engineers Level-2 and Level-3 training for which no. of participants might be increased from 25 to 50. Utilities were requested to preferably nominate the engineers working in the field of power system protection and make sure that nominated individual is available for entire duration of the training. It was stated that as the participants are being trained as trainer, they should further transfer the knowledge within their own utility so that additional trained manpower can be deployed.

The Level-2 training for 2nd batch is tentatively scheduled during November–December, 2018.

36th PSC meeting on 19th September, 2018 – SE(O), NRPC stated utilities are requested to share the details of Level -I training. He informed that NRPC in its 42nd meeting has approved for 50 no. of participants for 2nd batch of Level-2 and Level-3 training of Protection System Engineers. He proposed that training might be organized through any one of the OEM such as ABB, SIEMENS, GE etc. It would include classroom training as well as hands on training on Relays. The training is tentatively proposed to be held during during November– December, 2018.

SE(O) clarified that Level-1 training is to be conducted for supervisors and workman on the Field by utilities on their own. These trainings should be conducted regularly as to mitigate chances of maloperation/tripping due to human error.

Representative of UPPTCL informed that training for 2 months have been imparted at Lucknow for new recruits. Representative of Harayna informed that training is conducted at HPTI training academy which includes different modules for lineman, JEs, AEs, EEs and SEs. Members were again requested to share the details for Level -I training.

A.7. Format for Detailed Analysis report

Members of the Protection sub-committee had raised the issue of devising a common format for submission of detailed analysis report of the tripping event. Accordingly, a format had been prepared and same is enclosed as Annex-VII of 35th PSC agenda. In the discussions held in 33rd PSC meeting, it was decided to align the format (33 PSC Agenda Annex-IX) as per the SOPR. A committee to align the format as per SOPR is constituted and advised to submit the report by 04.08.2017.

In the 34th PSC & 35th PSC meeting, it was decided to deliberate on format once the constituted committee submits its report.

The Committee met to align the format as per SOPR but no consensus was reached among the members of the Committee. However, POWERGRID, NR-I has suggested a format for the Detailed analysis report which is enclosed as Annex – VI of 36th PSC agenda.

36th PSC meeting on 19th September, 2018 – Representative of NRLDC informed that format was prepared in such a way that event could be concluded from submitted data and hardware database of DR/EL facility and Numerical relays would be created. The database of DR/EL facility and Numerical relays at substation would help in monitoring the compliance of different protection standards.

Representative of POWERGRID told that main objective of any protection engineers is to study/analyze cause of the tripping and suggest/take remedial measures to avoid such trippings in future. He told that detailed analysis report consisting of above is regularly submitted by POWERGRID. He further stated that excel file format attached is time consuming which will affect the main objective of analysis. He agreed that database is necessary for which data can be submitted once. He stressed that not only the format but also its compliance should also be discussed considering its complexity.

Representative of DTL stated that data in mentioned format can be submitted but stressed that focus should be on tripping analysis. Representative of Punjab told that it is difficult to submit the data in mentioned format as many times trippings weren't reported by field engineers. He was of the view that many columns in excel format were irrelevant Representative of UPPTCL stated that format is very long but they were submitting the data in mentioned data.

Representative of NRLDC emphasized that data in the mentioned format is as important as tripping analysis and both should be submitted. SE(O) highlighted that data could also be used for Transmission availability certification. He advised to begin the data submission in mentioned format and considering the issues faced in implementation format would be simplified further, if required.

A.8. Follow up action on outstanding issues from previous meetings:

A.8.1. Non- availability/defective PLCC link of STU Lines terminated at POWERGRID (NR-2) substations

22nd PSC meeting on 22nd July, 2013- POWERGIRD had submitted a list of its NR-2 sub-station in 22nd PSC meeting where PLCC was non-functional at other side.

35th PSC meeting on 20th June, 2018- Status of PLCC work in these sub-stations, as updated in the meeting is as under:

Sl. No.	Name of Substation	Name of Transmission Line	Availability of PLCC	Updated Status in 35th PSC	Present status
PLCC issues with PSTCL					

1	Amritsar	220 kV Verpal –I	Not installed	PLCC Panels are installed on both end & wiring has been completed on PSTCL end & wiring on PGCIL end will be done with co-ordination of PLCC team of PSTCL by PGCIL. End to end testing will be completed by 30.09.2018	Equipment has been installed at both the ends. End to end testing would be completed by 30.09.2018.
---	----------	------------------	---------------	---	---

A.8.2. PLCC and Auto Re-closure issues related to UPPTCL

28th PSC meeting on 19th December, 2014 - POWERGRID had informed that there were various lines of UPPTCL wherein PLCC panels and auto re-closure schemes were not in working condition due to which frequent tripping of lines on transient faults were taking place.

35th PSC meeting on 20th June, 2018- Status updated by UPPTCL and POWERGRID in the meeting was as under:

Sl. No.	Name of Transmission Line	Details of PLCC	Status as updated in 35 th PSC	Present status
Allahabad S/S				
1.	220kV Allahabad-Rewa Road-I	PLCC link was through but failed frequently due to non availability of wave trap at Rewa Road end.	PLCC commissioned but not functional as end to end testing was pending.	Representative of UPPTCL stated that relay panels were to be replaced. The shutdown was awaited. It was expected to be done by end of the month.
2.	220kV Allahabad-Rewa Road-II			

Kanpur S/S				
1.	220kV Kanpur-Mainpuri	PLCC panels not available	-	PLCC panels were supplied but yet to be commissioned.
Gorakhpur S/S				
1.	220kV Gorakhpur-Barhua	PLCC were not functional	PLCC has been commissioned but available relays do not have carrier feature which were to be replaced in 1 month.	The relays were being replaced with Numerical relays.
2.	220kV Gorakhpur-Basti	PLCC panels were not available	PLCC allotment was expected in August 2017.	The LIO was done for 220kV Gorakhpur-Basti at Bassi and panel has been commissioned at Bassi.

A.8.3. Islanding scheme for Rajasthan and Punjab

A.8.3.1. Islanding scheme for Rajasthan

30th PSC meeting on 21st September, 2015 - RVPNL had stated that existing islanding scheme meant for RAPP-A and RAPP-B would change entirely if Mahi HPS is excluded from the scheme. Also, result of dynamic simulation studies had not yet been received from CPRI. RVPNL was requested to implement the scheme provisionally & necessary actions for procurement of relays etc. was to be initiated with completion target of one year. RVPNL had agreed for the same.

31st PSC meeting on 7th June, 2016 - RVPNL stated that the procurement process for this islanding scheme was underway and the scheme, without considering Mahi, was expected to be functional by December, 2016.

32nd PSC meeting on 30th November, 2016 - RVPNL informed that the scheme excluding Mahi HPS would be implemented by June 2017.

33rd PSC meeting on 22nd February, 2017 - Status could not be confirmed as no representative of RVPNL attended the meeting.

34th PSC meeting on 4th August, 2017 - RVPNL intimated that relay purchase in process and the scheme is to be implemented by 31.01.2018.

35th PSC meeting on 20th June, 2018 – Representative RVPNL intimated that scheme has been approved but the purchase process was reverted back. He further told that re-tendering for relays is in process.

36th PSC meeting on 19th September, 2018 – Representative of RVPNL stated that procurement has been completed and scheme would be implemented by Dec, 2018. He told that Mahi HPS has been permanently excluded from the scheme.

A.8.3.2. Islanding scheme for Punjab

A meeting was held on **27th November, 2014 at NRPC Secretariat** to review the islanding schemes for Punjab. In this meeting, it was decided that PSTCL would implement the scheme envisaged for Lehra Mohhabat TPS and Bhatinda TPS at first instance. Thereafter, based on the experience of such scheme, the islanding scheme meant for Ropar TPS would be implemented. PSTCL had informed that stability study for the scheme was being carried out by CPRI and report of the same would be available by **31.12.2014**. Thereafter, procurement would start.

29th PSC meeting on 9th February, 2015 - PSTCL had informed that CPRI has submitted the dynamic study for islanding scheme for Bhatinda TPS and PSTCL was under process of implementing the scheme. Procurement process was underway and the scheme would get implemented by **30.11.2015**. PSTCL was requested to share the approved scheme with NRPC Sectt. and NRLDC. PSTCL had agreed for the same.

31st PSC meeting on 7th June, 2016 - PSTCL had informed that relays for islanding scheme of Bhatinda TPS had already been procured and installation of these relays was under process. He further stated that the scheme would be made functional by **30.09.2016**.

32nd PSC meeting on 30th November, 2016 - PSTCL informed that Bhatinda, which is a part of the islanding scheme, would be in operation for a limited period during summer. In view of this, the scheme needs revision. Once the revised scheme is finalised it would be implemented. PSC advised PSTCL to finalise the scheme at the earliest and to share it with all the concerned including

NRPC Sectt.

33rd PSC meeting on 22nd February, 2017 - PSTCL was requested to expedite the process and submit the information at the earliest.

34th PSC meeting on 4th August, 2017 – PSTCL was given approval to implement islanding scheme for only GHTP control area citing the plans of PSPCL to shut the GNDTP Bathinda plant by the year end. They were further requested to complete the same by 30.09.2017 and to submit the details of actual implemented schemes to NRLDC Secretariat and NRPC.

35th PSC meeting on 20th June, 2018- Representative of PSTCL stated that consent of PSPCL was received a one week before for the execution of Islanding scheme on only GHTP control area. It will be executed by 30.09.2018.

36th PSC meeting on 19th September, 2018 - Representative of PSTCL stated that data was awaited from the PSPCL. He stated that PSPCL was requested to submit the data of the units which would be kept ON during peak/non-peak period. They have submitted the data stating that all the units would be kept ON but in actual scenario it has been observed that units for Lehra-Mohabbat TPS were off during winter and ran up to 50% in paddy seasons. He told that scheme would be implemented in a month after consultation with PSPCL.

SE(O) stated that issue of islanding scheme of Haryana was followed up since 2012 but no significant progress was observed. He stated that following was recorded in the MoM of 32nd PSC held on 30th Nov, 2016: “PSC expressed concern about taking such a long time in deciding about the islanding scheme and decided to drop the agenda as there was no progress in the matter.”

He asked representative of Haryana to submit current status of Haryana islanding scheme. It was also informed that Report of Enquiry committee on Grid disturbance on 30th and 31st July, 2012 has stated following in its Guidelines for Formation of islands:

“State load Dispatch Centers/ State Transmission Utilities along with the generating stations in their area should explore the possibility of formation of various islands.”

Accordingly, it was necessary for states to have operational islanding scheme. Representative of Delhi stated that islanding scheme for Delhi is operational but it needs to be modified considering phasing out of BTPS and 400kV Tughalakabad S/s. He informed that issue has been already taken up with OEM and modification is in progress.

Representative of UPPTCL informed that 3-4 years back islanding scheme was prepared for Lucknow and Raebareli with generation of Unchahar phase – A generation. It was deliberated that the scheme needs to be reviewed considering the modification in network topology. PCE- II

advised that a separate meeting needs to be held for deliberating about islanding schemes in NR. He suggested that IPPs could also be considered while designing islanding scheme.

A.8.4 Progress of rectification of deficiencies observed/improvements suggested in Basic Protection Audit.

The status of rectification of deficiencies observed in Basic Protection Audit carried out by POWERGRID & CPRI is to be submitted on monthly basis.

The updated status in regard to expected completion time of rectification of protection related deficiencies as informed by utilities is enclosed as **Annexure-IV**.

A.8.5. Third Party Protection Audit by the Protection Experts for intra-state system/ balance system not covered in Basic Protection Audit.

The status of TPPA as updated in the 36th PSC meeting is enclosed as Annex-VIII. In the 36th PSC meeting, PSC again stressed over non-rectification of deficiencies by most of the utilities. Utilities which have not submitted the action plan were requested to submit the same at the earliest. All the utilities were again requested to submit the action plan and to ensure expediting the process for rectification of discrepancies found in the audit. **Annexure-V**.

A.8.6. Status of Bus Bar protection

As per the report of Basic Protection Audit carried out by CPRI and POWERGRID in 2012, non-availability/non-functionality of Bus Bar Protection at many of the S/S was one of the major observations.

19th PSC meeting on 21st November, 2012 - Action plan for rectification of deficiencies enumerated in the report was updated by the utilities during the meeting. This status has subsequently been revised based on information submitted by the utilities from time to time.

20th PSC meeting on 5th April, 2013 – As per the decision taken in 83rd OCC held on 17th January, 2013, it was agreed that each transmission and generation utility would nominate two protection experts and thereafter protection audit at intra-State sub-stations and generating stations can be carried out by a team drawn from these experts. List of nominations was prepared and updated subsequently.

21st PSC meeting on 25th June, 2013 – Bus Bar Protection Status as available with NRPC secretariat was discussed in the form of tabled agenda item and utilities were requested to update the same within 15 days.

Minutes of 36th Protection Sub-Committee meeting

22nd PSC meeting on 22nd July, 2013 – Information was not submitted by any of the utilities. Members were requested to update the status of Bus Bar Protection.

23rd PSC meeting on 9th September, 2013 – Only DTL, BBMB PSTCL, POWERGRID, NHPC and HPSEB Ltd. submitted the status. All other utilities were requested to update the status of Bus Bar Protection.

24th PSC meeting on 17th December, 2013 – Only DTL, BBMB PSTCL, POWERGRID, NHPC and HPSEB Ltd. had submitted the status. All other utilities were requested to update the status of Bus Bar Protection.

25th PSC meeting on 12th February, 2014 – Immediate Alternative of Bus Bar Protection Scheme - RVPNL stated that in the Sub stations, where Bus Bar Protection Scheme was currently not available, time setting of bus coupler connected in between main Buses may be reduced to 100 ms (operating time) and reverse reach of feeders may be reduced to 2 km and with time of operation as 160 ms. With above settings, in case of actual Bus fault, bus coupler operation will isolate the faulty buses from other main buses and feeders will also trip. This operation will reduce the fault duration and the healthy buses will remain intact.

PSC was of the view that scheme can be used purely as a temporary substitute till Bus Bar Protection is not installed. But at the same time, members expressed that endeavour should be made to operationalize Bus Bar Protection at the earliest.

28th PSC meeting on 19th December, 2014 – Utilities were requested to expedite the implementation of Bus Bar Protection and submit the information.

31st PSC meeting on 7th June, 2016 – PSC expressed concern of non-functioning of Bus Bar Protection at many sub-stations in the region. It was decided that efforts would be made to expedite implementation of Bus Bar protection and submit the information to NRPC Sectt with progressive commissioning of Bus Bar protection.

Attention of members was also drawn towards deliberations in the 25th meeting of PSC held in Feb, 2014, wherein it was decided that as an interim arrangement an alternative to Bus Bar protection can be implemented. In this arrangement time setting of Bus coupler connected in between main Buses may be reduced to 100 ms (operating time) and reverse reach of feeders may be reduced to 2 km and with time of operation as 160 ms. With above settings, in case of actual Bus fault, Bus coupler operation will isolate the faulty Buses from other main Buses and feeders will also trip. This operation will reduce the fault duration and the healthy Buses will remain intact.

32nd PSC meeting on 30th November, 2016 – UPPTCL stated that as agreed in 25th PSC meeting held in Feb, 2014, an interim arrangement alternative to Bus Bar protection has been implemented in some of their sub-stations. It was also informed that as normal operation has been reported, therefore, UP was planning to implement the same in other sub-stations. Delhi and Rajasthan also informed the similar action. It was felt that other states e.g. Haryana and Punjab may also implement the same as an interim measure till the bus -bar protection is installed. However, it was again emphasised that this would be a temporary arrangement only and must not be considered as an alternative to bus -bar protection.

33rd PSC meeting on 22nd February, 2017 – PSC advised all the concerned utilities to make interim arrangement as decided in 32nd PSC meeting, till the Bus bar protection is not installed.

34th PSC meeting on 4th August, 2017- PSC advised to remove the alternate arrangement wherever Bus bar protection has been installed. UP has installed alternative schemes in almost all of the substations where Bus bar protection is installed. Rajasthan will start procurement after finalizing contract for implementation of Bus bar protection.

35th PSC meeting on 20th June, 2018 - Representative of UPPTCL informed that alternated arrangements were removed in all the substations wherever a bus bar protection was installed.

Representative of Rajasthan informed that out of 74 locations where bus bar protection was to be installed 56 locations have been completed. He informed that installation at other locations is in process. **(Annexure - VI)**

A.8.7. CERC order on Petition No. 9/SM/2014 and 10/SM/2015

SE, NRPC stated that CERC in its order dated 14.06.2016 in Petition no. 9/SM/2014 for investigation of tower collapse and load crash in Northern Region on 30.5.2014 and Petition no. 10/SM/2014 for investigation of Line Outage due to Tower Collapse in Northern Region during April 2015 to June 2015 directed RPC Secretariat to examine the cases of delayed clearance of faults on transmission system during last two years and to submit an analysis report within six month from the date of issue of the order. The status of the delayed clearance of the fault from 01.04.2014 to 01.06.2015 was enclosed as Annex-VI of the agenda of 32nd PSC meeting. In the agenda following action was proposed:

- Utilities which had not submitted the detailed report along with the remedial measures taken/being taken were requested to submit the same.
- Utilities whosoever had submitted the report along with the measures to avoid the recurrences of these types of tripping were requested to submit the status of action suggested in report.

In the 32nd PSC meeting, members were requested to submit the reason for delayed clearance of faults and action taken to avoid recurrence, by 15th Dec, 2016 to NRPC Sectt.

Again in the 33rd PSC expressed concern over non-submission of data. Utilities were requested to furnish the information by 07.03.2017, so that the report may be submitted to CERC.

Subsequently, vide letter dated 10.07.2017, members of PSC were asked to submit the action taken on the recommendation of the discussions held in last 04 PSC meetings (30th, 31st, 32nd, 33rd) by 25.07.2017).

The issue was again flagged in 34th PSC meeting in which all the members agreed to submit the details as required. The status of details received is as given below:

Description	Information submitted by
Details regarding Event List as mentioned at Annex-VI to 34 th PSC Minutes (Reasons /Action taken for Delayed Clearance of faults)	UPPTCL(Central and East North Zone), NJHPS, POWERGRID, NHPC, DTL, RRVPNL
Action taken status on the recommendation of the discussions held in last 04 PSC meetings (30 th , 31 st , 32 nd , 33 rd)	BBMB, NHPC, POWERGRID (NR-2) and NAPS

36th PSC meeting on 19th September,2018 - Members were informed that list of events of delayed clearance of faults from 01.04.2014 to 01.06.2015 was already circulated but data has not been submitted by utilities. Utilities were requested to furnish the information as mentioned above at the earliest as the details need to be submitted to CERC.

A.8.8. Submission of information in compliance to Hon'ble CERC Standards of Performance of inter-state transmission licensees Regulations, 2012:

In 32nd PSC meeting it was intimated that the Hon'ble **CERC SOPR-2012** regulation mandates inter-State Transmission Licensees to furnish the protection system reliability indices on monthly basis as attached at Annexure-I of the additional agenda of 32nd PSC. It had been observed that presently no such information was being received from the ISTS licensees.

It was requested that ISTS licensees submit such information on monthly basis to NRLDC.

Utilities were requested to share the DR/EL of the single element tripping and details of the tripping in desired format attached as Annexure-2 of the additional agenda of 32nd PSC.

36th PSC meeting on 19th September,2018 - SE(O) informed that as per CERC Minutes of 36th Protection Sub-Committee meeting

Standards of Performance of inter-state transmission licensees Regulations, 2012 data needs to be furnished the protection system reliability indices on monthly basis. He requested that ISTS licensees submit such information on monthly basis to NRLDC/NRPC.

A.8.9 Creation of Protection Analysis Sub-Group (PSAG):

SE, NRPC informed that in 31st PSC meeting it was deliberated that owing to the large number of grid events in the region and the intervening period between two successive PSC meetings, a detailed discussion of such large events during the limited time frame of the meeting becomes difficult. Further, it has been observed that several events in the grid require immediate analysis and rectification of defects.

He added that considering the above, it was proposed that a Protection Analysis Sub-Group (PSAG) would be formed to discuss and analyse major grid events, which require immediate attention. The subgroup would suggest specific corrective actions required by respective entity. The entities would submit the status of compliance of these recommendations in a stipulated time frame.

SE, NRPC further informed that PSC had decided to constitute a Protection Analysis Sub-Group with members from NRPC Secretariat, NRLDC and POWERGRID as permanent members. Further, all other utilities of Northern Region would provide one nomination each. The nominee from the utilities would be called when the tripping related to that utility is to be discussed. The group shall conduct its business on monthly basis and submit its report to PSC. In 32nd PSC meeting, members of the group were decided.

In 35th PSC held on 20th June, 2018: Representative of NRLDC emphasized that remedial actions as recommended by PSAG and PSC should be compiled in tabular form with the time frame by utility and submitted to NRPC/NRLDC. He also stated that PSAG group is to be expanded with more than one nomination from the utilities which might be sent for the physical audit in case of important multiple element tripping. MS, NRPC stated that expanding the group shall also help in manpower development as it is a learning exercise for Protection Engineers. Members were requested to send the additional nominations for the PSAG group.

36th PSC meeting on 19th September, 2018 - SE(O) stated that owing to the large number of grid events in the region and the intervening period between two successive PSC meetings, PSAG group was formulated. It does not have any specific periodicity and meeting might be called as in when required. It was also envisaged that PSAG members would go for physical audit of the station as per recommendation of PSC/PSAG meetings. The group also has importance in case of deliberating event from protection point of view on urgent basis. Members were requested to send the additional nominations for the group. (Enclosed as Annexure-VII)

A.8.10 General Recommendations/Best Practices in PSC meeting

In the 32nd PSC meeting it was deliberated that there is a need to keep the compilation of the general recommendations of the Protection Sub- Committee for reference. The compiled list of recommendations of PSC was circulated with the agenda of 33rd PSC meeting and also enclosed as Annexure – XII of 35th PSC agenda.

Members were requested to adhere to these general recommendations and follow the best practices as suggested by PSC. Members were also requested to forward best practices in their utility or any other utility which can be adopted to include in this compilation.

35th PSC meeting on 20th June, 2018 - It was informed that list of general recommendations was formed considering best practices as suggested by PSC but it has been observed that these practices were not being implemented. All the utilities were requested update the status regarding actions taken to adhere these general recommendations.

36th PSC meeting on 19th September, 2018- Representative of NRLDC stated that during the deliberations in PSC meetings if any recommendation was recurring, then it was considered as general recommendation by PSC to be adhered by utilities. It has been observed that these recommendations were not followed by utilities and tripping due to same reason have been noticed. He insisted that utilities should adhere with these recommendations. Utilities were also requested to share any frequent cause of tripping, maloperation observed due to particular setting or any input beneficial for other utilities so that these recommendations could be expanded.

PART-B: NRLDC

B.1 Tripping Events

The complete summary of the events along with the information reported, action taken by entities is attached at **Annexure-VIII**.

The recommendations of PSC are as follows:

A. Multiple Element tripping at 765/400kV Anta (Raj) at 14:40hrs of 02nd May 2018

1. Default Programmable Scheme Logic (PSL) configuration of Alstom make (P-741 relay) bus bar protection have common issue of assigning of tripping to master trip relay and it would further trip main and tie CB of connected elements. This default PSL needs to be modified for tripping of main CB only in case of operation of bus bar protection. (**Action: General Recommendation**)
2. DR recording time would be increased to 2500ms (-500 ms to +2000ms) (**Action: General Recommendation**)
3. Rajasthan shall also check the SPS operation of Chhabra/ Kawai/ Kalisindh complex and share the report. (**Action: Rajasthan, APL; Time: Within 15days**)
4. Separate meeting to be called for catering the issue of non-operation of Chhabra/Kawai/Kalisindh SPS and changes in logic of SPS. (**Action: NRPC. Utility involved: Rajasthan, APL, NRPC and NRLDC**)
5. Time synchronization of DR (Anta-Raj) needs to be checked and rectified, as it is not matching with the bus bar trip (DR) and PMU based timings. (**Action: Rajasthan, Time: Within 7days**)

B. Multiple element tripping at 400/220kV Ajmer (Raj) at 16:55hrs of 24th May 2018 and 17:55hrs of 06th Jun 2018

1. DR and Event Log of all the numerical relays needs to be checked within 15days for time synch and shall be time synch every time. (**Action: General Recommendation**)
2. Rajasthan shall submit the phase sequence of both end of all the POWERGRID connected station.
3. Separate meeting to be called for issue related to phase sequence at Rajasthan. (**Action: NRPC. Utility involved: Rajasthan, POWERGRID, NRPC and NRLDC**)
4. For the incident of 24th May 2018, all the remedial measures already taken by Rajasthan.
5. A detailed report covering the following points along with remaining DR, station EL shall be submitted: (**Action: Rajasthan; Time: Within 7days**)
 - For 06th Jun 2018:
 - i. In case of operation of distance protection, as Z-1 initiated in flag details, breaker should have operated and cleared the fault.

- ii. In case of operation of LBB protection, delayed operation of LBB protection (fault duration more than 1000ms), same has been checked through station EL details?
- iii. Exact location of fault to be reported.
- iv. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.
- v. Detailed report and supporting DR/EL needs to be submitted
- vi. Operation of 220 kV bus bar protection/ LBB operation at 400/220kV Ajmer (Raj) to be reviewed and corrected for delayed operation of bus bar/LBB operation.
- vii. Reason of three phase opening and reclosing of 220 kV Ajmer (400kV)-Ajmer ckt needs to be checked and corrected.
- viii. Time synchronization of DR to be checked and corrected

C. Multiple element tripping at Uri-II HEP at 13:55hrs of 26th May 2018

- 1. Alstom make Micom relay of 400 kV Uri-II (end)-Wagoora ckt to be checked and corrected. (**Action: NHPC**, Time: Within 15days)
- 2. Mapping of manual selector switch operation for A/R in numerical relay DR and station event logger to be done. (**Action: NHPC**, Time: Till November-2018)
- 3. GPS at Uri-II HEP shall be corrected for time synch. (**Action: NHPC**, Time: Till November-2018)
- 4. Reason of tripping of all running units at Uri-II HEP needs to be checked and corrected (**Action: NHPC**, Time: Within 15days)
- 5. Reason for closing of Y&B phases at Uri-I (after 100ms of opening of all three phase) without any indication to be checked and corrected. (**Action: NHPC**, Time: Within 15days)
- 6. Detailed report considering the aforesaid points shall be submitted. (**Action: NHPC**, Time: Within 15days)

D. Complete outage of 400kV Paricha TPS(UP) at 21:56hrs of 27th May 2018

- 1. No representative from UPRVUNL presented during the meeting, It was informed to STU/SLDC-UP to collect the information (DR/EL, detailed report) and submit the details considering the points for discussion mentioned below: (**Action: UPPTCL/ SLDC-UP**, Time: Within 15days)
 - a. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.

- b. Availability and healthiness of bus bar protection at Paricha TPS at the time of tripping to be shared.
- c. Reason for delayed clearance of around a second fault to be shared.
- d. In view of all tripped elements not captured in SCADA SoE data, digital SCADA data reporting from Paricha TPS to be checked, rectified and ensured in future

E. Multiple Element tripping at 400/132kV Anpara-ATPS and 400/220 kV Obra-B TPS at 22:25hrs of 28th May 2018

A detailed report covering the following points along with remaining DR, station EL shall be submitted: (**Action: UPPTCL/ SLDC-UP**; Time: Within 15days)

1. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.
2. Availability and healthiness of bus bar protection at Obra-B TPS at the time of tripping to be shared.
3. Is Pole discrepancy protection operated at 400 kV Obra-B TPS of 400kV Obra B TPS-Anpara TPS ckt?
4. Reason for delayed clearance of fault to be shared.
5. Reason of delayed bus bar protection operation at Anpara A TPS? (2.3second after fault occurrence time)
6. There is a significant difference between tripping of elements at 400kV Obra B TPS and Anpara TPS. Exact sequence of event needs to be checked and reported.
7. Reason of tripping of units at Obra-B TPS? What protection operated for Obra-B TPS units?
8. Reason of station transformer and 220/132kV ICT tripping at Obra-A TPS?
9. Reason of immediate tripping of Rewa Road-Obra B TPS from Rewa Road end?
10. Reason delayed tripping of 400 kV Obra B TPS-Panki from Obra B end?
11. Such delayed clearance of fault near generating complex may have resulted into major catastrophe in the grid and it shall be prevented for reliable and secure grid operation.
12. Points raised in 148th OCC Meeting:
 - a. Operational issue at Obra-B TPS. If Y&B-phase breaker stucked than that bus should vacate by opening of all the connected line from remote end.
 - b. Communication issue between Anpara-A TPS and Obra-B TPS
 - c. Operational issue as before opening of line side isolator and closing of earth switch O&M staff should check the line voltage in Y&B-phase.
 - d. Origin of fault.
 - e. Reason of fire in Obra-B TPS switchyard.
 - f. Reason of breaker stuck at Obra-B TPS and remedial measures

13. DR/EL and detailed report considering remedial measures is still awaited from UPPTCL.

F. Complete outage of Tehri-Koteshwar HEP complex at 19:15hrs of 29th May 2018

1. Distance Z-1 setting, A/R setting of 400 kV Koteshwar (THDC) end of 400 kV Koteshwar (THDC)-Koteshwar (PG) ckt-1 shall be checked and corrected. (**Action: THDC**, Time: Within 7days)
2. DTT (direct trip transfer) to remote end should not sent in case of operation PD (Pole Discrepancy). Koteshwar (THDC) end setting needs to be checked and corrected. (**Action: THDC**, Time: Within 7days)
3. POWERGRID shall check and report the reason of single phase A/R of 400 kV Koteshwar (PG)-Meerut ckt-2 from Koteshwar (PG) end after 500ms of fault occurrence. (**Action: POWERGRID**, Time: Within 7days)
4. POWERGRID shall also inform about the reason of over voltage in R-phase at Koteshwar (PG) bus during fault in the system. Is it related to GIS station and its phenomena? (**Action: POWERGRID**, Time: Within 7days)
5. 51NGT stage-1, 2 settings of GT (Generator Transformer) of the units at Tehri HEP having time delay of 1.2sec (stage-1 for tripping of bus coupler) & 1.6sec (stage-2 for tripping of units) needs to be relooked in view of protection co-ordination with adjacent 400 kV line. It should be tripped after tripping of Z-3 of 400 kV Tehri (THDC)-Koteshwar ckt Z-3. Reset ratio of 51 NGT also needs to be reported and improved if possible. (**Action: THDC**, Time: Within 15days)
6. In view of all tripped elements not captured in SCADA SoE data, digital SCADA data reporting from Koteshwar HEP to be checked, rectified and ensured in future. (**Action: THDC**, Time: Within 7days)
7. POWERGRID shall operationalize the DR recorder at Tehri HEP and also provide the necessary software to extract the DR details from the relay panel. (**Action: THDC, POWERGRID**; Time: Within 15days)
8. Report and remedial measures report to be submitted considering the aforesaid point. (**Action: THDC, POWERGRID**; Time: Within 15days)

G. Multiple Element tripping at 220kV Sarna (Punjab) on 01st Jun 2018 at 15:50hrs

1. ABB make Centralized Bus Bar Protection at 220 kV Sarna (Punjab) to be corrected. (**Action: Punjab**; Time: by 31.12.2018)
2. POWERGRID shall correct the reverse zone (Z-4) setting from 500ms to 100ms till the implementation of health bus bar protection at 220 kV Sarna. (**Action: POWERGRID**; Time: Within 7days)

H. Complete outage of 400kV Rosa TPS(UP) at 23:58hrs of 01st June 2018

Minutes of 36th Protection Sub-Committee meeting

1. No representative from UPRVUNL presented during the meeting, It was informed to SLDC-UP to collect the information (DR/EL, detailed report) and submit the details considering the points for discussion mentioned below (**Action: UPPTCL/SLDC-UP**, Time: Within 15days):
 - a. At 22:58hrs, 400kV Rosa-Shajahanpur-2 tripped on Z-1, fault cleared timely as seen from PMU. However, 400/220kV ICT-1 also tripped on differential protection. Reason for tripping of ICT, setting of differential protection, coordination between ICT protection and line protection to be looked into and shared.
 - b. Reason for tripping of Unit #3 at Rosa on V/f protection, setting of V/f protection to be looked into and shared.
 - c. Reason for fluctuation in V, Q of three running units, relevant plots showing such variation to be looked into and shared.
 - d. At 23:55hrs, reason for delayed clearance of fault to be looked into and shared.
 - e. At 23:55hrs, sequence of event of tripping of elements around Rosa area to be ascertained and shared
 - f. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.

I. Multiple Element tripping at 400kV Singrauli (NTPC) & Anpara (UP) Station at 15:24hrs of 02nd Jun 2018

1. In view of the lack of information and clarity about the events and no representative from UPRVUNL attended the meeting, the event would be included again for discussion in the next PSC meeting.
2. A detailed report covering the following points along with DR, station EL shall be submitted: (**Action: NTPC**; Time: Within 7days)
 - a. Bus configuration in antecedent condition at 400 kV Singrauli TPS needs to be looked into
 - b. As per SCADA SoE, reason of opening of bus sectionaliser of Bus-2A and Bus-2B needs to be looked into (as bus bar operation at 400 kV Bus-1 operated).
 - c. Exact reason of operation of bus bar protection at 400 kV Singrauli TPS as pickup setting cater the outage of one of the CT of fully loaded ckt from 400 kV Singrauli TPS.
 - d. Sensitive bus bar protection setting needs to be reviewed.
3. A detailed report covering the following points along with DR, station EL shall be submitted: (**Action: UPRVUNL/UPPTCL/SLDC-UP**; Time: Within 7days)
 - a. Bus configuration in antecedent condition at 400 kV Anpara TPS needs to be looked into.
 - b. Reason of multiple element tripping at 400kV Anpara TPS.

- c. Reason of tripping of unit-2 & 4 at Anpara TPS still awaited.
 - d. Protection co-ordination of unit protection with line distance protection needs to be looked into at 400 kV Anpara TPS.
 - e. At 15:26 hrs, from SOE it can be gathered that 400 kV Anpara-Sarnath ckt-I successfully reclosed from Anpara end after 1000ms. Details needs to be looked into
4. A detailed report covering the following points along with DR, station EL shall be submitted: (**Action: POWERGRID-NR3**; Time: Within 7days)
- a. Why all three phase main CB opened at Allahabad (PG) end of 400 kV Allahabad-Singrauli ckt-1 in antecedent condition?
 - b. Sensitive over current setting of HVDC Vindhyachal BtB to be checked, corrected and shared.

J. Multiple Element tripping at 400kV Singrauli (NTPC) Station at 15:05hrs of 10nd Jun 2018

1. A detailed report covering the following points along with DR, station EL shall be submitted: (**Action: NTPC**; Time: Within 7days)
 - a. Auxiliary supply arrangement and its single line diagram for 400/132 kV Singrauli stage-1 & 2 units to be shared.
 - b. Unit-1 tripped after some time and unit- 6 & 7 tripped immediately during fault at 132 kV bus of Singrauli TPS. It needs to be relooked. Reason of the same needs to be updated.
 - c. Unit tripping not captured in SCADA SoE. Availability of digital data needs to be looked into.
2. Reason of three phase tripping of 400 kV Anpara (UP)-Singrauli ckt from Anpara (UP) end needs to be checked and corrected. (Action: UPPTCL; Time: Within 7days)

K. Complete outage of 400kV Merta(RRVPNL) at 16:22hrs of 19th June 2018

1. Reason of non-operation of 400 kV bus bar differential protection at 400 kV Merta (Raj) shall be checked and corrected. Detailed report of the same to be submitted to NRPC/ NRLDC. (**Action: Rajasthan**; Time: Within 7days)
2. Rajasthan would check the pickup setting of bus bar differential protection and also check the fault current inward to the bus. (**Action: Rajasthan**; Time: Within 7days)

L. Multiple Element tripping at 400 kV Agra (UP) at 15:13hrs of 21st Jun 2018

1. Recommendation of 13th protection sub-committee meeting' held on 28th January 2011 again reiterated as "whenever any protection system such as Bus Bar

Minutes of 36th Protection Sub-Committee meeting

protection, LBB protection, Auto reclose etc. at generating station or grid substation is required to be taken out of service for any maintenance work, an operational code shall be taken from SLDC/NRLDC". (**General Recommendation; Action: All NR utilities**)

2. As advised in 34th PSC meeting for all NR constituents, at a substation:
 - a. Bus tied operation alarm shall be brought in front panel so that the shift operator could easily monitor the same.
 - b. Line/Bus isolator auxiliary contacts status input to bus bar protection/ stub protection operation needs to be checked after every isolator operation

General recommendation is not being followed by NR utilities. Multiple times complete outage of 400 kV and 220 kV station observed in Northern Region station. All the general recommendation should be followed strictly.

3. As reported by UPPTCL, 400 kV Numerical bus bar protection at Agra (UP) would be installed and in service by Nov-2018.
4. A detailed report covering the following points along with remaining DR, station EL shall be submitted: (**Action: UP; Time: Within 7days**)
 - a. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.
 - b. Is bus tied operation at 400 kV Agra (UP) is the reason of complete station outage?
 - c. DC earth fault at 400 kV Agra (UP) needs to be rechecked and confirmed.
 - d. As per PMU, Rise in 3-phase voltage occurred at 15:13:58.640hrs whereas tripping of relevant elements in SCADA SoE occurred at 15:13:33.405hrs and 15:13:57.874hrs. Time synchronization of digital SCADA status at 400kV Agra (UP) to be checked and corrected.
 - e. Healthiness of 400 kV bus bar protection to be ensured.
 - f. Reason of operation of bus bar protection for both 400 kV buses at Agra (UP). Similar incident of operation of both bus bar protection at 400 kV Agra (UP) on 04th Mar 2018 was also discussed during 35th PSC meeting. But remedial measures yet to be taken.
 - g. Point to be reported for 04th Mar 2018 incident (details are still awaited from UP):
 - i. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.
 - ii. Lightning Mast design in 400 kV Agra (UP) also needs to be looked into as both bus fault occurred due to lightening in the switchyard.
 - iii. As per SCADA SoE:
 1. Reason for tripping of 400kV Agra-Unnao ckt from Unnao end in ~140ms of fault to be looked into and shared.
 2. Reason for opening of 400kV Agra(UP)-Agra(PG) ckt from Agra(PG) end (tie CB during fault and main CB after ~1sec of fault) to be looked into and shared.

- iv. As per UP report, ICT-3 didn't trip. However, fault cleared in ~320ms. How the fault get cleared if ICT-3 didn't trip.
- v. As per UP report, bus bar protection of bus-2 operated and LBB of Fatehabad-1 ckt (connected to bus-2) also operated after operation of Z-4 relay (250ms time setting).

M. Multiple Element tripping at 400/220kV Sultanpur (UP) at 20:45hrs of 08th July 2018

- 1. Human error needs to be prevented and proper maintenance practices needs to be followed. (**Action: General Recommendation**)
- 2. Mal-operation of line reactor protection at 400 kV Sultanpur (UP) end of 400 kV Sultanpur-Obra ckt to be checked and corrected. (**Action: UP**, Time: Within 7days)
- 3. Protection co-ordination of 400/220 kV ICT and Zone-3 protection of remote end of Sultanpur (UP) to be checked and corrected. (**Action: UP**, Time: Within 7days)
- 4. Remedial measures report to be submitted considering the aforesaid points. (**Action: UP**, Time: Within 15days)

N. Multiple Element tripping at 400kV Rajpura (Punjab) on 23rd July 2018 at 03:15hrs:

- 1. DR recording time needs to be extended for better analysis of event. It should be - 500ms (pre fault) and +2500ms (post fault) for covering the tripping on PD (Pole Discrepancy) (**Action: General Recommendation**)
- 2. Punjab STU/ SLDC would separately organise the meeting with Rajpura TPS and find out the exact reason of tripping of Rajpura units and remedial measures. In earlier incident of line fault, tripping of generating unit reported. (**Action: Punjab**; Time: Within 7days)
- 3. A detailed report covering the following points along with remaining DR, station EL shall be submitted: (**Action: Punjab**; Time: Within 7days)
 - a. Reason of tripping of Rajpura units and remedial measures taken along with time frame.
 - b. Reason for initiation of LBB protection in few of the Tie bays at Rajpura (Punjab).
 - c. It seems from SCADA SoE and BCU Event Log data that CB of 415 and 417 bay opened after 350ms and 680ms of fault occurrence. However, fault got cleared within 100ms. Time synchronization of DR of 415 and 417 bay to be checked and corrected.

O. Multiple element tripping at 400/220 kV Panki (UP) at 02:38hrs of 26th July 2018:

- 1. Disturbance recorder shall be made functional at 400 kV Panki (UP). (**Action: UP**; Time: Within 30days)

2. DC earthing issue of all 400 kV station shall be attended or priority as it resulted into mal-operation of protection and multiple element tripping (**Action: General Recommendation**)

P. Multiple element tripping at 400/220 kV Suratgarh STPS (Raj) at 12:08hrs of 01st Aug 2018:

1. In view of the lack of information and clarity about the events and no representative from RRVUNL attended the meeting, the event would be included again for discussion in the next PSC meeting.
2. A detailed report covering the following points shall be submitted: (**Action: Rajasthan; Time: Within 7days**)
 - a. Reason of non-availability of UAT (unit auxiliary transformer) needs to be looked into.
 - b. Setting correction in back up earth fault protection of 400/220 kV ICT-1 & 2 needs to be shared along with time delay setting.
 - c. Time synchronization & status of SCADA SoE needs to be checked and corrected.
 - d. Phase Sequence error at 220 kV Suratgarh TPS needs to be checked as fault was in Yellow-phase (as per PMU data) but in Rajasthan report it was reported as Blue-phase to earth fault?
 - e. DR/EL should be available for event analysis, numerical protection to be implemented at 220 kV Suratgarh TPS (Bus Bar and ICT protection).


Q. Multiple element tripping and SPS operation at Jhakri/Rampur/Karcham complex at 04:02hrs of 29th Aug 2018

1. A/R issue of 400 kV Nalagarh-Rampur ckt-2 shall be discussed and resolved. Kindly check the necessity of PoW (Point on Wave) device, discuss with OEM and if it is not required than kindly bypass it (**Action: SJVNL; Time: Within 15 days**)
2. Parallel input of the R, Y & B-phase breaker instead of series input to the SPS logic at 400 kV Rampur HEP shall be corrected. (**Action: SJVNL; Time: Within 15 days**). Same issue shall also be checked at 400 kV Jhakri and Karcham HEP. (**Action: SJVNL, Himachal Pradesh (JSW); Time: Within 15 days**)
3. SJVNL shall share the following SPS details:
 - a. Logic calculation time.
 - b. Time in which tripping command sent to units after meeting the condition for SPS.
 - c. Logic for various SPS conditions checking.
4. Time synchronization of SCADA SoE shall be checked and corrected. (**Action: SJVNL; Time: Within 7 days**)

B.2 Oscillation and SPS related Agenda points


A. Observance of Oscillations in the grid on 08th Aug 2018 due to tripping of one of the evacuation line from 400kV Tehri-Koteshwar complex (N-1 contingency of line outage:

Tehri HEP is the major hydro generating station with 1000MW (4*250MW) capacity and in its downtail Koteshwar (THDC) HEP with capacity of 400MW (4* 100MW). The main evacuation line from the Tehri-Koteshwar HEP complex is 176 kM long 400 kV Koteshwar Pool to Meerut D/C line with 50% series compensation of each circuit at Meerut end. Connectivity Diagram is as below:




The antecedent generation of 1000 MW from Tehri HEP and 360 MW from Koteshwar HEP was being evacuated through on 400 kV Koteshwar Pool -Meerut ckt-1 & 2.



Fixed Series Compensation (FSC) of 400 kV Koteshwar Pool- Meerut- ckt-2 is out of service since 16th July 2015 except for brief period during July 2017 (01-13 Jul 2017). FSC of 400kV Koteshwar Pool -Meerut ckt-1 also went under outage on 1st Aug 2018. Thus at the incident time both the FSCs were out of service. SCADA plot of power flow of 400 kV Koteshwar Pool-Meerut ckt-1 & 2 is as below:



At 01:36hrs, 400 kV Koteswar Pool –Meerut ckt-2 tripped on Y-N fault after unsuccessful auto reclosing. Line tripped on permanent nature of fault after auto reclosing of the line. After tripping of 400 kV Meerut-Koteswar Pool ckt-2, power flow on ckt-1 reached more than 1200MW.

The outage of 400 kV Tehri-Koteswar (Pool) ckt-2 caused severe oscillations of growing nature in the grid. The voltage & Frequency of Meerut PMU is given below:





The oscillations seems to damp only after tripping of one unit at Tehri HEP after 21 second on some protection.

The modal analysis carried out on few of the frequency signal from PMUs of Northern Region stations indicate negative damping for dominant mode of **0.675Hz**.

Although SPS was implemented at Koteshwar (Pool) with following logic:

“If any one of the 400 kV Koteshwar-Meerut circuit trips and sum of antecedent power flow on both the circuit is more than 1200MW, one unit of 250 MW of Tehri HPS should be tripped instantaneously”

However, during this event this SPS did not operate despite conditions for operation of SPS being prevalent.

In 141th OCC meeting, after incident of 09th Nov 2017 in which widespread oscillation observed for 50 second, it was decided to change the setting of 1200MW to 1100MW in SPS logic of Tehri Koteshwar complex.

Oscillations were very severe and can have impact on safety and security of grid as well as that of units.

This Agenda point was again discussed in 151st OCC meeting, in which oscillation details were shown and discussed. Following points were discussed during the meeting:

- At Tehri HEP, the setting of unit #1 dead fault to be checked. Further, the sensitivity of Unit #1 as compared to other units also needs to be checked: ***THDC informed that AVR setting of unit-1 would checked in Nov-2018 and report would be submitted.***
- Full SPS including the functional logic needs to be checked at Koteshwar (PG)/ Tehri HEP: ***POWERGRID shall kindly update***
- In SPS logic, tripping of two units at Tehri HEP could also be thought of: ***Tripping of one unit at Tehri and one unit at Koteshwar HEP was approved. THDC shall kindly implement the tripping signal at Koteshwar HEP in co-ordination with POWERGRID.***
- In view of several fault incidents in recent past, strengthening of 400kV Tehri-Koteshwar-Meerut transmission lines to be looked into: ***Line maintenance needs to be checked and reported by POWERGRID.***
- Setting of df/dt relay operated in Punjab to be checked and shared: ***Punjab informed that df/dt setting checked at S/S and all the setting are as per NRPC recommended setting.***
- Any UFR, df/dt relay operation in any other state to be checked and confirmed: ***Details are awaited from the other utilities. Other state utilities kindly inform about operation/ non-operation of df/dt relay in its control area.***
- Long outage of FSC of 400 kV Meerut-Koteshwar ckt-2 to be looked into and revival of FSC shall be expedited: ***POWERGRID shall inform.***
- AVR/ PSS tuning needs to be looked into for better tuning at Tehri and Koteshwar HEP: ***Last PSS tuning was conducted in Dec. 2015 and to comply the guidelines issued in 34th NRPC and 30th TCC, the process for engaging M/s BHEL expert for PSS Tuning/Step response test of Excitation Systems (4 X 250MW) of Tehri HPP has already been initiated and the work shall be completed tentatively by Nov'18.***

- Reason of outage of FSC of 400 kV Meerut-Koteshwar ckt-1 (01 Aug to 08 Aug 2018) without informing to NRLDC, to be informed and such future cases to be avoided: **POWERGRID shall inform.**
- Auto reclosure issue of tie CB of 400 kV Meerut (end)-Koteshwar Pool ckt-2 to be checked and corrected: **POWERGRID shall inform.**

POWERGRID informed that SPS testing would be done in the month of Oct 2018 and healthiness of SPS protection would be ensured.

NRPC requested POWERGRID/ THDC to kindly also implement the tripping of one unit of Koteshwar (THDC) in the existing SPS at the earliest possible.

B. Oscillations observed in the grid on 25th & 29th July 2018 due to tripping of one of the evacuation line from 220 kV Dhauliganga HEP :


220 kV Dhauliganga station is connected with 220 kV Bareilly (UP) through two twin moose (400 kV charged at 220 kV) D/C line, in which one circuit has LILOed at 220 kV Pithoragarh (PG) (59km from Dhauliganga).

In last three months, three incident of growing nature of oscillations have been observed in the grid. Consolidated summary of these incident of growing nature of oscillation is tabulated below:


Particulars	Event at 18:07hrs of 18.04.2018	Event at 14:49 hrs of 25.07.2018	Event at 16:56 hrs of 29.07.2018
Antecedent Generation at Dhauliganga HEP	280MW	285MW	285MW
Event Brief	At Dhauliganga HEP, testing was underway from 17:00hrs of 18-Apr-18 to address the issue of oscillation observed at Dhauliganga HEP in the past. During this, as reported, full generation (280MW) at Dhauliganga was made to evacuate through one 220kV Pithoragarh ckt only. The testing also included different scenarios of PSS ON and	Tripping of 220 kV Dhauliganga-Pithoragarh ckt on B-N fault resulted into 285MW loading on Bareilly ckt. It further initiated the	Tripping of 220 kV Dhauliganga-Pithoragarh ckt on R-N fault resulted into 285MW loading on Bareilly ckt. It further initiated the growing nature

	OFF on different number of units (two units PSS ON and two units PSS off). Initiation of oscillations in the grid and resulted in tripping of unit number-1 at Dhauliganga. Immediate backing down (10MW from 70MW) was done at other units which resulted in damping of oscillations	growing nature of oscillation in the system	of oscillation in the system
Faulted phase and duration	No fault, testing was underway	B-N fault & 100ms	R-N fault & 100ms
Dominant mode of oscillation (in Hz)	0.8Hz	0.8Hz	0.87Hz
Damping	Negative	Negative	Negative
Duration of Oscillation	2 minutes	24 second	13 second
Generation Loss (in MW)	70	285	285
Oscillation continued till	Tripping of one unit and manual generation backing down (how much MW)	Tripping of remaining circuit (220 kV Dhauliganga-Bareilly (UP)) in Z-1 and all the running units of Dhauliganga HEP	Tripping of remaining circuit (220 kV Dhauliganga-Bareilly (UP)) on out of step (OOS) protection and all the running units of Dhauliganga HEP


The impact of oscillation was widespread in the grid and oscillation also observed on Inter Regional lines from NR. PMU plot of frequency and voltage during oscillation is given below:




PMU plot of frequencies at different stations showing oscillation (18th Apr 2018)




Power Spectral Density showing dominant mode of oscillation (18th Apr 2018)




PMU plot of frequencies at different stations showing oscillation (25th July 2018)



PMU plot of Voltages at different stations showing oscillation and B-N fault (25th July 2018)



PMU plot of frequencies at different stations showing oscillation (29th July 2018)



PMU plot of Voltages at different stations showing oscillation and R-N fault (29th July 2018)

This Agenda point was already discussed in 150th OCC meeting, in which oscillation details were shown and discussed. Following points were suggested to NHPC:

- Proper tuning/ retuning of PSS/AVR of the units at 220 kV Dhauliganga HEP
- SPS (System Protection scheme). With the following logic shall be implemented at 220 kV Dhauliganga HEP.
 - Probable logic of SPS could be: *Trip two units at Dhauliganga HEP in case of tripping of one of the 220 kV outgoing lines from Dhauliganga HEP or power flow on any of the outgoing line become zero*

Decision in 150th OCC meeting:

- NHPC representative stated that SPS logic has been prepared on the basis of power flow on lines and would be shared and approved in upcoming OCC/PSC meeting.
- NRLDC representative requested that PSS tuning shall be extensively carried out and report to be shared. Further, the dynamic machine parameters are important to assess the dynamic behaviour of the system and shall be shared by NHPC and other constituents as well.
- OCC requested constituents to provide the respective details.

Punjab representative informed that measurement cycle of UFR and rate of change of frequency (df/dt) in Punjab is in between 5-8 cycle. Measurement cycle setting is location dependent, if mal-operation arise at any location than setting is 8 cycle otherwise it is 5 cycle. Df/dt (rate of change of frequency) operated at Amritsar, Bhatinda, Chandigarh and its nearby area.

NRPC suggested Punjab to put the measurement cycle setting as 8 cycle instead of 5 cycle.

NHPC representative submitted the SPS logic details and same is attached as Annex-XI of the Agenda.

NRLDC representative stated that SPS proposal submitted by NHPC is more or less ok except this logic would not help during outage of one bus at Dhauliganga HEP and suggested NHPC to prepare procedure for immediate manual backing down of the generation at Dhauliganga in such condition.

NRPC suggested NHPC to put the proposal in next TCC meeting for approval of the member and implement the scheme till Nov-2018.

Annexure- I

List of participants for 36th Protection Sub-Committee Meeting.**Date:19.09.2018**

Sl. No.	Name	Designation	Organization	Tel. No./Mobile No.	E-mail
1	Sh. Prakash Negi	Asstt. Manager	SJVNL	9736549558	ee.23007@gmail.com
2	Sh. Pankaj Kumar Gupta	AE	UPPTCL	9453043916	pankaj_hil@yahoo.co.in
3	Sh. Mohd. Waris Khan	SE	UPPTCL	9415311083	setncalbd@upptcl.org
4	Sh. Rajbir Singh Walia	ASE	PSTCL	9646118223	ce_pm@pstcl.org
5	Sh. Jaganath Pani	Asstt. Manager	NHPC	7978699693/9410220248	jaganathnhpc@gmail.com
6	Sh. SK Das	Manager (E)	NHPC	9717786721	sdas_nhpc@yahoo.co.in
7	Sh. D.P. Singh	AGM(OS)	NTPCL	9450916643	dpsingh05@ntpc.co.in
8	Sh. BS Meena	EE	NRPC	8750251805	bhanwarmeenamop@gmail.com
9	Sh. Ratnesh Kumar	EE	NRPC	9811101805	ratnesh.cea@gmail.com
10	Sh. Nitin Yadav	उप प्रबंधक	POSOCO	9560050257	nitinyadav@posoco.in
11	Sh. R.P. Pradhan	SE	NRPC		rp.pradhan@nic.in
12	Sh. S.S.S. Laxman Rao	Manager	THDCIL	9557735777	ssslaxmanrao@gmail.com
13	Sh. Sandeep Yadav	EE	HVPNL	9310404372	mpccggn@gmail.com
14	Sh. Rajender Singh Redhu	Asstt. Director	BBMB	9466121202	rsinghredhu@yahoo.com
15	Sh. RK Chandan	Director	BBMB	9417202059	dirpc@bbmb.nic.in
16	Sh. Kishori Lal	SE	UPPTCL	9458096601	setncagra@upptcl.org

17	Sh. VM Singh	GM	UPPTCL	7355022380	vmsingh@isowxinfrastructure.com
18	Sh. Soni Kumar	Sr. Mgr	SJVNL	9418450875	visit2soni@gmail.com
19	Sh. Abhishek Sharma	Mgr (T)	DTL	9999533893	abhidtr.2@gmail.com
20	Sh. Hitesh Kumar	DGM(T)	DTL	9999533662	hiteshkumar.dtl@gmail.com
21	Sh. Hemanshu Pundir	EE(T&E)	UPPTCL	9412749819	etncmrt@gmail.com
22	Sh. KK Chaudhary	EE(T&C)	UPPTCL	8887137962	setncgkp@gmail.com
23	Sh. Nitin Verma	Manager	POWERGRID	8005499952	nverma@powergridindia.com
24	Sh. M.S. Hada	Ch. Manager	POWERGRID	9650555997	mshada@powergridindia.com
25	Sh. Praveen Kumar	Manager	PG-NR-II	9906546606	me.praveenkumar@powergridindia.com
26	Sh. Vikas Saxena	President (PS)	LPGCL	9971200857	vsaksena@lpgcl.com
27	Sh. H.K. Chawla	DGM	POSOCO	9650074803	hk.chawla12@gmail.com
28	Sh. Pankaj Malviya	SE (T&C)	UPPTCL	9450909474	mpankaj121@gmail.com
29	Sh. Amit Gupta	Dy. Manager	POSOCO	8800690954	amitgupta@posoco.in
30	Sh. R. C. Mahawar	XEN	RRVPNL	9413384026	xen1.prot.jaipur@rvpn.co.in
31	Sh. Amit Kumar Gupta	CE	RRVPNL	9414061096	ce.mps@rvpn.co.in
32	Sh. B.L. Yadav	AGM	NTPC	9650993044	blyadav@ntpc.co.in

S.No	Constituent/ Utility	Nomination			
		Name	Designation	Address	Ph. (O) /Mob. No.
1.	SJVNL	1.Sh. Prakash Chand	Manager (E)	NJHPS, Jhakri, Distt-Shimla, HP	01782-275140
		2.Sh. Pintu Das	Dy.Manager (E)	NJHPS, Jhakri, Distt-Shimla, HP	01782-275140
2.	DTL (Updated)	1.Sh. Praveen Kumar	AM (T)		9999533903
		2.Smt. Ramneet Chanana	AM(T)		9999533730
		3.Sh.Avishek Malik	AM (T) Prot.		9999535139
3.	POWERGRID	1.Sh. Y.S. Rana	Sr. Engr.	POWERGRID, Moga	09501102085
		2.Sh. Subhas Kumar	Sr. Engr.	POWERGRID, Hisar	09729872353
		3. Sh. Ajay Gola	Sr. Engr.	NR-I HQ, New Delhi	09899555175
4.	NTPC	1.Sh. B.L.Yadav	AGM (OS)		09650993044
5.	PSTCL (Updated)_	Sh. Ranbir 1. Singh Walia	ASE	PSTCL, Ludhiana	9646118223
		2.Sh. Harvinder Singh	Sr EXN, Protection	PSTCL, Jalandhar	
		3. Sh Sanjeev Kumar	AEE	Protection Division, Mohali	
6.	HVPNL	1.Sh. Y.S. Gulia	Executive Engineer	HVPNL, M&P, Panipat	09354194830
7	RRVNL	1. Sh.Jyotirma Jaiminy	AEN-III (C&M)	400 kV GSS, Heerapura	09413382408
		2. Sh. Vijay Pal Yadav	AEN (Prot.)	RRVNL, Alwar	09414061407
8	UPPTCL	1.Sh. D.K Acharya	Advisor to Director (Op) UPPTCL	Shakti Bhawan Extn (11 th Floor) 14, Ashok Marg, Lucknow-226001	Ph.(O) –Director (Op) office 0522-2287833 Fax- 0522-2286476
		2.Sh. Kavindra Singh	Advisor to CE (TW), Meerut UPPTCL		
9	HPSEBL	1. Sh. Sat Pal Jamwal	Exe.Engg.	Protection & Testing Division, HPSEB Ltd. Kangra (HP)	09418122067 Telefax- 01892-264519
		2.Sh. Dharam Singh Rana	Asst. Engg.	Protection & Testing Division, HPSEB Ltd. Kangra (HP)	09418017213 Telefax- 01892-264519
10	PTCUL	1.Anupum Singh	Exe.Engg.	T&C	
		2. Asim Beg	Asst. Engg.	T&C	
11	NPCIL	1. Sh. N. K. Pushpakar	Maintenance Superintendent NAPS, or his nominee	Plant Site, Narora, Bulandshahar Distt. UP-202397	(5734) (O) 222167 (R) 222228 M-09412768002 e-mail- nkpshpakar@npcil.co.in

		2. Sh. Virender Yadav	RAPS-A	Rawatbhata Rajasthan Site, P.O. Anushakti, via: Kota, Rajasthan-323303	M- 09413358024
		3. Sh. Sanjay Jhamtani	RAPS-B	Rawatbhata Rajasthan Site, P.O. Anushakti, via: Kota, Rajasthan-323303	M- 09413356912
		4. Sh. Randhir Misra	RAPS-C	Rawatbhata Rajasthan Site, P.O. Anushakti, via: Kota, Rajasthan-323303	M- 09413358237
12	RRVNL	1. Sh. Jyotimay Jaiminy	AEn-III (O&M)	400 kV GSS Heerapura, Jaipur	09413382408
		2. Vijay Pal Yadav	AEn(Prot.)	RRVNL, Alwar	09414061407
13	Rosa Power Supply Co. Ltd.	1. Sh. N. Kishore Kumar	DGM	Rosa Power Supply Co.Ltd., Hardoi Road, Service Building, Rosa Shahajahanpur-242406	05842-306675/09389495241
		2.Sh. Gaurav Gupta	Sr. Manager	Rosa Power Supply Co.Ltd., Hardoi Road, Service Building, Rosa Shahajahanpur-242407	05842306789/09369076402
14	NHPC	Sh. Amitabh Jha	Sr. Manager (E)	Uri Power Station, Baramullah, J&K	
		Sh. P. K. Das	Manager (E)	Baira Siul Power Station, Chamba, HP	
15	UJVN Limited	1. Sh. Manoj Rawat	A.E.	Dakpathar, Distt: Dehradun	09456590406
		2. Sh. Anoop Deepak	A.E.	Galogi, Distt: Dehradun	09456590173
16	BBMB	Sh. Ranbir Singh Sharma	Assistant Director	P&T Cell BBMB Panipat	9466121202



केन्द्रीय विद्युत अनुसंधान संस्थान

(भारत सरकार की सोसाइटी, विद्युत मंत्रालय)

प्रो सर सी. वी. रामन रोड, सदाशिवनगर डाक घर, पो. बा. सं. 8066, बेंगलूर - 560 080

CENTRAL POWER RESEARCH INSTITUTE

(A Govt of India Society under Min. of Power)

Prof. Sir C.V. Raman Road, Sadashivanagar P.O., P.B. No. 8066, Bangalore - 560 080, India

वेबसाइट/website : <http://www.cpri.in>

No.

04. Sept., 2018

To,

Member Secretary

Northern Regional Power Committee,

Central Electricity Authority,

18-A, Shaheed Jeet Singh Marg,

Katwaria Sari,

Delhi -110016

Dear Sir,

Sub: Protection Audit-Workshop/Training Programme.

Drawing your kind attention on the discussion held in Power Systems Division on 24 August 2018 at CPRI regarding organising the Protection Audit training programme for the Utilities under NRPC at Bangalore.

First of all we are thankful for your interest in this training programme & we are hereby pleased to submit the offer for same.

1.0 INTRODUCTION:

Government of India has established the Northern Regional Power Committee (NRPC) comprising of power systems and generating units of union territory of Chandigarh, states of Haryana, Himachal Pradesh, Jammu and Kashmir, Punjab, Rajasthan, Uttarapardesh, Uttrakhand and Delhi. To facilitate the stability and smooth operation of the integrated grid and economy & efficiency in the operation of power system in the Northern region, NRPC is involved by undertaking regional level operation analysis for improving grid performance,

facilitating inter-state/inter-regional transfer of power, and planning for maintaining proper voltages through reactive compensation studies for the states coming in Northern region.

Protection is one of the key operational aspect of power systems operation. The revision in protection setting /schemes for modification in network topologies is essential for reliable operation of power systems. The NPRC coordinates with all transmission utilities of Northern Grid for any revision in Protection schemes/setting and auxiliary protection function. Therefore periodic audit of these protection schemes/setting/protection functions and auxiliary protection is an healthy practice for enhancing the protection reliability.

In the recent past, CPRI carried out protection audit for RVPNL, BBMB, UPPTCL, PSTCL, Power grid western region, Goa Electricity Board NHPC, Torrent Power, Essar Power, Nellore Power Plant, Indrasagar, Rosa Power, Panki Power etc.

In this context, *Power Systems Division of Central Power Research Institute* (CPRI) is pleased to submit an offer for conducting a protection audit programme for Power Utilities under NRPC.

2.0 Topics to be covered.

The topics to be covered in brief during the three (03) days training programme are as under:

- Day1- Protection Audit of main Protection for Power Transformer, Lines, Bus bars, reactors & Short circuit Studies.
- Day-2: Protection Audit of main Protection for Alternators
- Day-3: Protection Audit of Backup Protections & Auxiliary Protection functions
Demonstration of Protection in Lab. & Lab. visits

The actual daily schedule may change as per the availability of Experts.

3.0- Training Fee

Training Fee for Central /State Govt. Power Utilities/ Electricity Boards Personnel is as under:

Fee Per Day/Participant <i>Rs.</i>	Days	Total Without GST <i>Rs.</i>	Total with GST@18% <i>Rs.</i>
3,500	3	10,500	12,390

The fee is to be paid in favour of "CPRI, through online transaction mode as per following details:

Name of beneficiary-Central Power Research Institute
Branch SBI, CPRI
IFSC Code: SBIN0010370
Account No: 10356553310.

4.0: Travel and Accommodation

- Bengaluru is well connected by Road, Rail and Air
- Participants have to make their own travel arrangements
- Guest house accommodation on twin sharing basis can be provided on chargeable basis subject to availability
- CPRI is situated in between Mekhri Circle and Yeshwanthpur.
Near Indian Institute of Science (commonly known as Tata Institute)


5.0 Venue:

CCAR Auditorium, Central Power Research Institute
Prof. Sir. C V Raman Road,
Sadashivanagar P O,
Bengaluru 560 012

I hope the above, training offer meets the protection audit requirement of NRPC, if any additional requirement are there, and same may be communicated to CPRI

Thank you

Yours sincerely,



04th Sept 18

(K. S. Meera)

Additional Director, Power Systems Division

Status of pending rectification of defects observed during BPA

Sl. No.	Utility	No. of sub-stations covered under BPA	Expected Completion	Remarks
1	UPPTCL	21	-	Representative of UPPTCL informed that in 220 kV stations, auto recloser deficiency due to PLCC issue is remaining rest all have been rectified. Order has been placed for PLCC and deficiency will be rectified once the equipment are supplied.
2	UPRVUNL	4	-	<p><u>Obra 'A'</u> – including rectification of time synchronization & BBP, PLCC (to be installed by UPPTCL). To be completed by November, 2016.</p> <p><u>Harduagani</u> – to be completed by March, 2017</p> <p>Status could not be updated as there was no representation from UPRVUNL in the last 03 (33rd PSC, 34th PSC and 35th PSC) meetings.</p>
3	HPSEB Ltd.	1	October 2017	<ul style="list-style-type: none"> • Out of 12 deficiencies observed, 8 already rectified. • 1 no. deficiency to be rectified by March 2017 and • 3 others by October 2017.
4	UJVNL	1	December, 2016	<p>Breaker for 220 kV Khodri-I &II needs to be replaced. Expected date as intimated by SLDC Uttarakhand in 127th OCC meeting was 31.12.2016.</p> <p>Status could not be updated as there was no representation from UJVNL in the meetings.</p>
5	PDD, J&K	3	Status of progress is not submitted.	As informed during 33 rd NRPC meeting that deficiencies where procurement was not involved had been rectified and other

			Target completion not known.	<p>works where procurement is involved are yet to be taken up. PDD J&K informed that they have submitted the proposal for PSDF funding and deficiencies will be rectified when fund will be disbursed from PSDF.</p> <p>As informed by PSTCL defects at 220kV Sarna-Udhampur line, pertains to PDD, J&K.</p> <p>Status could not be updated as there was no representation from PDD J&K in the meetings.</p>
--	--	--	------------------------------	---



Protection audit of intra-state system/balance system not covered in Basic Protection Audit

Utility	Third party protection audit carried out by	No. of sub-stations covered/ expected to be covered	Status of Audit	Status of Report	Status of submission of action Plan for rectification of deficiencies
RRVPNL, RRVUNL	CPRI	RRVPNL-39 RRVUNL-5	Completed	Submitted	<u>RRVPNL</u> - Lead Acid Batteries have been procured and installed. <u>RRVUNL</u> - Action Plan submitted.
BBMB	-do-	20	Completed	Submitted	The action to attend the deficiencies observed in the audit is underway.
PSTCL, PSPCL	-do-	PSTCL-22 PSPCL-3	Completed	Submitted	Representative of PSTCL informed that Report on CPRI Audit already submitted and emailed.
UPRVUNL	-do-	2	Completed	Submitted	Parichha TPS and Panki TPS: All the deficiencies are likely to be rectified by March, 2018
UPPTCL	-do-	41	Completed	Shall be submitted after receipt and examination of Report, same.	Action plan to be submitted by 11.08.2017 .

Utility	Third party protection audit carried out by	No. of substations covered/ expected to be covered	Status of Audit	Status of Report	Status of submission of action Plan for rectification of deficiencies
Rosa Power	-do-	1	Completed	Submitted	Action Plan submitted and the deficiencies observed rectified.
UJVNL	-do-	2 (Chilla, Chhibra)	Completed	Submitted	Action Plan not submitted. No representative was present.
PDD J&K	-do-	3 (Janipur, Amargarh, Hiranagar)	Completed	Submitted	Action Plan for Heeranagar and Amargarh not submitted. No representative was present.
JSW	-do-	1	Completed	Submitted	Rectification of observation complied.
HPSEB Ltd.,	-do-	6 (Uprela Nangal, Giri 220 kV, Jassore 220 kV, Baddi, 220 kV Kangoo, 220 kV Kotla)	Completed	Submitted	Action Plan for 220 kV Kotla not yet submitted. Rectification of observation partly complied. Rectification will be completed by October 2017
UT Chandigarh	-do-	1 (Kishengarh)	Completed	Submitted	Not submitted. No representative was present.
Budhil Power	-do-	1	Completed	Submitted	Not submitted. No representative was present.

Utility	Third party protection audit carried out by	No. of sub-stations covered/ expected to be covered	Status of Audit	Status of Report	Status of submission of action Plan for rectification of deficiencies
HVPNL	-do-	4 (Sector 72, Gurgaon ; Tepla; Bastara; A-5, Faridabad)	Completed	Submitted	To be rectified by December 2017
DTL	-do-	4 (Rohini; Mehrauli; Mundka; Shalimar Bagh)	Completed	Submitted	Action has already been taken. Report will be submitted.
PTCUL	-do-	4 (Pantnagar, Haridwar, Kashipur, Roorkee)	Completed	Submitted	Not submitted for Haridwar, Roorkee Relays have been delivered at the site. To be completed by 31 st October, 2017



Status of Bus bar Protection for Northern Region Constituents

State/ Constituent	TRANSC O/GENC O	Total no. of S/S/ Sw. yards (220 kV and above)	No. of S/S/ Sw. yards where Bus bar protection is functioning	Remarks	Action Plan
Delhi	DTL	37	34	For 220 kV S/S namely, Gopalpur and Kanjhawala is being planned.(Lodi Road is GSS)	PO awarded to M/s GE T&D India Ltd. for the work of Supply and ETC of 26nos. Bus Bar Schemes in 400 and 220kV DTL substations on 06.04.18. Completion period is 9 months.
Haryana	HVPNL	56	39	17 nos. defective	1 done; next 14 by June ,17 and other 2 in 2017-18, as control cable was not available.
	HPGCL	03	03		
Rajasthan	RVPNL	53	46 (7 defective)		74 nos. New Bus bar Protection scheme under commissioning. 10 Commissioned.
	RVUNL	05	05		
Himachal Pradesh	HPSEB	08	04	At one s/s it was working, 2 sub-station it was defective.	04 nos. commissioned and for remaining 04

					s/s to be done by Oct 2017.
Punjab	PSTCL	98(5 no 400 kV s/s)	46(5 no. 400 kV s/s)		Work in progress for BBPS protection, 46/98 (220kV) 05/05 (400kV) completed. Till then reverse zone protection time set to 160 ms. For remaining substations, work has been undertaken by TS organization and will be completed by 31.12.19. by TS organization. Procurement process for BBPS delayed due to re-tendering twice by Finance wing of PSTCL. Re-tendered again last month and target date is 31-12-19 & PSDF funding available. PLCC work will also be completed by 31-3-19 as procurement process is underway.
	PSPCL	03	03		
J&K	PDD	06	-		The status for the same could not be ascertained as representative from PDD, J&K

					was not present in the meeting.
Uttarakhand	PTCUL	10	09		Order placed for 01 defective. Would be completed by May 2017.
	UJVNL	-	-		
BBMB	BBMB	23	20	Not required at Dhulkote and Jagadhari. also for Sangrur, Kurukshetra and Delhi as no. of feeders is less than five. PSC decided that it needs to be installed.	Sangrur-commissioned 19.01.2016. For Kurukshetra and Delhi, LOI has been issued on 27.06.18 & material is likely to be received by March, 2019. For Barnala it is to be provided by PSTCL as agreed in PSC. PSTCL were to commission it by 31.12.2016.
Uttar Pradesh	UPPTCL	99	10	04 no. are pending	For the remaining stationed procurement action has been initiated.
	UVUNL	05	-		
POWERGRID	PGCIL	55	55		
Central Generating Stations	NTPC	11	11		
	NHPC	09	09		
	NPCIL	02	02		
	THDC	02	02		
	SJVNL	02	02		

List of members of Protection Analysis Sub-Group (PSAG)

Sl. No.	Organisation	Nominated Officer	Contact Details
1.	NRPC Secretariat	Sh. B S Meena	+91-8750251805
2.	NRLDC	Sh. Nitin Yadav	+91-9560050257 yadavnitin06@gmail.com
3.	PGCIL, NR-1	Sh. M S Hada	+91-9650555997 mshada@powergridindia.com
4.	PGCIL, NR-2	Sh. Praveen Kumar	+91-9501102054 mr.27praveenkumar@powergridindia.com
5.	BBMB	Sh. Sunil Shivaj Sh. Ravi Lal, Dy. Director Sh. Amandeep Singla, Asst. Director Sh. Sunil Kumar, Asst. Director	+91-9728107866 ddpntbwn@gmail.com
6.	DTL	Sh. B L Gujar	+91-9999533985
7.	UPPTCL		
8.	NTPC, NR	Sh. Md. Zia	+91-9415005883
9.	NTPC, NCR	Sh. B L Yadav	+91-9650993044
10.	NPCIL	Sh. Sanjay Jamtani	+91-9413356912
11.	HVPNL	Sh. R N Mishra	+91-9312712754 mpccggn@gmail.com , rnmisraxon@gmail.com
12.	RVPNL	Sh. R C Mahavar	+91-9413384026 xen1.prot.jaipur@rvpn.co.in
13.	PSTCL	Sh. Rajbir Walia	+91-9646118223
14.	PTCUL	Sh. Anupam Singh	+91-7088117919
15.	HPSEB	Sh. Rajender Kumar Singh	+91-9418225566
16.	NHPC	Sh. S K Das	+91-9717786721

17.	SJVNL	Sh. Pintu Das Sh. Prakash Chand	+91-9418475284 +91- 9418492085
18.	Adani Power	Sh. Sanjay Bhatt	+91-9099005221 Sanjay.bhatt@adani.com
19.	PSPCL		
20.	HPGCL	Sh. Raman Sobti, (PTPS, Panipat) Sh. Jitender Kumar, (DCRTPP, Yamunanagar) Sh. Vineet Mishra, (RGTPP, Khedar)	9355084410 raman.sobti@hpgcl.org.in
21.	UPRVUNL	Mr. Shekh Salim	9415900086 se.omc_3.parichha@uprvunl.org
22.	IPGCL	Mr. Arif Rahman Mr. Satyendra Prakash	+91- 9717694928 +91- 9717694813
23.	UJVNL		
24.	PGCIL, NR-3	Sh D Kushwaha	+91-9425409591 dkushwaha72@gmail.com

Annexure - VIII

1. Tripping events

A. Multiple Element tripping at 765/400kV Anta (Raj) at 14:40hrs of 02nd May 2018

Event category: GD-1

Generation loss: 1315 MW (As per Rajasthan report)

Loss of load: Nil (As per Rajasthan report)

Energy Loss: Nil (As per Rajasthan Report)

Data Summary received/available at NRLDC:


Description	Reference	Fault Info	Remarks
Fault Clearance Time	PMU data	NA	No fault
Phase of the fault	PMU data	NA	No fault

Description	Utilities	Status	Remarks
Availability of Digital Data (SCADA Data)	Rajasthan	Not Available	
DR/EL	Rajasthan	Received	Within 24hrs
Preliminary Report	Rajasthan	Received	Within 24hrs
Detailed Report	Rajasthan	Not Received	Remedial action report pending

Description	Clauses	Utility	Remarks
Violation of Clauses	1. 43.4.A of CEA Technical Standard for Construction of Electrical Plants and Electric Lines 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3) 3. CEA Grid Standard 3.1.e 4. CEA Transmission Planning Criteria	Rajasthan	1. Detailed Report didn't provide 2. Adequately Sectionalized and graded protective relaying system 3. Incorrect/ mis-operation / unwanted operation of Protection system

Based on above information description of the events is:

1. Connectivity Diagram of Chhabra/ Kawai/Kalisindh complex:



2. 400 kV Anta (Raj) is connected with Kawai D/C, Kalisindh D/C, Chhabra SCTPS D/C and three 3*500MVA 765/400 kV ICT's. It has one and half breaker scheme.
3. 400 kV Bus-2 of Anta (Raj) was already under planned shutdown for testing of bus bar protection.
4. During testing all tie CB except tie CB for 400 kV Kalisindh ckt-2 tripped at 400 kV side of 765/400 kV Anta (Raj). No power system fault occurred in the system.
5. After tripping of all main and tie CB at 400 kV Anta (Raj), 400 kV Kalisindh ckt-1, Kawai D/C, Chhabra SCTPS D/C tripped.
6. After tripping of 400 kV Kawai-Anta (Raj) D/C, Kawai generation pushed towards Chhabra TPS. As 400 kV Chhabra-Hindaun ckt was already under planned outage, 400 kV Chhabra-Bhilwara ckt loaded in the range 1100-1200MW.
7. Sudden shifting of power and constraint in transmission network resulted into oscillation in the system.
8. 400 kV Chhabra-Bhilwara ckt also tripped on power swing.

9. After tripping of all outgoing transmission line from Chhabra-Kawai complex resulted into outage of units (three units at Chhabra TPS, one unit at Kawai SCTPS) on over speed/ over frequency protection.
10. As 400 kV Anta-Kalisindh ckt-2 remain connected in the system, it resulted into survival of only running unit (unit-2) of 400 kV Kalisindh TPS.
11. SPS didn't operate at 400 kV Kawai SCTPS.

12. Antecedent Condition:

- 400 kV Chhabra-Hindaun ckt was already under planned shut down.
- 660MW Unit-2 of Kawai SCTPS was already under planned outage.
- Unit-1 of Kalisindh TPS was also under planned shutdown on less demand
- Unit-4 of Chhabra TPS was under planned shutdown.
- Power flow on different feeders:


S. No.	Name of Element	Load before the incident
1	400 kV CTPP-Bhilwara line	400 MW
2	400 kV CTPP-Hindaun line	0 MW
3	400 kV CTPP-Adani line	135 MW
4	ICT	185 MW
5	Unit#1	250 MW
6	Unit#2	250MW
7	Unit#3	250 MW
8	Unit#4	0 MW

13. Name of the tripped elements are as below:

- 400 kV Anta-Kawai ckt-1 & 2
- 400 kV Anta-Kalisindh ckt-1
- 400 kV Anta-Chhabra ckt-1
- 400 kV Chhabra-Bhilwara ckt
- 400 kV 250MW Unit-1,2,3 of Chhabra TPS.
- 400 kV 660MW Unit-1 of Kawai SCTPS


14. DR plots:

DR -400 kV Chhabra(end) –Bhilwara ckt




Continuous oscillation observed in the line.
It seems DR capturing time is 1000ms instead of 2500ms (decided in PSC meeting)

DR -400 kV Chhabra(end) –Kawai ckt




Continuous oscillation observed in the line.
It seems DR capturing time is less than 2500ms as decided in PSC meeting


DR -400 kV Chhabra(end) Unit-1




DR -400 kV Chhabra(end) Unit-2



DR -400 kV Chhabra(end) Unit-3




DR -400 kV Kawai(end) Unit-1



Continuous oscillation observed in the line.
Unit tripped on turbine over speed

DR -400 kV Anta (end) Bus Bar




403D_Main Kalisindh Bay


404T_Tie Kalisindh Bay

Time Synchronisation Error


15. PMU plots:



PMU plot of frequency of different station



PMU plot of frequency of different station showing oscillation at Bassi (PG)



PMU plot of phase voltages of Bassi (PG)

16. As per PMU data:

- No fault in the system
- Oscillation occurred for **2200ms** in the system

17. As per Kawai (Adani) Report:

- It was communicated from Anta end that Bus-bar protection was operated at their substation which caused isolation of 400 kV Kawai-Anta Line-1 & 2 from grid. Load through-off at Line-1 & 2 caused transfer 600MW power flow to 400 kV Adani, Kawai-Chhabra line.
- As per information received from Chhabra TPP, one of the 400kV O/G line was under shutdown at CTPP while three units were in running

condition there. Transfer of 600MW on available out going 400kV line at Chhabra caused overloading of lines. Therefore outgoing line of Chhabra tripped from remote end (May be due to over voltage) and complete black-out happened for Chhabra-Kawai complex.

- 400KV Adani, Chhabra-Kawai Line tripped from Chhabra end manually but no DT received at Kawai end.

Preliminary Report

<u>Date & Time of event:</u> -	:	02/05/2018
<u>Introduction of Event:</u> -	:	Tripping of Unit-1 & Black-out at 400kV switchyard of 2X660MW KAWAI TPP.
<u>Total Loss of Generation</u>	:	650MW
<u>Total Loss of Load:</u> -	:	625MW
<u>Weather</u>	:	42°C (Normal wind speed)
<u>Triggering Incident:-</u>		

Sr. NO.	NAME OF ELEMENT	TRIPPING DATE	TRIPPING TIME	CLOSING DATE	CLOSING TIME	INDICATION	REMARKS
1.	660MW UNIT-1	02/05/2018	14:40:46Hrs	03/05/2018	01.32 Hrs.	Over-speed & SPS - Zero Power protection operated	
2.	400kv Kawai Anta Line-1	02/05/2018	14:40:46Hrs	02/05/2018	15:02:25Hrs	Line Voltage became zero Line Under power detected	
3.	400kv Kawai Anta Line-2	02/05/2018	14:40:46Hrs	02/05/2018	15:02:25Hrs	Line Voltage became zero Line Under power detected	
4.	400kv Adani, Kawai – Chhabra Line-3	02/05/2018	14:40:46Hrs	02/05/2018	15:02:25Hrs	Line Voltage became zero Line Under power detected Zone-3 Protection Started	

18.As per Chhabra TPS Report:

S. No.	Name of Element	Tripping		Closing Date	Closing Time (in hrs)	Remarks
		Date	Time (in hrs)			
1	UNIT-1	2/5/2018	14:40	2/5/2018	20:41	Over Frequency trip
2	UNIT-2	2/5/2018	14:40	2/5/2018	21:50	Over Frequency trip
3	UNIT-3	2/5/2018	14:40	2/5/2018	23:23	Over Frequency trip
4	UNIT-4	2/5/2018	14:40	2/5/2018	-	Under annual shutdown from 11/04/2018
5	400 kV Chhabra-Kawai	2/5/2018	14:47:11 Hrs. (Manually open)	2/5/2018	18:39	
6	400 kV CTPP-Hindaun	2/5/2018	-.	2/5/2018	21:23	Under planned shutdown from 01-05-2018
7	400 kV CTPP-Bhilwara	2/5/2018	14:47:44 Hrs. (Manually open)	2/5/2018	22:54	
8	220 kV CTPP- Kawai Line	2/5/2018	14:47:40 Hrs. (Manually open)	2/5/2018	18:33	
9	220 kV CTPP-Jhalawar Line	2/5/2018	14:47:37 Hrs. (Manually open)	2/5/2018	15:33	

19. Extract of Rajasthan report:

Preliminary Report

Date & Time of event:-	:	02.05.2018 at 14.40 Hrs
Introduction of Event:-	:	Multiple trippings at 765 KV GSS at Anta
<u>Total Loss of Generation</u>	:	Nil
<u>Total Loss of Load:-</u>	:	
<u>Weather</u>	:	

Triggering Incident:-

Sl. No.	Name of Element	Tripping Date	Tripping Time	Closing Date	Closing Time	Indication	Remarks
1	400 KV Anta _ Kalasindh	02.05.2018	14.40	02.05.2018	15.26	Bus Bar Protection Main I unit	
2	400 KV Anta- Chabra Ck I	02.05.2018	14.40	02.05.2018	15.25	Bus Bar Protection Main I unit	
3	400 KV Anta – Kawai I	02.05.2018	14.40	02.05.2018	15.02	Bus Bar Protection Main I unit	
4	400 KV Anta _ Kawai II	02.05.2018	14.40	02.05.2018	15.03	Bus Bar Protection Main I unit	
5	400 KV Anta _ Kawai Spare Line	02.05.2018	14.40	02.05.2018	15.28	Bus Bar Protection Main I unit	

DETAILED ANALYSIS REPORT FOR TRIPPING AT 765 kV GSS ANTA

A. INTRODUCTION

1. Time & Date of Event: May 2, 2018 at 14:40 Hours
2. Substation affected along with voltage level: 400/765 kV GSS ANTA,
3. Brief event summary: *400 kV Tie Breakers tripped causing interruption on 400 kV Lines to KAWAI (APRL), CSCTPS & KALISINDH SCTPS*

B. ANTECEDENT CONDITION

1. Weather Information: - Hot Summer Afternoon with high Velocity Winds
2. Additional relevant Information: -

C. EVENT DATA

1. Change in Frequency:
2. Generation Loss: None
3. Single Line Diagram of affected area:

4. Name and time of the tripped elements in the time chronology: 1. 400 kV KAWAI Circuit 182, 400 kV CHHABRA Circuit # 1 & 400 kV KALI SINDH Circuit# 1

5. Location and type of fault: Tripping caused during testing of Bus Bar Protection Relay at Anta 400 kV Bus End.

6. Flag Detail, DR and EL for each affected element: *Bus Bar Protection Relay Main 1 operated.*

7. Appropriate Graphical plot.

8. Equipment Failure: -

- D. Event Description /Analysis of the event

9. Description: -

E. RESTORATION

- #### 10. Restoration Time of Tripped elements in time chronology:

ANTA-> KAWAI Circuit # 1 & 2	15:02 Hours & 15:03 Hours respectively
CHHABRA Circuit # 1	15:25 Hours
KALISINDH Circuit # 1	15:26 Hours

11. Special finding/issues identified during restoration: - NA

F. REMEDIAL ACTION

12. Remedial action taken: The Relay Programmed Logic corrected.

13. Remedial action to be taken along with the frame: Relay tested ok


- G. Lesson Learnt : More care & check Next time**

- H. Any other Information: - NA


20. SCADA Analog data and SoE:

No SCADA SoE available in NR SCADA

SLD of 765/400 kV Anta (Raj) before the incident



SLD of 765/400 kV Anta (Raj) after the incident



21. Preliminary Report, DR/EL and detailed report has been received from Rajasthan. However, remedial measures report from Rajasthan was not received before the meeting.

Rajasthan representative informed following during the meeting:

1. Alstom make P-741 bus bar protection relay implemented at 400 kV Anta (Raj). 400 kV bus bar protection tripping was also assigned to tie CB (lockout contact of tie CB was assigned from bus bar protection) of all the connected elements.
2. Two new bays for 400 kV Kota (PG) and Chhabra SCTPC ckt was introduced and testing of bus bar protection was being done in antecedent condition. Testing was done in new bay PU which is in same bay of 400 kV Anta-Kalisindh ckt-2 and tripping was kept out for tie CB.
3. During testing bus bar protection was wrongly operated and it tripped all main and tie CB of 400 kV connected elements on 400 kV Bus-2 of Anta (Raj) except 400 kV Anta-Kalisindh ckt-2.

4. 400 kV Chhabra-Bhilwara ckt tripped on PSB (power swing blocking) after 2 second of deblock time due to persistent nature of power swing in the system.
5. After tripping this configuration issue was checked in all new 400 kV station of Rajasthan and same issue was also found in Ajmer (Rajasthan) and corrected later on.
6. DR recording time was 500ms and same would be modified to 2500ms (pre fault: -500ms to post fault: +2000ms).
7. Chhabra/Kawai/Kalisindh SPS was not operated during the incident.
8. In 400 kV transmission lines of Rajasthan, all zone blocked during power swing.

POWERGRID informed that similar type of issue was also faced during multiple element tripping at Jhatikara (PG) station and same has been discussed during PSC meeting.

NRLDC representative informed that other utility shall infer the case of other utilities and correct its setting accordingly.

Representative from RRVUNL was not attended the meeting. SPS issue was yet to be discussed.

B. Multiple element tripping at 400/220kV Ajmer (Raj) at 16:55hrs of 24th May 2018 and 17:55hrs of 06th Jun 2018

Event category: GD-1

Generation loss:

Nil	(24.05.2018, As per Rajasthan Report)
Nil	(06.06.2018, As per Rajasthan Report)

Loss of load:

Nil	(24.05.2018, Rajasthan may confirm)
110MW	(06.06.2018, Rajasthan may confirm)

Energy Loss:

Nil MU	(24.05.2018, Rajasthan may confirm)
___ MU	(06.06.2018, Rajasthan may confirm)

Data Summary received/available at NRLDC:


Description	Reference	Fault Info	Remarks
Fault Clearance Time	PMU data	100ms	24.05.2018
		1000ms	06.06.2018
Phase of the fault	PMU data	Y-N fault followed by B-N fault	24.05.2018
		B-N fault	06.06.2018

Description	Utilities	Status	Remarks
Availability of Digital Data (SCADA Data)	Rajasthan	Not Available	24.05.2018
			06.06.2018
DR/ EL	Rajasthan	Received (Partial)	24.05.2018 (Not received)
			06.06.2018 (After 24hrs)
Preliminary Report	Rajasthan	Received	24.05.2018 (Within 24hrs)
			06.06.2018 (After 24hrs)
Detailed Report	Rajasthan	Not Received	24.05.2018
			06.06.2018

Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3) CEA (Technical standard for connectivity to the Grid, Amendment Regulation 2013), part-II, B2	Rajasthan	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Correct operation of Protection System 4. Delayed Clearance of fault 5. Adequately Sectionalized and graded protective relaying system

Based on above information description of the events is:

1. 400 kV Ajmer (Raj) is connected with D/C Ajmer7 (PG), Bhilwara D/C, Phagi D/C, Deedwana S/C and three 315MVA 400/220 kV ICT's. It has one and half breaker scheme.
2. 220 kV Ajmer 4 (Raj) connected with 220 kV Ajmer S/C, 220 kV Beawar, 220 kV Jethana D/C. At 220 kV side DMT (double main transfer breaker) scheme.
3. Event Description for 24th May 2018 event:
 - a. SLD of 400 kV Ajmer (Raj):



- b. Bus Bar Protection operated for 400 kV Bus-2 Ajmer (Raj).
- c. Name of the tripped element:
 - 400 kV Ajmer-Deedwana
 - 400/220 kV 315MVA ICT-1 & 3 at Ajmer (Raj)
 - 400 kV Bus Bar-2 at Ajmer (Rajasthan)
- d. As per Rajasthan report:

Preliminary Report

Date & Time of event:- : 24.05.2018 at 16.55
Introduction of Event:- : 400 KV Ajmer - Deedwana
Total Loss of Generation : Nil
Total Loss of Load:- : NA
Weather :


Triggering Incident:-

Sr. NO.	NAME OF ELEMENT	TRIPPING DATE	TRIPPING TIME	CLOSING DATE	CLOSING TIME	INDICATION	REMARKS
1	400 KV Ajmer - Deedwana	24.05.2018	16.55	24.05.2018	17.32	Bus - Bar Protection operated	
2	400 KV ICT-1at 400 KV GSS Ajmer	24.05.2018	16.55	24.05.2018	17.38		
3	400 KV ICT 3 at 400 KV GSS Ajmer	24.05.2018	16.55	24.05.2018	17.36		

e. PMU data of frequency and phase voltages:


PMU Plot of frequency at Bassi(PG)

16:55hrs/24-May-18



PMU Plot of phase voltage magnitude at Merta(Raj)

16:55hrs/24-May-18



- f. SCADA SoE data: No SoE reported
- g. As per PMU data:
 - Y-N fault followed by B-N fault observed at 16:55:38.800hrs and 16:55:39.360hrs respectively.
 - Fault clearance time in less than 100ms for both the incident
- h. As per SCADA data:
 - 400 kV Ajmer-Deedwana, 315 MVA ICT 1 & 3 tripped.
 - Bus 2 voltage was not became zero after tripping of 400 kV Bus-2

Rajasthan representative informed the following during the meeting:

- At 400 kV Ajmer (Raj) have one and half breaker scheme and have total 7 dia. Among these 7 dia, 2 dia was completed in antecedent condition and other 5 dia was not completed.
- On the day of tripping, tie CB of 400 kV Deedwana-Bhilwara dia was being charged (tie CB was already in service but R-phase CT was damaged), at the same time flashover occurred in R-phase CT and after 450ms of R-phase to earth fault Y-phase CT bursted and



it resulted into Y-phase bus fault. CT was of AREVA make. 17CT of AREVA make CT is in the process of charging.

- 400 kV Bus Bar Protection is Siemens make 7SS-522 relay. Bus Bar tripping (Main relay tripping) was looped with Master trip relay and it resulted into tripping of main and tie CB during operation of bus bar protection. Looping of Main trip and Master trip relay has been removed. Now in case of operation of bus bar protection breaker connected to that bus would only trip.
- Second CB (as dia was not completed) of 400 kV Phagi ckt-1 and 400/220 kV ICT-2 (ICT-2 was not charged) didn't trip due to wiring problem in 96 relay. 400 kV bus-1 & bus-2 was not separated and bus voltage was available at 400 kV bus-2.
- Multiple element tripping on operation of bus bar protection was due to looping (wiring) of main trip ckt with master trip ckt. This wiring issue has been attended.
- Non-tripping of tie CB on operation of 96 relay has been attended and rectified.
- Damaged CT of AREVA make yet to be replaced.
- Detailed report and DR/EL would be submitted.

Rajasthan reported fault in R-phase followed by Y-phase however in PMU details, initial fault was in Y-phase followed by B-phase.

4. Event Description for 06th Jun 2018 event:


- a. In antecedent condition, 220 kV Bus-1 of 400/220kV Ajmer (Raj) was already under outage
- b. SLD of 400/220 kV Ajmer (Raj):




h. SCADA SoE data: No SoE reported

i. AS per DR details:

DR of 220 kV Ajmer4 (end)-Ajmer line




DR of 220 kV Ajmer4 (end)-Ajmer line




Point 1. Only B-phase was under open condition (from the start of the captured DR)

Point 2. All three phase of the line tripped

DR of 220 kV Ajmer4 (end)-Ajmer line



Time synch error or check the PMU plot at 17:55 hrs



SCADA 200

File Pictures Tools Software Extra

15:40:58 07-Jun-18

Welcome SYSTEM Login Logout HELP?

Home Substation Topology Alarms Events Reports

RRVNL, AJMER

Acknowledge Alarm List

Filter: Total 30000 Unacknowledged 740

Alarm options: [X] [Y] [Z] [W] [V] [U] [T] [S] [R] [Q] [P] [O] [N] [M] [L] [K] [J] [I] [H] [G] [F] [E] [D] [C] [B] [A]

Profile: [X] [Y] [Z] [W] [V] [U] [T] [S] [R] [Q] [P] [O] [N] [M] [L] [K] [J] [I] [H] [G] [F] [E] [D] [C] [B] [A]

Output: [X] [Y] [Z] [W] [V] [U] [T] [S] [R] [Q] [P] [O] [N] [M] [L] [K] [J] [I] [H] [G] [F] [E] [D] [C] [B] [A]

Stat.	Description	Nature	Received	Acknowledged	Cleared	User - full name
●	AMER 220kV Line2 E203.7SA522 MainTBC CB B Ph Open	ALARM	>>06-Jun-18 17:56:17.832	-06-Jun-18 19:07:34	<<06-Jun-18 19:10:05.807	Administrator
●	AMER 220kV Line3 E209.7SA522 MainTBC CB R Ph Open	ALARM	>>06-Jun-18 17:56:17.833	-06-Jun-18 19:07:34	<<06-Jun-18 19:10:05.805	Administrator
●	AMER 220kV Line3 E209.7SA522 MainTBC CB B Ph Open	ALARM	>>06-Jun-18 17:56:17.833	-06-Jun-18 19:07:34	<<06-Jun-18 19:10:05.805	Administrator
●	AMER 400kV TIE 5 B417.7W6181 AR BLOCK	ALARM	>>06-Jun-18 17:56:17.833	-06-Jun-18 19:07:34	<<06-Jun-18 20:27:52.491	Administrator
●	AMER 400kV TIE 5 B417.7W6181 AR Lockout	ALARM	>>06-Jun-18 17:56:17.833	-06-Jun-18 20:30:26	<<06-Jun-18 22:27:22.274	Administrator
●	AMER 400kV TIE 5 B417.7W6181 AR Lockout	ALARM	>>06-Jun-18 17:56:17.833	-06-Jun-18 20:30:26	<<06-Jun-18 22:27:22.265	Administrator
●	AMER 400kV TIE 5 B417.7W6181 AR BLOCK	ALARM	>>06-Jun-18 17:56:17.833	-06-Jun-18 19:07:34	<<06-Jun-18 20:27:52.491	Administrator
●	AMER 400kV TIE 5 B417.7W6181 AR Lockout	ALARM	>>06-Jun-18 17:56:17.833	-06-Jun-18 19:07:34	<<06-Jun-18 20:27:52.491	Administrator
●	AMER 400kV Station Aux BCU MSB Incoming 1 ACB Position Status	CLOSE	>>06-Jun-18 18:52:22.623	-06-Jun-18 19:07:34	<<06-Jun-18 20:27:51.945	Administrator
●	AMER 400kV Station Aux BCU(RTU) 220V DCB-1A2 E/F Trip	TRIP	>>06-Jun-18 18:52:23.560	-06-Jun-18 19:07:34	<<06-Jun-18 20:27:51.945	Administrator
●	AMER 400kV TIE 3 B408.6MD63 CB S2 Position Status	OPEN	>>06-Jun-18 18:55:13.080	-06-Jun-18 19:07:34	<<06-Jun-18 19:01:21.494	Administrator
●	AMER 400kV PQCL Tie1 B423.6MD66 ISO 89TB Position Status	OPEN	>>06-Jun-18 18:55:13.080	-06-Jun-18 19:07:34	<<11-Apr-18 20:42:31.752	Administrator
●	AMER 400kV PQCL Line2 B419.6MD66 CB S2 R Ph Position Status	OPEN	>>06-Jun-18 18:55:13.080	-06-Jun-18 19:07:34	<<12-Apr-18 14:25:27.286	Administrator
●	AMER 400kV Line5 B410.6MD66 CB S2 Position Status	OPEN	>>06-Jun-18 18:55:13.112	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:50.812	Administrator
●	AMER 400kV TIE 2 B405.6MD63 ESW 89TBE Position Status	OPEN	>>06-Jun-18 18:55:13.112	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:50.812	Administrator
●	ED422R8SystemOrgG001 In2 arVal MAIN CB B PH OPEN	NORMAL	>>06-Jun-18 18:55:13.112	-06-Jun-18 19:07:34	<<12-Apr-18 17:27:20.361	Administrator
●	AMER 400kV Line2 B404.6MD66 TIE CB R PH OPEN	NORMAL	>>06-Jun-18 18:55:13.112	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:50.812	Administrator
●	AMER 400kV TIE 4 B411.6MD63 CB S2 B Ph Position Status	OPEN	>>06-Jun-18 18:55:13.112	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:21.084	Administrator
●	AMER 400kV Trfo1 B418.7B002 Relay Channel 1 Fail	HEALTHY	>>06-Jun-18 18:55:13.127	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:03.278	Administrator
●	AMER 400kV Line3 B406.6MD66 ISO 89SA Position Status	OPEN	>>06-Jun-18 18:55:13.127	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:57.629	Administrator
●	AMER 400kV BusBar BCU-1 ISO 89VTA Position Status	OPEN	>>06-Jun-18 18:55:13.127	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:15.179	Administrator
●	AMER 400kV Trfo3 B409.6MD66 ISO 89BC Position Status	OPEN	>>06-Jun-18 18:55:13.127	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:22.656	Administrator
●	AMER 400kV Trfo3 B418.6MD66 CB S2 R Ph Position Status	OPEN	>>06-Jun-18 18:55:13.127	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:40.891	Administrator
●	AMER 400kV TIE 3 B408.6MD63 LINE 2 PT SELECT	HEALTHY	>>06-Jun-18 18:55:13.127	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:34.726	Administrator
●	AMER 400kV PQCL Tie1 B423.6MD66 CB Ready	NORMAL	>>06-Jun-18 18:55:13.143	-06-Jun-18 19:07:34	<<24-May-18 17:48:08.233	Administrator
●	AMER 400kV Line3 B405.6MD66 TIE CB R PH OPEN	NORMAL	>>06-Jun-18 18:55:13.143	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:52.001	Administrator
●	AMER 400kV Trfo1 B409.6MD66 CB Ready	NOT READY	>>06-Jun-18 18:55:13.143	-06-Jun-18 19:07:34	<<06-Jun-18 18:56:15.179	Administrator

Remarks

j. As per PMU data:

- B-N fault observed at 17:56:15.360hrs & 17:56:16.880hrs
- Slight voltage dip observed in all three phase.
- Fault clearance time more than 1000ms for two incident of fault

k. As per Rajasthan details:

Sr. NO.	NAME OF ELEMENT	TRIPPING DATE	TRIPPING TIME	CLOSING DATE	CLOSING TIME	INDICATION	REMARKS
	220 kV Ajmer S/C Line	06.06.2018	17:55 Hrs	06.06.2018	19:24 Hrs	400 kV GSS Ajmer End- Main-2 Zone-1 optd, B-phase Dist. Protection 2.45kms, Main-1 Zone 1 optd, B phase DT Send, carrier send CH1 CH2. 220 kV GSS Ajmer end- 85x2, 86T, 86 AR, 86 BR, 86 CR	220 KV Bus bar operated
	400/220 kV, 315 MVA ICT-I	06.06.2018	17:55 Hrs	06.06.2018	18:56 Hrs	LBB initiation 86.1, 86.2 optd	Tripped due to 220 kV Main I Bus Bar Operated
	400/220 kV, 315 MVA ICT-III	06.06.2018	17:55 Hrs	06.06.2018	18:54 Hrs	LBB initiation 86.1, 86.2 optd	Tripped due to 220 kV Main I Bus Bar Operated
	220KV Ajmer-Jethana ckt-I	06.06.2018	17:55 Hrs	06.06.2018	19:01 Hrs	400 kV Ajmer end: LBB initiation 86.1, 86.2 optd 220 kV Jethana End: Main I, Main II Distance protection operated, Zone III, A ph. optd, 81.5 km	Tripped due to 220 kV Main I Bus Bar Operated
	220 kV Ajmer-Jethana ckt-II	06.06.2018	17:55 Hrs	06.06.2018	19:24 Hrs	400 KV Ajmer end: LBB initiation 86.1, 86.2 optd 220 kV Jethana End: Main I, Main II Distance protection operated, Zone III, A ph. optd, 81.6 km	Tripped due to 220 kV Main I Bus Bar Operated
	220 kV Beawar line	06.06.2018	17:55 Hrs	06.06.2018	19:09 Hrs	400 kV Ajmer end: LBB initiation 86.1, 86.2 optd 220 kV Beawar end: Main I: A ph. optd. Zone II Distance 77.9 km Main II: A ph. optd. Zone II Distance 78.2 km 86.A, 86.B operated	Tripped due to 220 kV Main I Bus Bar Operated

- I. Preliminary report and DR/EL (partial) has been submitted however DR/EL and detailed report is still awaited from Rajasthan

Rajasthan representative informed the following during the meeting:

- Blue phase CB of 220 kV Ajmer (400/220 kV)-Ajmer (220 kV) ckt bursted at 400/220 kV Ajmer (Raj). It resulted into bus fault for only charged 220 kV Bus-2 at 400/220 kV Ajmer (Raj)
- All the 220 kV charged elements also connected on the same bus and all the elements tripped along with 400/220 kV 315MVA ICT-1 & 3 at Ajmer (Raj).
- Initially Blue phase of the breaker opened and reclosed after 1000ms. At the time of reclosing fault again observed and it resulted into bus fault.
- Time synchronization of DR would be checked and corrected

NRLDC raised concern for three phase opening and again reclosing after 20-30ms during second incident of fault observance. When other breaker opened

than A/R lockout should come into picture. But as per DR it seems all three phase opened for 30ms and again reclosed.

NRLDC also informed about the importance of time synchronization of all the DR, as in this case also operation time of bus bar protection could not conclude due to time synch error in bus bar DR of 220 kV Ajmer (400/220kV) Bus.

NRPC also suggested all the utilities to kindly check the time synch of numerical relays periodically and to be attended in priority.

C. Multiple element tripping at Uri-II HEP at 13:55hrs of 26th May 2018

Event category: GD-1

Generation loss: 240MW (As per NHPC report)

Loss of load: Nil

Data Summary received/available at NRLDC:

Description	Reference	Fault Info	Remarks
Fault Clearance Time	PMU data	240ms	As per PMU data
Phase of the fault	PMU data	R-N fault	As per PMU data

Description	Utilities	Status	Remarks
Availability of Digital Data (SCADA Data)		Available	
DR/EL	NHPC	Received	Within 24hrs
Preliminary Report	NHPC	Received	Within 24hrs
Detailed Report	NHPC	Received	Not in proper format

Description	Clauses	Utility	Remarks
Violation of Clauses	1. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 2. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; 3. CEA Grid Standard 3.1.e 4. CEA Transmission Planning Criteria	NHPC	1. Correct operation of Protection System 2. Delayed Clearance of fault 3. Adequately Sectionalized and graded protective relaying system

2. R-N fault occurred in 400kV Uri-II-Uri-I ckt. R-phase opened at both ends.
3. At the time of auto-reclosing, R-phase CB closed from Uri-I end but failed to close from Uri-II end resulting in tripping of other two poles on pole discrepancy.
4. At the time of opening of R-phase CB from Uri-I end, 400kV Uri-II-Wagoora ckt sensed fault in Z-1 from Uri-II end resulting in tripping of R-phase.
5. Units at Uri-II tripped at the time of opening of R-phase of both lines from Uri-II.
6. At Uri-I, in 400kV Uri-II-Uri-I ckt, R-phase fault occurred again after 245ms of closing of R-phase. Thus, 3-phase trip occurred due to fault in reclaim time. However, after 100ms, Y & B phases again got closed at Uri-I.
7. Name of the tripped elements are as below:
 - Unit #2, #3, #5 & #6 at Uri-II
 - 400kV Uri-II – Uri-I
8. As per NHPC Report and DR details:


NHPC Report, Uri-II

1. Date & Time of Event:	On 26/05/2018 at 13:55 hrs.
2. Substation Name:	Uri-II पावर स्टेशन
3. Antecedent Condition:	1. Four Units were running. 2. Two Lines were in operation.
4. Change in Frequency:	N.A.
5. Generation Loss/Load Loss:	NIL
6. Name of Tripped Elements & Time of tripped Elements:	Uri-I Line at 13:55 hrs. on 26-May-2018 Unit-1 at 13:55 hrs. on 26-May-2018 Unit-2 at 13:55 hrs. on 26-May-2018 Unit-3 at 13:55 hrs. on 26-May-2018 Unit-4 at 13:55 hrs. on 26-May-2018
7. Single Line Diagram of affected Area:	NA
8. Triggering Incident:	Uri-I Line at 13:55 hrs.
9. Flag Details, DR/EL:	DR/EL already sent.
10. Event Description:	<p>1. Uri-I Lines: From the DR of the line protection relay it is evident that maximum dip in voltage and increase in current was in R-phase. Accordingly distance protection relay sensed the fault in Zone-I and tripped the faulty phase. However, the faulty phase did not reclose after 1 Sec dead time and other two phases ultimately opened on pole discrepancy, as evident from the EL. This indicates that the auto reclose relay has not operated correctly. The reason for non-operation of auto-reclose relay needs to be investigated.</p> <p>2. Wagoora Line: The distance protection relay of wagoora line initially sensed the fault in Zone-4 (reverse) as the fault was in Uri-II to Uri-I line. At the time of opening of faulty phase of Uri-II to Uri-I line, the distance protection relay of wagoora line sensed the fault in Zone-I and opened the R-phase circuit breaker which ultimately successfully auto-reclosed at 1 sec dead time. However, as the fault was on Uri-II to Uri-I line and no fault was on wagoora line, the activation of Zone-I in Wagoora line needs to be investigated. The distance protection relay of wagoora line needs to be tested for any mal-operation during current reversal as happened during the above event.</p>
	<p>3. Units: It is evident from the DR of Line and generator protection relay that all the four running units got tripped at the time of opening of R-phase breaker of both the lines. The reason for tripping of all the units has neither been recorded in DR/EL of the generator protection relay nor in the station EL. Therefore, Power Station needs to investigate the reason for tripping of units in the instant case.</p>
11. Appropriate Graphical Plot if any:	NA
12. Restoration Time:	Uri-I Line at 16:00 hrs. on 26-May-2018 Unit-1 at 15:17 hrs. on 26-May-2018 Unit-2 at 15:33 hrs. on 26-May-2018 Unit-3 at 15:27 hrs. on 26-May-2018 Unit-4 at 15:43 hrs. on 26-May-2018
13. Remedial Action Taken:	NIL
14. Remedial Action to Be Taken:	Power Station shall investigate the reason for tripping of units, in the instant case and shall take remedial action as required.


NHPC Report, Uri-I

1. Date & Time of Event:	On 26/05/2018 at 13:55 hrs.
2. Substation Name:	Uri पावर स्टेशन
3. Antecedent Condition:	1. Four Units were running. 2. All three Lines were in operation.
4. Change in Frequency:	N.A.
5. Generation Loss/Load Loss:	NIL
6. Name of Tripped Elements & Time of tripped Elements:	Uri-II Line at 13:55 hrs. on 26-May-2018
7. Single Line Diagram of affected Area:	NA
8. Triggering Incident:	Uri-II Line at 13:55 hrs.
9. Flag Details, DR/EL:	DR/EL already sent.
10. Event Description:	1. Lines: From the DR of the line protection relay it is evident that maximum dip in voltage and increase in current was in R-phase. Accordingly distance protection relay sensed the fault in Zone-I at 12.38 km and tripped the faulty phase. The faulty phase reclosed after 1 Sec dead time and after 245 ms of closing of breaker, a fault again occurred on R-phase. As the fault occurred within 500 ms window, SOTF/TOR function got activated and issued three phase trip command. Accordingly, all three phase breaker got opened but after 100 ms, Y and B-phase breaker got closed but R-phase circuit breaker was in open condition. Immediately after operation of SOTF/TOR function, closing command is being issued to the circuit breaker of healthy phases. The reason for successive closing of two pole has not been recorded in the EL of the relay. Therefore, the reason for closing of circuit breaker, in the instant case, needs to be investigated.
11. Appropriate Graphical Plot if any:	NA
12. Restoration Time:	Uri-II Line at 16:01 hrs. on 26-May-2018
13. Remedial Action Taken:	NIL
14. Remedial Action to Be Taken:	Power Station has been requested to perform the test on auto-reclose along with SOTF/TOR function to find out the source of closing command to the breaker e.g. from auto-reclose & check sync relay, any other signal from GIS controller etc to ensure complete three phase tripping (without reclosing) in case of unsuccessful single phase, single shot auto reclose.


DR: 400kV Uri-I(end)-Uri-II ckt




DR: 400kV Uri-I(end)-Uri-II ckt



DR: 400kV Uri-I-Uri-II(end) ckt




DR: 400kV Wagoora-Uri-II(end) ckt



9. PMU plots:


PMU Plot of frequency at Kishenpur(PG)

13:55hrs/26-May-18




PMU Plot of phase voltage magnitude at Kishenpur (PG)

13:55hrs/26-May-18




10. As per SCADA data:

Snapshot of Power Network before the incident



Snapshot of Power Network after the incident



11. As per PMU & SCADA data:

- R-N fault occurred at 13:55:50.080hrs and cleared in 240ms.
- R-N fault again occurred at 13:55:51.520hrs and cleared timely.
- All units at Uri-II tripped within 20ms starting at 13:55:44.320hrs.
- 400kV Uri-II-Uri-I tripped at 13:55:45.415hrs (~1100ms after units tripping) from Uri-II end.

12. Preliminary Report, DR/EL and Detailed Report received from NHPC but investigation report as mentioned in the detailed report is yet to be received.

NHPC representative informed the following during the meeting:

1. Reason for delayed fault clearance of around 250ms to be shared.

- Fault was cleared on time when it reached into Z-1. Initially distance relay sensed the fault in Z-3 and after 197ms, fault came into Z-1 and resulted into instantaneous tripping of line.
- Fault was very near to Uri-II end, 2km from Uri-II end of 400 kV Uri-II-Uri-I ckt (12km line)
- Fault was high resistive in nature, it was observed earlier particularly in this season due to walnut trees. Tree touching resulted into high resistive fault and fault came into distance Z-3 followed by Z-1.

2. No auto-reclosing in case of single L-G fault at Uri-II end to be investigated corrected and findings to be shared.

- Uri-II end of faulted line (400 kV Uri II-Uri I ckt) didn't A/R. After investigation it was suspected that manual selector switch of A/R was in off position. Position of manual selector switch is not configured in DR/EL. Position of manual selector switch would put in DR/EL during next shutdown of the line in the month of November 2018.

3. Reason for closing of Y&B phases at Uri-I without any indication to be shared.

- Reason of opening of Y&B-phase could not be ascertained. It would be discussed with OeM and reverted.

4. Reason for tripping of R-phase of Wagoora ckt at Uri-II in zone-1 to be shared.

- Alstom Make Micom distance protection of 400 kV Uri-II (end)-Wagoora ckt sensed the fault in Z-4 initially and during A/R, fault sensed in Z-1 and line tripped from Uri-II end only. Event would be replay through relay tester and would check further.
 - Time synchronization of DR would be checked and corrected
5. Reason of tripping of all running units at Uri-II HEP:
- Reason of tripping of running units of Uri-II would be checked and reported.
6. As per PMU, fault occurred at 13:55:50hrs; As per SoE, units opened at 13:55:45hrs; As per DR, fault occurred at 13:55:55hrs. It seems all three sources of information are not in time synchronization. The same needs to be checked.
- Uri-I has been time synchronized.
 - In Uri-II HEP, Alstom make GPS is not time synchronized as of now but it would be corrected in the month November-2018.
7. It seems pole discrepancy timing at Uri-II for Uri-I feeder is around 1.5sec.
- As Uri-II station have DMT (double main transfer breaker) scheme, 1.5 second is sufficient considering the 1000ms of A/R time.

POWERGRID representative informed that Alstom make Micom P-442 relay mal-operate during close in fault in the line and these relays has been replaced in POWERGRID network wherever issue arises. Setting of memory voltage also played important role in the relay operation during close in fault. NHPC may also check the setting of memory voltage.

NHPC representative informed that this tripping would again discussed with OEM and detailed report would be submitted again after discussion and further analysis.

D. Complete outage of 400kV Paricha TPS(UP) at 21:56hrs of 27th May 2018

Event category: GD-1

Generation loss: 700MW (UP may confirm)

Loss of load: Nil (UP may confirm)

Energy Loss: __ MU (UP may confirm)

Data Summary received/available at NRLDC:


Description	Reference	Fault Info	Remarks
Fault Clearance Time	PMU data	880ms	As per PMU data
Phase of the fault	PMU data	B-N fault	As per PMU data

Description	Utilities	Status	Remarks
Availability of Digital Data (SCADA Data)	Uttar Pradesh	Available (Partial)	
DR/EL	Uttar Pradesh	Not Received	
Preliminary Report	Uttar Pradesh	Received	After 24hrs
Detailed Report	Uttar Pradesh	Not Received	


Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3) CEA (Technical standard for connectivity to the Grid, Amendment Regulation 2013), part-II, B2 4. CEA Grid Standard 3.1.e 5. CEA Transmission Planning Criteria	Uttar Pradesh	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Correct operation of Protection System 4. Delayed Clearance of fault 5. Adequately Sectionalized and graded protective relaying system

Based on above information description of the events is:


1. Connectivity Diagram:



Single Line Diagram: **Paricha TPS (400kV)**



Single Line Diagram: **Paricha TPS (220kV)**



2. Paricha TPS is having following elements at 220kV: Bhartna S/C, Orai T/C, Jhansi Dorana D/C, Mahoba S/C, 220/132kV 100MVA and 160MVA ICTs, 400/220kV 315MVA ICT #1 & #2. Paricha has 2x110+2x210+2x250MW generation capacity. It has DMT (double main transfer breaker) scheme.
3. Antecedent condition:
Unit #1 at Paricha TPS under planned S/D for R&M work since 02-Jul-16
4. B-phase CT of 220kV bus-A of bus coupler get damaged.
5. This resulted in complete outage of Paricha TPS.
6. Name of the tripped elements are as below:
 - Unit #2, #3, #5 & #6
 - 220kV Paricha-Orai-1, 2&3
 - 220kV Paricha-Mahoba
 - 220kV Paricha-Jhansi Dorana D/C
 - 220kV Paricha-Bharthna
 - 220/132kV 100MVA & 160MVA ICTs
 - 400/220kV 315MVA ICT #1 & #2
7. As per UP Report:

Sub: - Report on the Incident of tripping of elements at Parichha TPS based of the information received from Parichha TPS Jhansi.

Dear Sir,

On 27.05.2018 at 21:56 hrs, all transmission lines, ICTs and Units connected with Parichha TPS tripped. Normalization time of the elements is mentioned below:-

S. No.	Name of element	Date & time of normalization		Remarks
1.	110MW Unit – II	28.05.2018	07:35	
2.	210MW Unit – III	28.05.2018	05:10	
3.	250MW Unit – V	28.05.2018	02:20	
4.	250MW Unit – VI	28.05.2018	03:21	
5.	220KV Parichha – Bharthana	27.05.2018	23:49	
6.	220KV Parichha – Orai – I	28.05.2018	02:17	
7.	220KV Parichha – Orai – II	28.05.2018	04:42	
8.	220KV Parichha – Orai – III	28.05.2018	04:42	
9.	220KV Parichha – Dunara – I	28.05.2018	00:45	
10.	220KV Parichha – Dunara – II	28.05.2018	00:45	
11.	220KV Parichha – Mahoba	28.05.2018	04:35	
12.	220KV Bus 'B'	27.05.2018	23:10	
13.	100MVA ICT	31.05.2018	21:00	
14.	160MVA ICT	27.05.2018	23:06	
15.	315MVA ICT – I	27.05.2018	23:05	
16.	315MVA ICT – II	27.05.2018	23:05	

Flags of the elements which tripped and single line diagram of the relevant portion of the grid are enclosed at annexure.

Analysis—At 21:56 hrs on 27.05.2018, B phase CT of Bus 'A' of 220KV Bus coupler damaged. Due to damaged CT all 220KV lines ICTs tripped. Due to failure of station supply unit 2, 3, 5 and 6 also got tripped on (class A and class B), HV back up earth fault, Flame failure and both ID fans trip respectively.

Remedial Measures:-


1. Testing of station protection system is required.



8. PMU plots:


PMU Plot of frequency at Kanpur(PG)

21:56hrs/27-May-18




PMU Plot of phase voltage magnitude at Kanpur(PG)

21:56hrs/27-May-18



PMU Plot of phase voltage magnitude at Kanpur(PG)

21:56hrs/27-May-18



9. Probable sequence of events:

Probable sequence of event

Based on UP SCADA SoE and PMU data

Time (in hrs)	Time Duration (in ms)	S/S Name	Voltage Level (in kV)	Element Name	Element Type	Status	Remarks
21:56:22,360	0ms	PMU data					Reference Time
21:56:22:575	215ms	ORAI1_U	220	01T1	CB	Open	Main CB of 220 kV Orai(end)-Parichha Ckt 1 opens
21:56:22:625	265ms	MHOBA_U	220	01PRINC	CB	Open	Main CB of 220 kV MAHOBA(end)- Parichha opens
21:56:23:255	895ms	BHRTN_UP	220kV	E_03(PRINC)	CB	Open	Main CB of 220 kV Bharthna(end)- Parichha opens; Fault clears

10. As per PMU & SCADA data:

- B-N fault occurred at 21:56:22.360hrs and cleared with delay of 880ms at 21:56:23.240hrs.
- A rise in 3-phase voltage also observed at 21:57:04.920hrs.
- 220kV Orai-Paricha-1 and 220kV Mahoba-Paricha ckt tripped after ~250ms of fault.
- 220kV Bharthna-Paricha tripped at the time of clearing of fault after ~900ms.

11. Preliminary Report and Detailed Report received from UP but DR/EL are still awaited from UP. Remedial measures report is also awaited from UPPTCL.

Action Points:

1. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.
2. Availability and healthiness of bus bar protection at Paricha TPS at the time of tripping to be shared.
3. Reason for delayed clearance of around a second fault to be shared.
4. In view of all tripped elements not captured in SCADA SoE data, digital SCADA data reporting from Paricha TPS to be checked, rectified and ensured in future.

No representative from UPRVUNL presented during the meeting.

NRPC raised concern about absence of concerned person from constituents specially from generation side and requested all the STU/SLDC to share the feedback with generators.

E. Multiple Element tripping at 400/132kV Anpara-ATPS and 400/220k V Opra-B TPS at 22:25hrs of 28th May 2018

Event category: GD-1

Generation loss: 850MW (As per NTPC report)

Loss of load: 250MW (As per UP report)

Energy Loss: ____ MU (UP may confirm)

Data Summary received/available at NRLDC:

Description	Reference	Fault Info	Remarks
-------------	-----------	------------	---------



Fault Clearance Time	PMU data	2minute	As per PMU data
Phase of the fault	PMU data	Y-B phase to phase to earth fault	As per PMU data



Description	Utilities	Status	Remarks
Availability of Digital Data (SCADA Data)	Uttar Pradesh	Available (Partial)	
DR/EL	Uttar Pradesh	Not Received	
Preliminary Report	Uttar Pradesh	Received	After 24hrs
Detailed Report	Uttar Pradesh	Not Received	

Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3) CEA (Technical standard for connectivity to the Grid, Amendment Regulation 2013), part-II, B2 4. CEA Grid Standard 3.1.e 5. CEA Transmission Planning Criteria	Uttar Pradesh	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Correct operation of Protection System 4. Delayed Clearance of fault 5. Adequately Sectionalized and graded protective relaying system

Based on above information description of the events is:

1. Single Line Diagram of Obra-A, B TPS and Anpara-A TPS:







2. 400 kV Obra-B TPS is connected with Anpara TPS S/C, Rewa Road S/C and Sultanpur S/C. It also has five units of 200MW and two 400/220kV 240MVA ICTs. It has DMT bus bar scheme.
3. On 28th May 2018 at 21:28hrs 400 kV Anpara-Obra line tripped on R-phase to earth fault. All three phase of the line tripped from Anpara end however Y&B-phase stucked at Obra end.
4. As informed by Anpara TPS, written instruction for opening of line side isolator and closing of earth switch was received from Obra TPS.
5. At 22:25hrs, on the instruction of Obra end, Anpara end isolator for 400kV Anpara-Obra line opened and earth switch closed manually. It resulted into Y&B-phase to earth fault and dead short ckt at Anpara TPS as Y&B-phase of the line was already stucked at Obra-B TPS.
6. It resulted into widespread fire in 400kV Bay of Anpara-Obra line at Anpara end and operation of bus bar protection for 400kV Bus-2 of Anpara-A TPS.
7. Breaker at Obra end didn't open during the incident and fault persisted in the system for more than **2minutes**.
8. Finally at Obra end also all the connected 400kV elements tripped along with running units of Obra TPS.
9. Name of the tripped elements are as below:
 - 400 kV Anpara-Obra B ckt
 - 400 kV Obra B-Sultanpur (UP)
 - 400 kV Obra B-Rewa Road (UP) ckt
 - Unit 1 & 3 of 200MW at Anpara TPS
 - Unit 9, 10 & 11 of 200MW at Obra-B TPS
 - 400 kV Bus-B of Anpara TPS.
 - 400/132 kV 100MVA ICT-2 at Anpara TPS
 - 400/220 kV 240MVA ICT-1 at Obra B TPS
 - 220/132 kV ICT-1 & 2 at Obra A TPS
 - Station Transformer-4 & 6 of Obra-A TPS
10. In antecedent condition:
 - 400/220 kV 240MVA ICT-2 of Obra-B TPS was already under outage
 - 220/132 kV 100MVA ICT-3 at Obra A TPS was already under outage

11. PMU plots:

PMU data of Anpara Bus Frequency




PMU Plot of phase voltages of Anpara



12. As per SCADA data:

UP Demand Pattern



Time (in ms)	Station Name	Voltage Level (in kV)	Element Name	Element Type	Status
22:25:27,437	ALHA1_U	400kV	14OBAB	CB (Circuit Breaker)	Open
22:25:27,532	ANPAR_UP	400kV	F_10(U03)	CB	Open
22:25:27,532	ANPAR_UP	132kV	D_14(T2)	CB	Open
22:25:27,532	ANPAR_UP	400kV	F_02(T2)	CB	Open
22:25:27,532	ANPAR_UP	400kV	23BS	CB	Open
22:25:27,532	ANPAR_UP	400kV	07MBC	CB	Open
22:25:28,090	OBRA(A)	132kV	D_07(XFMR6)	CB	Open
22:25:28,090	OBRA(A)	220kV	E_20(T2)	CB	Open
22:25:28,510	OBRA(A)	132kV	D_03(XFMR4)	CB	Open
22:25:28,510	OBRA(A)	220kV	E_21(T1)	CB	Open
22:25:28,891	OBRA(A)	132kV	D_01(RIHAN)	CB	Open
22:25:28,891	OBRA(A)	220kV	E_03(T3)	CB	Open
22:25:29,350	ANPAR_UP	132kV	D_19(RIHAN-1)	CB	Open
22:25:29,350	ANPAR_UP	132kV	D_20(RIHAN-2)	CB	Open
22:27:36,365	OBAB_UP	400kV	F_12(U09)	CB	Open
22:27:43,925	OBAB_UP	400kV	F_07(PANK1)	CB	Open
22:29:40,419	RIHAN_UP	132kV	D_20(SONE_-2)	CB	Open
22:29:44,179	RIHAN_UP	132kV	D_13(ALFAC-2)	CB	Open
22:29:46,279	RIHAN_UP	132kV	D_15(ALFAC-1)	CB	Open

13. As per PMU and SCADA data:

- Y-B LLG fault occurred at **22:25:25.360hrs** and cleared with delay of 1320ms at **22:25:26.680hrs**.
- A dip in 3-phase voltage also observed at **22:27:35.360hrs**.
- Bus Bar Protection at Anpara- A TPS operated after 2300ms of fault occurrence.
- Unit-9 of Obra B TPS tripped after 2 minutes of fault occurrence.
- 400 kV Obra B-Panki ckt also tripped after 2 minutes of fault occurrence.
- 400 kV Rewa Road-Panki ckt tripped within 2300ms of fault occurrence.
- Station transformer and 100MVA 220/132 kV ICTs tripped after 2600ms of fault occurrence.

14. As per UP Report:

Sub: - Flash Report on the Incident of Simultaneous tripping at Obra TPS and Anpara TPS.

On 28.05.18 at 22:25 Hrs. 200MW unit 9,10, and 11 and 400KV Obra – Sultanpur line and Obra – Rewa Road line at Obra TPS and 210MW unit I & III and 100MVA ICT – II tripped at Anpara TPS on Bus Bar protection. Normalization time of the elements is mentioned below:-

Sl. No.	Name of element	Date & time of Normalization		Remark
1.	200MW unit – 9 (Obra TPS)	29.05.2018	02:18	
2.	200MW unit – 10 (Obra TPS)	Shut Down		
3.	200MW unit – 11 (Obra TPS)	29.05.2018	05:28	
4.	400KV Obra – Sultanpur	29.05.2018	00:20	
5.	400KV Obra – Rewa Road	29.05.2018	01:36	
6.	210MW unit – I (Anpara TPS)	29.05.2018	00:16	
7.	210MW unit – III (Anpara TPS)	29.05.2018	00:38	
8.	100MVA T/F – II (Anpara TPS)	28.05.2018	23:05	

Generation Loss = 850 MW, (At Obra - 500MW, At Anpara - 350MW)
Load Loss = 304MW

It has been reported by site authorities that 400KV Obra – Anpara line Tripped at 21:28 hrs on distance protection. At 22:25 hrs during closing of earth switch after opening the isolators at Anpara TPS as required by maintenance people at Obra TPS heavy flash over occurred at Anpara TPS and bus bar protection operated at Anpara and Obra causing black out at Obra TPS and Bus – II at Anpara – A got isolated. B phase CT, isolator and Bus bay also got damaged at Anpara end. On inspection it was found that only one Pole of Ckt breaker at Obra end of 400KV Anpara – Obra line was open and other two poles were in closed position. 210MW unit No I & III and 100MVA ICT – II were on Bus – II at Anpara. Detailed report will be sent after receipt of data event logger and other information from Anpara TPS and Obra TPS.

15. As per Anpara A TPS Report:

Report on tripping of Units and 400 KV Lines at Anpara TPS on 28.05.2018

Status of various elements just prior to incident was as under:-

400KV BUS I of ATPS G-2, ICT-1, ICT-3, L-1 L-3

400KV BUS II of ATPS - G1, G3, ICT-2, L-2

400KV BTPS- G4, L-6, L-9

400KV BTPS- G5 L-5, L-8

BUS coupler – Both the Buses were coupled through Bus coupler at both ATPS & BTPS S/Y.

BUS SECTION- (I) Main Bus-I & II of ATPS and Main Bus-I & II of BTPS connected through Bus section.

(II) Main Bus-I & II of BTPS and Main Bus-I & II of CTPS connected through Bus section.

Description of tripping of lines with cause.

- **Anpara-Obra Line (L-2)** Tripping Time: 21:28:49Hrs.

Tripped on distance protection Zone-2 (R phase)

Fault current $I_a=8.54$ KA, Fault distance=37 KM from Anpara end.

Trip relay 86.1 & 86.2 operated, breaker of all three phase opened on protection.

- At about 22:10 Hrs MCB, OBRA TPS verbally instructed to MCB ATP, Anpara TPS for opening of line Isolator and closing of earth switch of obra line at Anpara end because of fire in Obra switchyard. MCB, Anpara TPS refused to execute any operation on verbal instruction and requested to send written message through proper code for any operation. Thereafter following message received By AE (O), MCB Anpara from MCB operation OBRA TPS at 22:12Hrs vide message code no.OB/05/4896 as detailed below:-

आप को अवगत कराना है कि 400 केवीओ ओबरा-अनपरा एल-2 लाईन का अनपरा छोर पर एल0एस0आई0 खुलवाकर एवं अर्थ ब्लेड लगा कर सूचित करें । (Copy of message register of AE Operation enclosed)

- Thereafter at about 22:25Hrs MCB operation Staff of Anpara TPS opened all the three phase line isolators of OBRA line and started to close B phase earth switch in compliance of above message at 400KV 'A' TPS, Anpara Switchyard end. Suddenly flashover occurred and fire initiated on same earth switch. Consequent upon Bus Bar protection of 400KV ATPS Bus-II operated and following elements tripped.

1. 210MW Unit-1
96 bus bar protection operated.
2. 210 MW Unit-3
96 bus bar protection operated.
3. Bus coupler ATPS Switchyard.
96 bus bar protection operated.
4. Bus Section-II
96 bus bar protection operated.
5. 400/132/33KV, 100MVA ICT-II
96 bus bar protections operated.

Following equipments found damaged after incident.

B-phase line side isolator including earth switch, 4" IPS tube approximate length 20 meters,

B-phase transfer Bus pantograph isolator including support insulator, B-phase CT & 4" IPS tube support insulator.

Normalization-

Date	Time	Description of Normalization
28.05.2018	22:58	400KV Bus-Section-II charged.
28.05.2018	23:00	400KV Bus-Coupler ATPS charged.
28.05.2018	23:02	400KV ICT-2 charged.
29.05.2018	00:16	210MW Unit# 1 charged.
29.05.2018	00:38	210MW Unit# 3 charged.

Analysis-

At 21:28:49Hrs on 28.05.2018 400KV Anpara-Obra Line (L-2) tripped on R phase zone-2 fault and breaker of all three phases opened on protection. In compliance of written message of MCB OBRA TPS received at 22:12Hrs MCB operation of Anpara TPS opened all three phases of line isolators of OBRA line at about 22:25Hrs. Whereas as per normal practice MCB, Obra TPS should not send message to open line isolators without confirmation of properly isolation of connected systems at Obra end. When B phase earth switch of OBRA line closed heavy flashover on earth switch occurred due to OBRA line was in charged condition from OBRA end, as OBRA end breaker of R & B phase reportedly was not opened. Simultaneously Bus Bar differential protection 87B of 400KV Bus-II of 'A' TPS switchyard operated and this bus was isolated after tripping of all elements (G-1, G-3, ICT-2, Bus coupler, Bus section-II).

16. Such delayed clearance of fault near generating complex may have resulted into major catastrophe in the grid and it shall be prevented for reliable and secure grid operation.
17. Preliminary Report has been received but DR/EL, detailed report and remedial measures report is still awaited from UPPTCL.

Points for Discussion:

1. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.
2. Availability and healthiness of bus bar protection at Obra-B TPS at the time of tripping to be shared.
3. Is Pole discrepancy protection operated at 400 kV Obra-B TPS of 400kV Obra B TPS-Anpara TPS ckt?
4. Reason for delayed clearance of fault to be shared.
5. Reason of delayed bus bar protection operation at Anpara A TPS? (2.3second after fault occurrence time)
6. There is a significant difference between tripping of elements at 400kV Obra B TPS and Anpara TPS. Exact sequence of event needs to be checked and reported.

7. Reason of tripping of units at Obra-B TPS? What protection operated for Obra-B TPS units?
8. Reason of station transformer and 220/132kV ICT tripping at Obra-A TPS?
9. Reason of immediate tripping of Rewa Road-Obra B TPS from Rewa Road end?
10. Reason delayed tripping of 400 kV Obra B TPS-Panki from Obra B end?
11. Such delayed clearance of fault near generating complex may have resulted into major catastrophe in the grid and it shall be prevented for reliable and secure grid operation
12. Points raised in 148th OCC Meeting:
 - a. Operational issue at Obra-B TPS. If Y&B-phase breaker stucked than that bus should vacate by opening of all the connected line from remote end.
 - b. Communication issue between Anpara-A TPS and Obra-B TPS
 - c. Operational issue as before opening of line side isolator and closing of earth switch O&M staff should check the line voltage in Y&B-phase.
 - d. Origin of fault.
 - e. Reason of fire in Obra-B TPS switchyard.
 - f. Reason of breaker stuck at Obra-B TPS and remedial measures
13. DR/EL and detailed report considering remedial measures is still awaited from UPPTCL.

NRLDC representative informed that this point was already discussed in OCC meeting but action point and remedial measures report is still awaited from UP. No representative from UPRVUNL presented during the meeting.

NRPC raised concern about absence of concerned person from constituents specially from generation side and requested all the STU/SLDC to share the feedback with generators.

NRPC would also write letter to all the heads of state generating companies for presence in the various RPC meeting.

F. Complete outage of Tehri-Koteshwar HEP complex at 19:15hrs of 29th May 2018

Event category: GD-1
 Generation loss: 600MW (As per THDC report)
 Loss of load: Nil
 Energy Unserved: Nil

Data Summary received/available at NRLDC:

Description		Fault Info	Remarks
Fault Clearance Time		100ms & 2360ms	As per PMU data
Phase of the fault		B-N fault	As per PMU data


Description	Utilities	Present Status	Remarks
Availability of Digital Data (SCADA Data)	THDC & POWERGRID	Available	
DR/ EL	THDC	Received	After 24hrs
	POWERGRID	Not Received	
Preliminary Report	THDC	Received	After 24hrs
	POWERGRID	Not Received	
Detailed Report	THDC	Not Received	
	POWERGRID	Not Received	

Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1.	THDC & POWERGRID	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Correct operation of Protection System 4. Delayed Clearance of fault 5. Adequately Sectionalized and graded protective relaying system

	(6.1, 6.2, 6.3) CEA (Technical standard for connectivity to the Grid, Amendment Regulation 2013), part-II, B2 4. CEA Grid Standard 3.1.e 5. CEA Transmission Planning Criteria	
--	--	--

Based on above information description of the events is:

1. Connectivity Diagram and SLD of 400 kV Tehri HEP:



2. 400kV Tehri HEP and Koteswar HEP are connected to 400kV Koteswar(PG) S/S through 400kV D/C lines each. 400kV Koteswar(PG) is further connected to 400kV Meerut(PG) through a 400kD/C having FSC on both circuits. Tehri and Koteswar HEP have 4x250MW and 4x100MW of generation capacity respectively.

3. Antecedent Condition:

- 400kV Koteshwar (THDC)-Koteshwar (PG)-2 and suspected to be under outage (THDC may confirm): THDC informed that this line was in service.
- Unit #1, #2 & #4 running at Tehri HEP
- Unit #1 & #3 running at Koteshwar HEP
- FSC of 400kV Koteshwar(PG)-Meerut(PG)-2 out

4. At 19:15hrs, B-N fault occurred. All elements at Koteshwar HEP tripped.

5. At 19:18hrs, B-N fault occurred. It seems fault was in 400kV Meerut-Koteshwar (PG) ckt-2 and didn't clear timely.

6. Due to this, units at Tehri tripped on 51NGT protection stage-1 & 2 after 1.2sec & 1.6sec.

7. Name of the tripped elements are as below:

- At 19:15hrs: Koteshwar HEP complete outage
 - i. 400kV Koteshwar (THDC)-Koteshwar (PG)-1 at 19:15hrs
 - ii. Unit #1 & #3 at Koteshwar HEP
- At 19:18hrs: Tehri HEP complete outage
 - i. Unit #1, #2 & #4 at Tehri HEP
 - ii. 400kV Koteshwar (PG)-Meerut (PG)-2


8. As per THDC Report:

- Tehri HEP was running with 3-Units at total station load of 399MW as per the schedule.
- At 19:15hrs, Zone-2 distance protection operated in Line-1 and subsequently A/R operated in B-phase. As per the DR, A/R operating cycle was approx. 1.1 second. Fault location recorded by protection relay was about 12.57Km from Tehri end.
- After 3 min at 19:18hrs, again disturbance in both the lines was reported and the duration was quite large resulting in tripping of bus coupler and CBs of all the generating Units of Tehri HEP on operation of 51NGT(earth fault at 400kV side) stage-1 and Stage-2 after the pre-set delay of 1.2 & 1.6 sec. respectively.
- On analyzing the fault, it indicates that fault existed at 400kV KPS-Meerut section, which was not cleared at KPS end. Hence, delay in clearing the fault reflected at Generator end causing unbalance in the system resulting in operation of 51NGT.
- DR of Main-2 relay of both the Tehri-KPS lines are attached. DR PC installed at Tehri by PGCIL is unable to download the disturbance from the Main-1 relays of both the lines as it is not communicating and the same needs to be rectified on priority.
- Further, it is pertinent to mention here that this was the 5th incident in the current month w.r.t. fault in Tehri-KPS Lines. Other incidents which

had occurred on 30.04.18, 02.05.18, 09.05.19&13.05.18 have been appraised to PGCIL vide letter no. THDCIL/Tehri/DGM(O&M)/F-88/73 dated 16.05.18(attached) for taking necessary action to avoid any unanticipated tripping of lines & units of Tehri HEP in future. The DR of all the incidents is being attached herewith for ready reference.


9. As per DR details:

DR of 400kV Tehri (**end**)-Koteshwar ckt-1 (**19:15hrs**)




- B-N fault. Z-2 from Tehri end.
- B-phase tripped within 100ms due to carrier received from remote end.
- Successful A/R.

DR of 400kV Tehri (end)-Koteshwar ckt-2 (19:15hrs)



- B-N fault. Z-2 from Tehri end.
- Z-2 start, no tripping as fault was in ckt-1 and cleared timely


DR of 400kV Tehri (end)-Koteshwar ckt-1 (19:18hrs)



- Fault was not in the line.
- Delayed clearance of fault
- Oscillation also observed in the system

It seems units tripped after 1.6sec of fault


DR of 400kV Tehri (**end**)-Koteshwar ckt-2 (**19:18hrs**)



- Fault was not in the line.
- Delayed clearance of fault
- Oscillation also observed in the system


It seems units tripped after 1.6sec of fault

DR of 400kV Tehri-Koteshwar (**end**) ckt-1 (**19:15hrs**)



- B-N fault. Z-1 from Koteshwar PG end.
- B-phase tripped within 100ms.
- Successful A/R.


M-1 DR of 400kV KoteswarPG (end)-Koteswar TH ckt-1 (19:15:32hrs)



- Tripped on DT received from remote end.

Direct Transfer Trip


M-2 DR of 400kV KoteswarPG (end)-Koteswar TH ckt-1 (19:15:32hrs)



- Tripped on DT received from remote end.


Direct Transfer Trip

DR of 400kV Meerut-KoteshwarPG (end) ckt-2 (19:18hrs)





- What protection operated at Koteshwar PG end?
- B-phase tripped after 500ms of fault occurrence and A/R after 1000ms of B-phase opening. After A/R continuous fault feeding for another 600ms and line finally tripped. But this time fault current was less because Tehri units tripped in between at 19:18:47.365hrs, only Koteshwar (THDC) generation was feeding fault

DR of 400kV Meerut (end)-Koteshwar PG ckt-2 (19:18hrs)




- Meerut end tripped after 2000ms in Z-3?

10. PMU plots:




PMU Plot of frequency at Koteswar pool(PG)

19:18hrs/29-May-18




PMU Plot of phase voltage magnitude at Koteswar pool (PG)




PMU Plot of phase voltage magnitude at Koteswar pool (PG)

19:15hrs/29-May-18




PMU Plot of phase voltage magnitude at Koteswar pool (PG)

19:18hrs/29-May-18




11. As per SCADA SLD:


SLD of 400 kV Koteswar pool (PG) before the incident




SLD of 400 kV Koteswar pool (PG) after the incident



SLD of 400 kV Koteswar pool (PG) after the incident



12. As per SCADA data plot:



13. As per SCADA SoE:

Time (hrs)	Substation	Voltage (kV)	Element	Device	Status	Remarks
19:15:29,096	KOTESHWAR	400kV	01TEHRI1	Protection Trip	App	400kV KoteshwarPG(end)- Tehri-1 A/R
19:15:29,123	KOTESHWAR	400kV	01TEHRI1	Circuit Breaker	disturbe	
19:15:29,197	KOTESHWAR	400kV	01TEHRI1	Protection Trip	Disp	
19:15:30,432	KOTESHWAR	400kV	01TEHRI1	Circuit Breaker	Close	
19:15:32,447	KOTESHWAR	400kV	07TH2	Protection Trip	App	400kV KoteshwarPG(end)- KoteshwarTH-1 tripped
19:15:32,474	KOTESHWAR	400kV	07TH2	Circuit Breaker	disturbe	
19:15:32,489	KOTESHWAR	400kV	07TH2	Circuit Breaker	Open	
19:15:32,587	KOTESHWAR	400kV	07TH2	Protection Trip	Disp	
19:18:46,456	KOTESHWAR	400kV	04MEERT2	Protection Trip	App	
19:18:46,483	KOTESHWAR	400kV	04MEERT2	Circuit Breaker	disturbe	
19:18:46,559	KOTESHWAR	400kV	04MEERT2	Protection Trip	Disp	
19:18:47,694	KOTESHWAR	400kV	04MEERT2	Circuit Breaker	Close	
19:18:48,142	KOTESHWAR	400kV	04MEERT2	Circuit Breaker	disturbe	
19:18:48,161	KOTESHWAR	400kV	04MEERT2	Circuit Breaker	Open	400kV KoteshwarPG(end)- Meerut-2 tripped
19:18:48,360	KOTESHWAR	400kV	04MEERT2	Protection Trip	App	
19:18:48,490	KOTESHWAR	400kV	04MEERT2	Protection Trip	Disp	
19:18:48,594	TEHRI	400kV	11H04	Circuit Breaker	Open	Running units at Tehri tripped
19:18:50,597	TEHRI	400kV	02H01	Circuit Breaker	Open	
19:18:50,598	TEHRI	400kV	06H02	Circuit Breaker	Open	

14. As per PMU & SCADA data:

- B-N fault occurred at 19:15:29.000hrs and cleared in ~100ms.
- After 3 min, a B-N fault again occurred at 19:18:45.720hrs and cleared with delay of 2360ms at 19:18:48.080hrs.
- 400kV Koteshwar PG(end)-KoteshwarTH-1 tripped at 19:15:32.490hrs i.e. after ~3.5sec of fault.
- 400kV Koteshwar PG(end)-Meerut-2 tripped at 19:18:48.160hrs i.e. after ~2.5sec of second fault.
- Unit #4 at Tehri tripped at 19:18:48.600hrs i.e. after ~3sec of fault whereas Unit #1 & #2 tripped after ~5sec of fault.

15. As per POWERGRID Report:

Sequence of Events:

- 400kV Koteshwar (PG)-Tehri A/R operated on B-N Fault at 19:15 Hrs on 29th May 18.
- 400kV Koteshwar (PG)-KHEP Ckt-I Tripped on Direct trip received at 19:15 Hrs on 29th May 18.
- 400kV Koteshwar (PG)-Meerut (PG) Ckt-II Tripped on Directional Earth Fault at 19:18 Hrs on 29th May 18.

Fault Analysis:

- **400kV Koteshwar (PG)-Tehri Ckt-I**
 - 400kV Koteshwar(PG)-Tehri Ckt-I successfully auto reclosed on B-N Fault at 19:15:29 Hrs
 - Fault Current – 8.84kA
 - Fault Location – 0.8KM.
- **400kV Koteshwar (PG)-KHEP Ckt-I**
 - 400kV Koteshwar(PG)-KHEP Ckt-I tripped on Direct trip received from KHEP end at 19:15:32 Hrs
- **400kV Koteshwar (PG)-Meerut (PG) Ckt-II**
 - 400kV Koteshwar (PG)-Meerut (PG) Ckt-II tripped on Directional Earth Fault at Koteshwar end and Zone-3 from Meerut end
 - Koteshwar (PG) end: Line tripped on DEF Trip
 - Meerut (PG) end: Line tripped on Zone-3 Trip.

Charging Sequence:

- 400kV Koteshwar (PG)-KHEP Ckt-I - Charged at 21:57 Hrs on 29.05.18
- 400kV Koteshwar (PG)-Meerut (PG) Ckt-II - Charged at 20:04 Hrs on 29.05.18

POWERGRID/ THDC representative informed the following during the meeting:

1. At 19:15hrs, B-N fault occurred in 400 kV Koteshwar (PG)-Tehri ckt-1, this line tripped and successfully A/R.
2. After 3.5second, 400 kV Koteshwar (PG)-Koteshwar (THDC)-1 also tripped on DT received from Koteshwar (THDC) end.
3. At 19:18hrs, fault occurred in 400 kV Meerut-Koteshwar (PG) ckt-2. Fault was highly resistive in nature and faulted phase of the line tripped from Koteshwar (PG) end in 600-700ms and again A/R from Koteshwar (PG) end.
4. Reason for tripping of 400kV Koteshwar (PG)-Koteshwar (THDC)-1 at 19:15:32.490hrs i.e. after ~3.5sec of fault to be shared.
 - At 19:15hrs B-N fault observed in 400 kV Koteshwar (PG)-Tehri ckt-1, line tripped in Z-1 and successfully A/R after 1000ms. During initial B-N fault in the line, 400 kV Koteshwar (PG)-Koteshwar (THDC) ckt-1 also tripped in Z-1 from Koteshwar (THDC) end. Line didn't A/R and finally tripped after 2.5second on Pole Discrepancy (PD). Koteshwar (THDC) end send the DT (direct trip) to remote end (Koteshwar-PG) of the line.
5. Tehri unit-2, 1 & 3 tripped at 19:18:47.345hrs, 19:18:47.352hrs and 19:18:47.365hrs respectively on back up earth fault (51NGT) protection of unit GT (generator transformer) at Tehri HEP.

6. Reason for staggered tripping of units at Tehri in ~3sec and ~5sec of fault occurrence to be looked into and shared:

- It may be due to SCADA signal of unit CB come to RLDC control room and unit CB opening time is different from protection operation time. THDC reported time is for protection operation at unit GT.

G. Multiple Element tripping at 220kV Sarna (Punjab) on 01st Jun 2018 at 15:50hrs

Event category: GD-1

Generation loss: Nil (As per Punjab Report)

Loss of load: 60MW (As per Punjab Report)

Energy Loss: ___MU (Punjab may confirm)

Data Summary received at NRLDC:

Description		Fault Info	Remarks
Fault Clearance Time		580ms	As per PMU data
Phase of the fault		Maximum dip in B-phase	As per PMU data


Description	Utilities	Present Status	Remarks
Availability of Digital Data (SCADA Data)	Punjab	Available	
DR/ EL	Punjab	Received	After PSC Agenda
	POWERGRID	Not Received	
	J&K	Not Received	
Preliminary Report	Punjab	Received	After PSC Agenda
	POWERGRID	Not Received	
	J&K	Not Received	
Detailed Report	Punjab	Received	After PSC Agenda


Description	Clauses	Utility	Remarks
-------------	---------	---------	---------

Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA grid Standard 15.3 3. CEA (Technical standards for connectivity to the Grid) Regulation, 2007-6. 4.d 4. 43.4.A of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; 5. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3)	Punjab	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Adequately Sectionalized and graded protective relaying system
	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA grid Standard 15.3	POWERGRID, J&K	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report



Based on above information description of the events is:

1. Connectivity Diagram:






2. 220 kV Sarna HEP connected with Wadala Granthian four ckt (one ckt LIL0ed at Tibber), RSD (Ranjit Sagar Dam) four ckt, Kishenpur D/C, Dasuya D/C, Sujanpur Railway D/C, Hiranagar S/C, Udhampur S/C, one ICT of 220/132kV & one ICT of 220/66kV.
3. Bus scheme is double bus single breaker scheme at 220kV Sarna stations.
4. In antecedent condition:
 - As per SCADA data, it seems 220 kV Bus-2 of Sarna (Punjab) was already under outage
 - 220 kV Sarna-Wadala granthian ckt-1 & 2, 220 kV Sarna-RSD ckt-3 & 4 was also under outage
5. CT (Current Transformer) of 220 kV Sarna (end)-Wadala granthian ckt-4 bursted and resulted into bus fault for 220 kV Sarna (Punjab).
6. Name of the tripped elements:
 - 220 kV Kishenpur-Sarna ckt-1 & 2
 - 220 kV Sarna-Wadala ckt-IV
 - 220 kV Sarna-Timber ckt
 - 220 kV Sarna-Dasuya ckt
 - 220 kV Sarna-Hiranagar (J&K) ckt
 - 220 kV Sarna-Udhampur ckt
 - 220 kV Sarna-RSD ckt-1 & 2
7. PMU plot of frequency, df/dt and phase voltages:



8. As per PMU and SCADA data:

- B-N fault observed at 15:50:14.160hrs
- Voltage dip observed in Blue phase.
- Fault clearance time 580ms.

- SCADA MW flows:



- SCADA SoE:

Time (in ms)	Reference Time	S/S Name	Voltage Level (in kV)	Element Name	Element Type	Status	Remarks
15:50:14,160	0ms						PMU data (Fault started)
15:50:14,300	140ms	SARNA	220kV	E_11(WDALA-4)	Circuit Breaker	disturbe	
15:50:14,301	140ms	SARNA	220kV	E_10(TIBBER)	Circuit Breaker	Open	
15:50:14,307	145ms	SARNA	220kV	E_3(UDHAM)	Circuit Breaker	Open	
15:50:14,310	150ms	SARNA	220kV	E_12(RSDPH-2)	Circuit Breaker	Open	
15:50:14,313	155ms	SARNA	220kV	E_13(RSDPH-1)	Circuit Breaker	Open	
15:50:14,506	345ms	SARNA	220kV	E_11(WDALA-4)	Circuit Breaker	Close	
15:50:14,511	350ms	SARNA	220kV	E_11(WDALA-4)	Circuit Breaker	disturbe	
15:50:14,637	475ms	SARNA	220kV	E_7(DASYA-2)	Circuit Breaker	disturbe	
15:50:14,645	485ms	SARNA	220kV	E_5(HRNGR)	Circuit Breaker	disturbe	
15:50:14,662	500ms	SARNA	220kV	E_8(KISHN-1)	Circuit Breaker	Open	
15:50:14,664	505ms	SARNA	220kV	E_7(DASYA-2)	Line Isolator	Open	
15:50:14,664	505ms	SARNA	220kV	E_7(DASYA-2)	BusBar Isolator 2	Open	
15:50:14,664	505ms	SARNA	220kV	E_9(KISHN-2)	Circuit Breaker	Open	
15:50:14,687	525ms	SARNA	220kV	E_7(DASYA-2)	BusBar Isolator 1	Open	
15:50:14,720	560ms						PMU data (Fault cleared)
15:50:15,293	1135ms	SARNA	220kV	E_16(T1)	Circuit Breaker	disturbe	
15:50:17,492	3330ms	SARNA	220kV	E_11(WDALA-4)	Circuit Breaker	Open	
15:50:17,645	3485ms	SARNA	220kV	E_11(WDALA-4)	Circuit Breaker	disturbe	
15:50:20,524	6365ms	SARNA	220kV	E_16(T1)	Circuit Breaker	Close	
15:50:20,587	6425ms	SARNA	220kV	E_11(WDALA-4)	Circuit Breaker	Open	
15:50:20,741	6580ms	SARNA	220kV	E_11(WDALA-4)	Circuit Breaker	disturbe	
15:58:53,805		SARNA	220kV	E_17(T2)	Circuit Breaker	Close	
15:58:53,821		SARNA	220kV	E_17(T2)	Circuit Breaker	Open	
15:58:53,823		SARNA	220kV	E_17(T2)	Circuit Breaker	disturbe	

9. Punjab report received after preparation of Agenda of the meeting. It was observed that Punjab is continuously violating the IEGC clause 5.2.r which states that *“All the Users, STU/SLDC and CTU shall send information/ data including disturbance recorder/sequential event recorder output to RLDC within 24 hours for purpose of analysis of any grid disturbance/event. No User, SLDC/STU or CTU shall block any data/information required by the RLDC and RPC for maintaining reliability and security of the grid and for analysis of an event”*

10. As per Punjab Report:

Ref : Preliminary Report No: NR_GD_GI/1267 Dated 04.June.2018

1.	Confirm the actual load loss.	60 MW
2.	Reason of bus fault.	-
3.	Action being taken to prevent such incident in future.	-
4.	Reason of delayed clearance of fault as per IEGC.	-

5	Detailed Report	
a.	Time and date of event (GPS Sync time)	01.06.18 15:50 Hrs
b.	Location.	220kV S/S Sarna (Punjab)
c.	Plant and/or Equipment directly involved.	220kV Sarna-W. Granthian Ckt-1,2,3&4. 220kV Sarna-Dasuya Ckt-1, 2 220kV Sarna-Udhampur Ckt, 220kV Sarna-Hiranagar Ckt, 220kV Sarna-RSD Ckt 1,2&3 220kV Sarna-Kishenpur ckt 1&2
d.	Single line diagram showing the connection (isolators) of various 220 KV lines, bus coupler, ICT's etc	Attached
e.	Description and cause of event.	CB Blast of 220kV Wadala Granthia – Sarna Line and it leads to Bus-Bar fault
f.	Antecedent conditions of load and generation, including frequency, voltage and the flows in the affected area.	Generation Loss- Nil Load Loss- 60 MW Frequency – 49.92 Hz Voltage – 220kV
g.	Time duration of tripping including Weather Condition prior to the event.	Weather Condition - Thunderstorm
h.	Duration of interruption and Demand and/or Generation (in MW and MWh) interrupted.	Nil
i.	All Relevant system data including copies of records of all recording instruments including Disturbance Recorder, Event Logger, DAS etc of DPR's of affected lines.	Attached
j.	Sequence of tripping with time.	#
k.	Details of Relay Flags.	
l.	Remedial measures.	--

BEFORE

Time.....15:00:00 Hrs

Sr No	T/Line or T/F Description	Load in Amp/MW	Import/Export	C.B. Position
1	Wadala Granthia ckt-1	80 Amp	Export	Closed
2	Wadala Granthia ckt-2	80 Amp	Export	Closed
3	Wadala Granthia ckt-3	80 Amp	Export	Closed
4	Wadala Granthia ckt-4	80 Amp	Export	Closed
5	Dasuya ckt-1	45 Amp	Import	Closed
6	Dasuya ckt-2	45 Amp	Import	Closed
7	Udhampur	110 Amp	Import	Closed
8	Hira Nagar	110 Amp	Export	Closed
9	Kishanpur ckt-1	160 Amp	Import	Closed
10	Kishanpur ckt-2	160 Amp	Import	Closed
11	R.S.D. ckt-1	50 Amp	Import	Closed
12	R.S.D. ckt-2	50 Amp	Import	Closed
13	R.S.D. ckt-3	50 Amp	Import	Closed
14	Transformer T-1 (220/132kV)	15 MW	Export	Closed
15	Transformer T-2 (220/66kV)	15 MW	Export	Closed
16	Transformer T-3 (220/132kV)	15 MW	Export	Closed
17	Transformer T-4 (220/66kV)	15 MW	Export	Closed

AFTER

Time.....16:00:00 Hrs

Sr No	T/Line or T/F Description	C.B. Position
1	Wadala Granthia ckt-1	Open
2	Wadala Granthia ckt-2	Open
3	Wadala Granthia ckt-3	Open
4	Wadala Granthia ckt-4	Open
5	Dasuya ckt-1	Open
6	Dasuya ckt-2	Open
7	Udhampur	Open
8	Hira Nagar	Open
9	Kishanpur ckt-1	Open
10	Kishanpur ckt-2	Open
11	R.S.D. ckt-1	Open
12	R.S.D. ckt-2	Open
13	R.S.D. ckt-3	Open
14	Transformer T-1 (220/132kV)	Open
15	Transformer T-2 (220/66kV)	Open
16	Transformer T-3 (220/132kV)	Open
17	Transformer T-4 (220/66kV)	Open

➤ Wadala Granthian Circuit 1

Sarna End

- Fault occurred in B-phase
- Circuit Breaker B-phase got damaged while operation and jumper snapped & fell on ground.
- DR not available.

Wadala End

- Distance Protection Relay sensed Zone 1 fault in B-phase and issued trip instantaneously.

➤ Wadala Granthian Circuit 2

- Distance Protection Relay at Remote End sensed 3-phase fault in Zone-2 and trip was issued.
- DR could not be traced in Distance Protection Relays at local end due to time and date mismatch as the GPS was unhealthy and got damaged recently due to lightning.
- GPS is being sent to OEM for repair.

➤ Wadala Granthian Circuit 3

- Distance Protection Relay sensed Zone 4 (Reverse Zone) fault and issued the Trip command to R,Y,B phases after 160 msec of sensing the fault.
- Zone 4 time settings were set to 160 msec since Bus-Bar Protection Scheme is not yet commissioned at the Sub-Station.
- Circuit remain charged from Remote End.

➤ Wadala Granthian Circuit 4

- Distance Protection Relay sensed Zone 4 (Reverse Zone) fault and issued the Trip command to R,Y,B phases after 160 msec of sensing the fault.
 - Zone 4 time settings were set to 160 msec since Bus-Bar Protection Scheme is not yet commissioned at the Sub-Station.
- Circuit remain charged from Remote End as CVT line voltage maintained in DR.

➤ **RSD Circuit 1**

- Distance Protection Relay sensed Zone 4 (Reverse Zone) fault and issued the Trip command to R,Y,B phases after 160 msec of sensing the fault.
- Zone 4 time settings were set to 160 msec since Bus-Bar Protection Scheme is not yet commissioned at the Sub-Station.
- Circuit remain charged from Remote End as CVT line voltage maintained in DR.

➤ **RSD Circuit 2**

- Distance Protection Relay sensed Zone 4 (Reverse Zone) fault and issued the Trip command to R,Y,B phases after 160 msec of sensing the fault.
- Zone 4 time settings were set to 160 msec since Bus-Bar Protection Scheme is not yet commissioned at the Sub-Station.
- Circuit remain charged from Remote End as CVT line voltage maintained in DR.

➤ **RSD Circuit 3**

- DR could not be traced in Distance Protection Relays at local end due to time and date mismatch as the GPS was unhealthy as reported.
- Fault was cleared from Local End as the line remain charged from the Remote End as communicated by RSD.

➤ **Dasuya Circuit 1 (PGCIL)**

- Distance Protection Relay sensed the disturbance but didn't got picked for any fault.
- The fault got cleared from Remote End.
- The circuit was later manually opened.

➤ **Dasuya Circuit 2 (PGCIL)**

Sarna End

- Distance Protection Relay sensed Zone 4 (Reverse Zone) fault and issued the Trip command to R,Y,B phases after 489 msec of sensing the fault.
- Zone 4 time settings were set to 500 msec.

Dasuya End

- Distance Protection Relay sensed Zone-2 fault in B-phase and issued the General Trip within specified time (Zone 2 time is 500 msec)

➤ **Udhampur**

- Distance Protection Relay sensed Zone 4 (Reverse Zone) fault and issued the Trip command to R,Y,B phases after 160 msec of sensing the fault.

➤ **Kishanpur Circuit 1 (PGCIL Circuit)**

- Distance Protection Relay sensed Zone 4 (Reverse Zone) fault and issued the Trip command to R,Y,B phases after 492 msec of sensing the fault.

➤ **Kishanpur Circuit 2 (PGCIL Circuit)**

- Distance Protection Relay sensed Zone 4 (Reverse Zone) fault and issued the Trip command to R,Y,B phases after 492 msec of sensing the fault.
- Zone 4 time settings were found to be 500 msec.

➤ **Hiranagar (Jammu) (PGCIL Circuit)**

- Distance Protection Relay sensed Zone 4 (Reverse Zone) fault and issued the Trip command to R,Y,B phases after 532 msec of sensing the fault.

SUMMARY

Ckt	Local		Remote End
	Zone	Time Setting	Zone
WG1	1	0 ms	1
WG2	-	-	2
WG3	4	160 ms	-
WG4	4	160 ms	-
Dasuya1	4	500 ms	2
Dasuya2	4	500 ms	2
RSD1	4	160 ms	-
RSD2	4	160 ms	-
RSD3	-	-	-
Udhampur	4	160 ms	-
Kishanpur1	4	500 ms	-
Kishanpur2	4	500 ms	-
Jammu	4	500 ms	-

#Remarks

- Zone 4 (Reverse Zone) settings for Wadala Circuits, RSD Circuit 1,2 and Udampur Circuit were found to be 160 ms. Hence, these circuits got tripped within stipulated time and cleared the fault.
- Rest of the circuits (i.e. of PGCIL), the Zone 4 time settings were found to be 500 ms. Hence delay in fault clearing time.
- In PGCIL circuits, Zone 2 settings were also found to be 500 ms (as attached with the report). Hence the fault could not be cleared from Remote End as well.
- GPS at the Sub-Station got damaged recently due to lightning, hence the time is not sync for the relays. The system is being sent to OEM for repair and would be in operation soon.

- Fault was in 220 kV Sarna-Wadala Granthian ckt-1 at Sarna end. (CB blast)
- Bus Bar Protection at 220 kV Sarna was not healthy. ABB make Centralized Bus Bar Protection was suitable for 18bays and two year back one more bay with ICT came in service at 220 kV Sarna. At that time bus bar protection was taken out of service. Work order for correcting the ABB make bus bar protection has been issued and would be corrected in another three months.
- Reverse zone setting of all the feeders changed to 160ms except POWERGRID bays at 220 kV Sarna station. Bus coupler setting was 100ms
- 220 kV Sarna-Wadala Granthian ckt-2 tripped from Wadala end in Z-2
- All other 220 kV ckt connected to Punjab is tripped from Sarna end in reverse zone after 160ms of fault occurrence.
- 220 kV elements connected to 220 kV Kishenpur (PG), Dasuya D/C and Hiranagar S/C tripped from remote end in Z-2.

Punjab/POWERGRID informed following during meeting:

1. Reason of outage of 220 kV Bus-2 at Sarna (Punjab): 220 kV Bus-2 was not under outage.
2. If 220 kV bus-2 was not under planned outage, reason of tripping of complete station to be looked into: All the feeders were coupled through both the buses through bus side isolator. Physically both the 220 kV buses were coupled through bus side isolator of both buses along with bus

coupler. Bus coupler setting was already 100ms with back up over current setting. Instruction has been issued for separating the bus side isolator and connect only one side of bus isolator

3. *Exact location of fault to be reported:* 220 kV Sarna (end)-Wadala Granthian ckt-1. Breaker limb was damaged at Sarna end.
4. *Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared:* Detailed report submitted.
5. *Reason of delayed clearance of fault:* Delayed clearance of fault was due to co-ordination issue between Punjab and POWERGRID. Z-4 setting in POWERGRID bays was coordinated with Z-2.
6. *Delayed clearance of fault in case of operation of bus bar protection at 220 kV Sarna (Punjab) needs to be looked into:* Z-4 setting of POWERGRID bays at Sarna end to be changed from 500ms to 160ms. POWERGRID would change the setting within 7days
7. *Status of bus bar protection at 220kV Sarna (during incident of 19.02.2016, it was out of service):* Bus Bar Protection at 220 kV Sarna was not healthy. ABB make Centralized Bus bar Protection was suitable for 18bays. Two year back one more bay with ICT came in service at 220 kV Sarna. At that time bus bar protection was taken out of service. Work order for correcting the ABB make bus bar protection has been issued and would be corrected in another three months

H. Complete outage of 400kV Rosa TPS(UP) at 23:58hrs of 01st June 2018

Event category: GD-1

Generation loss: 440MW (As per UP report)

Loss of load: Nil (As per UP report)

Energy Loss: ____ MU (UP may confirm)

Data Summary received/available at NRLDC:

Description	Reference	Fault Info	Remarks
Fault Clearance Time	PMU data	1760ms	As per PMU data
Phase of the fault	PMU data	Y-N fault	As per PMU data


Description	Utilities	Status	Remarks
Availability of Digital Data (SCADA Data)	Uttar Pradesh	Available (Partial)	
DR/EL	Uttar Pradesh	Not Received	

Preliminary Report	Uttar Pradesh	Received	Within 24hrs
Detailed Report	Uttar Pradesh	Not Received	


Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3) CEA (Technical standard for connectivity to the Grid, Amendment Regulation 2013), part-II, B2 4. CEA Grid Standard 3.1.e 5. CEA Transmission Planning Criteria	Uttar Pradesh	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Correct operation of Protection System 4. Delayed Clearance of fault 5. Adequately Sectionalized and graded protective relaying system

Based on above information description of the events is:

1. Connectivity Diagram:



Single Line Diagram: **Rosa TPS**



2. Rosa TPS has following elements at 220kV: Badaun D/C, Shahjahanpur(UP) D/C, Dohana S/C, Unit #1, #2; At 400kV: 400kV Shahjahanpur(PG) D/C and Unit #3, #4; Rosa TPS has 4x300MW capacity.
3. Antecedent condition and tripped elements as per UP report:

S. No.	Name of element	Date & time of normalization		Remarks
1.	300MW Unit – I	03.06.2018	17:02	Hand tripped at 23:56:18
2.	300MW Unit – II	03.06.2018	19:31	Hand tripped at 23:56:22
3.	300MW Unit – III	03.06.2018	17:17	Tripped on generator protection V/F at 23:58:04
4.	300MW Unit – IV	03.06.2018	17:53	Hand tripped at 23:02:10
5.	400KV (PG) line – I	02.06.2018	00:11	Tripped at 23:03
6.	400KV (PG) line – II	02.06.2018	05:12	Tripped at 23:03
7.	220KV Shahjahanpur – I	02.06.2018	02:18	Hand tripped at 00:05:13
8.	220KV Shahjahanpur – II	02.06.2018	01:33	Hand tripped at 00:05:45
9.	220KV Badaun – I	02.06.2018	00:43	Hand tripped at 00:04:49
10.	220KV Badaun – II	02.06.2018	02:06	Hand tripped at 00:04:29
11.	220KV Dohna	10.06.2018	18:27	Already tripped at 21:53:52 hrs

4. At 22:58hrs, 400kV Rosa-Shajahanpur-2 tripped on Z-1 from Rosa end and 400/220kV ICT-1 at Rosa tripped on differential protection.
5. At 23:01hrs, 400kV Rosa-Shajahanpur-1 also tripped on Z-1 from Rosa end.
6. Due to tripping of both 400kV Shajahanpur(PG) ckts, loading on 220kV Shajahanpur(UP) ckts increased to ~300MW each ckt. To reduce it, unit #4 hand tripped.
7. At 23:52hrs due to heavy system jerk, unit #1 excitation system came to manual mode. There were heavy disturbance in generator terminal voltage and reactive power in all three running units which came on house load due to load thrown off and OPC acted several times in all units.
8. 220kV line CBs were closed at Rosa TPS but none of them were taking load.
9. Unit #1, #2 were hand tripped whereas unit #3 tripped on generator protection at 23:58:04hrs.
10. As per UP Report:

Flash Report

No: 1663 /SE(R&A)/EE-II /Report

Dated: 02/06/2018

General Manager, NRLDC
18-A, SJSS Marg, Katwaria Sarai,
New Delhi – 110016

Sub: - Flash Report on the Incident of Simultaneous tripping at Rosa TPS Rosa Shajahanpur .

On 01.06.2018 at 23:58 hrs. 300MW Units and 220KV Ckt tripped simultaneously. Normalization time of the elements is mentioned below:-

Sl. No.	Name of element	Date & time of Normalization		Remark
1.	315MW Unit – I	-	-	
2.	315MW Unit – II	-	-	
3.	315MW Unit – III	-	-	
4.	220KV Rosa – Shajahanpur – I	02.06.2018	02:18	
5.	220KV Rosa – Shajahanpur – II	02.06.2018	01:33	
6.	220KV Rosa – Badaun – I	02.06.2018	00:43	
7.	220KV Rosa – Badaun – II	02.06.2018	02:06	
8.	220KV Rosa – Dohna	Shut down		
9.	400KV Rosa – PGCIL – I	02.06.2018	00:11	
10.	400KV Rosa – PG – II	02.06.2018	05:12	
11	300MW Unit - IV	-	-	

Generation Loss = **440MW**Load Loss = **NIL**

It has been reported by site authorities that 220KV Y phase lightning arrester damaged of 220KV Badaun – Rosa Ckt at 220KV S/S Badaun. All 220KV Ckts 300MW Unit I, II, & III simultaneously tripped 300MW Unit 4th all ready open because 400KV Rosa PGCIL – I & II tripped on line fault at 23:03hrs on 01.06.2018.

Detailed report will be sent after receipt of data event logger and other information from Rosa TPS.

No: 1971 CE(C&S)/SE(R&A)/EE-II/Report

Dated: 30/6/2018

General Manager, NRLDC
18-A, SJSS Marg, Katwaria Sarai,
New Delhi - 110016

Sub: - Report on the Incident of tripping/hand tripping of elements at Rosa TPS based on the information received from Rosa TPS.

Dear Sir,

On 01.06.2018 at 23:58 hrs, all transmission lines, Units connected with Rosa TPS tripped/ hand tripped. Normalization time of the elements is mentioned below:-

S. No.	Name of element	Date & time of normalization		Remarks
1.	300MW Unit – I	03.06.2018	17:02	Hand tripped at 23:56:18
2.	300MW Unit – II	03.06.2018	19:31	Hand tripped at 23:56:22
3.	300MW Unit – III	03.06.2018	17:17	Tripped on generator protection V/F at 23:58:04
4.	300MW Unit – IV	03.06.2018	17:53	Hand tripped at 23:02:10
5.	400KV (PG) line – I	02.06.2018	00:11	Tripped at 23:03
6.	400KV (PG) line – II	02.06.2018	05:12	Tripped at 23:03
7.	220KV Shahjahanpur – I	02.06.2018	02:18	Hand tripped at 00:05:13
8.	220KV Shahjahanpur – II	02.06.2018	01:33	Hand tripped at 00:05:45
9.	220KV Badaun – I	02.06.2018	00:43	Hand tripped at 00:04:49
10.	220KV Badaun – II	02.06.2018	02:06	Hand tripped at 00:04:29
11.	220KV Dohna	10.06.2018	18:27	Already tripped at 21:53:52 hrs

Analysis report of the elements which tripped/hand tripped and single line diagram of the relevant portion of the grid are enclosed at annexure.

Analysis- At 22:58:17 hrs on 01.06.2018, 400/220KV ICT – I (200MVA) tripped due to differential protection, 400KV (PG) – II tripped at 22:58:17 hrs on Zone – I protection and 400KV (PG) – I also tripped at 23:01:25 hrs on Zone – I protection. Due to tripping of 400KV lines loading on 220KV Shahjahanpur – I and – II lines raised to more than 300MW on each line. To reduce overloading of these lines unit – 4 was hand tripped.

At 23:52:46 hrs due to heavy system jerk, unit – I excitation system came in manual mode. There was heavy disturbance in generator terminal voltage and reactive power in all three running units. All three running generators 1, 2, 3 at Rosa came house load due to load throw off and OPG acted several times in all units. 220KV lines breaker were closed at Rosa TPS but none of them were taking load units – I, II were hand tripped and unit – III tripped on generator protection at 23:58:04 hrs.

Due to above incidence complete black out occurred at Rosa TPS.

INCIDENCE #1

Pre conditions:

On 01.06.2018, just before the incidence, at 22:45 hrs, all units were on partial load (back down by LDC) with unit load as Unit #1 (169 MW), Unit #2 (166 MW), Unit #3 (168 MW) and Unit #4 (166 MW).

Line loading at 22:45 hrs was as per following:

- 220 KV Rosa SPN #1: 124 MW
- 220 KV Rosa SPN #2: 123 MW
- 220 KV Rosa Dohna: Line in tripped condition. Line tripped on Z2 protection on 21:53:52 hrs
- 220 KV Rosa Badaun #1: -7.8 MW
- 220 KV Rosa Badaun #2: -8.1 MW
- ICT #1 HV: -36 MW (power flow from 400 KV to 220 KV system)
- ICT #2 HV: -36 MW (power flow from 400 KV to 220 KV system)
- 400 KV PG line #1: 189 MW
- 400 KV PG line #2: 193 MW

So as per above readings, in 220 KV system; power was flowing through SPN line #1 & #2 only.

Sequence of events during incidence #1:

- ICT #1 tripped at 22:58:17 hrs on 01st Jun'18 on differential protection and consequently ICT #2 HV loading increased to -69 MW.
- 400 KV PG line #2 tripped at 22:58:17 hrs on 01st Jun'18 on Z1 protection and PG line 1 loading increased to 377 MW.
- 400 KV PG line #1 also tripped after few minutes at 23:01:25 hrs on Z1 distance protection.

So there was no power evacuation from 400 KV side. Badaun line #1 & #2 were also not taking load. SPN line #1 & #2 were only source of power evacuation at Rosa station. SPN line #1 & #2 load increased above 300 MW plus each.

Unit #4 was hand tripped at 23:02:10 hrs on 01st Jun'18 to avoid further SPN line overloading and to avoid subsequent line tripping. After U#4 hand tripped, SPN line load normalized to 180 MW each.

- Unit #3 load reduced to 155 MW.
- ICT #1 was charged at 23:27:26 hrs and ICT #1 & #2 loading was 58 MW each. ?

Pre conditions:

Just after the survival from above incidence #1 (by hand tripping U#4) at 23:45 hrs (01.06.2018), Unit #1, Unit #2 and Unit #3 load before station blackout was 151 MW, 158 MW & 138 MW respectively. Unit #4 was already in trip condition (hand tripped during incidence #1).

Line loading at 23:45 hrs was as per following:

- 220 KV Rosa SPN #1: 180 MW
- 220 KV Rosa SPN #2: 181 MW
- 220 KV Rosa Dohna: Line in tripped condition.
- 220 KV Rosa Badaun #1: 17 MW
- 220 KV Rosa Badaun #2: 17 MW
- ICT #1 HV: Charged with normal loading 58 MW
- ICT #2 HV: Charged with normal loading 58 MW
- 400 KV PG line #1: Line in trip condition
- 400 KV PG line #2: Line in trip condition

Sequence of events during incidence #2:

Unit #1, Unit #2 and Unit #3 load before tripping was 151MW, 158 MW & 138 MW respectively.

At 23:52:48 hrs due to heavy system jerk, Unit #1 excitation system came in manual mode. There was heavy disturbance in generator terminal voltage and reactive power in all three running units.

All the three running generators #1, #2 & #3 at Rosa came on house load (10 MW) due to load throw off and OPC acted several times in all units. Stage #1 220 KV lines breaker were closed at Rosa end but none of them were taking load.


- Unit #1 was hand tripped at 23:56:18 hrs.
- Unit #2 was hand tripped at 23:56:22 hrs and
- Unit 3 tripped on generator protection v/f at 23:58:04 hrs.

So there was complete black out at Rosa station.

After station black out following 220 KV line breakers were manually opened from Rosa end.


- SPN 1: 00:05:13 hrs
- SPN 2: 00:05:45 hrs
- BDN 1: 00:04:49 hrs
- BDN 2: 00:04:29 hrs

11. PMU plots:




PMU Plot of phase voltage magnitude at Bareilly

22:58hrs/01-June-18




PMU Plot of phase voltage magnitude at Lucknow(PG)

23:56hrs/01-June-18




12. As per SCADA data:

400kV connected elements MW flow: Rosa TPS



220kV connected elements MW flow: Rosa TPS



Uttar Pradesh/**PG** SoE

Time (in hrs)	Station	Voltage	Element	Device	Status	Remarks
21:53:52,467	ROSA_UP	220kV	E_04(DOHNA)	CB	Open	220kV Rosa-Dohna ckt tripped
22:04:02,170	DOHNA_UP	220kV	E_02(CBGA2)	CB	Open	
22:34:18,920	ROSA_UP	400kV	F_03(T1)	CB	Close	
22:34:39,882	ROSA_UP	220kV	E_13(T1)	CB	Close	
22:58:16,661	SJNPR_PG	400kV	16ROS2	CB	disturbe	400kV Shajahanpur-Rosa-2 tripped in Z-1
22:58:16,662	SJNPR_PG	400kV	17TIE	CB	disturbe	
22:58:16,685	ROSA_UP	400kV	F_07(BRELY-1)	CB	Open	
22:58:16,721	ROSA_UP	400kV	F_03(T1)	CB	Open	400/220kV ICT-1 at Rosa tripped on differential protection
22:58:16,722	ROSA_UP	220kV	E_13(T1)	CB	Open	
22:58:18,753	SJNPR_PG	400kV	17TIE	CB	Close	
22:58:19,283	SJNPR_PG	400kV	16ROS2	CB	Open	
23:01:23,793	SJNPR_PG	400kV	17TIE	CB	disturbe	400kV Shajahanpur-Rosa-2 tripped in Z-1
23:01:23,804	ROSA_UP	400kV	F_06(LKNOW-1)	CB	disturbe	
23:01:24,807	ROSA_UP	400kV	F_06(LKNOW-1)	CB	Open	
23:01:24,876	SJNPR_PG	400kV	17TIE	CB	Close	
23:01:53,853	SJNPR_PG	400kV	17TIE	CB	disturbe	
23:01:54,915	SJNPR_PG	400kV	17TIE	CB	Close	
23:02:08,688	SJNPR_PG	400kV	17TIE	CB	Open	

Uttar Pradesh/**PG** SoE

Time (in hrs)	Station	Voltage	Element	Device	Status	Remarks
23:02:10,055	ROSA_UP	400kV	F_02(G4)	CB	Open	Unit #4 at Rosa hand tripped
23:07:14,934	DOHNA_UP	220kV	E_02(CBGA2)	CB	Close	
23:27:26,245	ROSA_UP	400kV	F_03(T1)	CB	Close	
23:27:37,733	ROSA_UP	220kV	E_13(T1)	CB	Close	
23:55:55,308	SHJHA_UP	220kV	E_01(SITPR)	CB	Open	
23:55:56,237	SHJHA_UP	220kV	E_06(CBGA1-1)	CB	Open	
23:56:25,097	ROSA_UP	220kV	E_11(G2)	CB	Open	Unit #2 at Rosa hand tripped
23:56:38,732	SHJHA_UP	220kV	E_02(T1)	CB	Open	
23:56:51,367	ROSA_UP	220kV	E_10(G1)	CB	Open	Unit #1 at Rosa hand tripped
23:57:57,212	ROSA_UP	400kV	F_01(G3)	CB	Open	Unit #1 at Rosa tripped on generator protection V/f
23:58:03,807	BADUN_UP	220kV	E_03(T1)	CB	disturbe	

13. As per PMU & SCADA data:

- B-N fault occurred at 22:58:16.560hrs and cleared timely.
- Two successive Y-N faults occurred at 23:55:54.880hrs and 23:55:56.240hrs with delayed clearance of fault.
- Tripping / Manual opening of multiple elements captured in SCADA SoE.

14. Preliminary Report, Detailed Report is received from UP. DR/EL along with remedial measures report is still awaited from UP.

Action Points:

1. At 22:58hrs, 400kV Rosa-Shajahanpur-2 tripped on Z-1, fault cleared timely as seen from PMU. However, 400/220kV ICT-1 also tripped on differential protection. Reason for tripping of ICT, setting of differential protection, coordination between ICT protection and line protection to be looked into and shared.
2. Reason for tripping of Unit #3 at Rosa on V/f protection, setting of V/f protection to be looked into and shared.
3. Reason for fluctuation in V, Q of three running units, relevant plots showing such variation to be looked into and shared.
4. At 23:55hrs, reason for delayed clearance of fault to be looked into and shared.
5. At 23:55hrs, sequence of event of tripping of elements around Rosa area to be ascertained and shared.
6. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.

No representative from UPRVUNL presented during the meeting.

NRPC raised concern about absence of concerned person from constituents specially from generation side and requested all the STU/SLDC to share the feedback with generators.

I. Multiple Element tripping at 400kV Singrauli (NTPC) & Anpara (UP) Station at 15:24hrs of 02nd Jun 2018

Event category: GD-1

Generation loss: 1100MW

Loss of load: Nil (UP may confirm)

Energy Loss: ____MU (UP may confirm)

Data Summary received/available at NRLDC:



Description		Fault Info	Remarks
Fault Clearance Time		100ms	As per PMU data
Phase of the fault		Multiple fault	As per PMU data


Description	Utilities	Present Status	Remarks
Availability of Digital Data (SCADA Data)	NR and UP	Available	
DR/ EL	NTPC	Not Received	
	UP	Not Received	
	POWERGRID	Received (Partial)	After 24hrs
Preliminary Report	NTPC	Not Received	
	UP	Not Received	
	POWERGRID	Received (Partial)	After 24hrs
Detailed Report	NTPC	Not Received	
	UP	Not Received	

Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA grid Standard 15.3 3. CEA (Technical standards for connectivity to the Grid) Regulation, 2007-6. 4.d 4. 43.4.A of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; 5. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3)	NTPC & Uttar Pradesh	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Adequately Sectionalized and graded protective relaying system
	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA grid Standard 15.3	POWERGRID	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report

Based on above information description of the events is:

1. Connectivity Diagram & SLD of Singrauli and Anpara TPS:






2. In antecedent condition, weather was stormy.
3. Name of the tripped element:
 - 400 kV Singrauli NTPC-Anpara (UP) ckt
 - 400 kV Singrauli NTPC-Allahabad (PG) ckt-1 & 2
 - HVDC Vindhyachal BtB block-1
 - 200MW Unit-2 & 4 of 400 kV Singrauli NTPC
 - 400 kV Anpara-C to Anpara-D ckt
 - 765/400 kV 1000MVA ICT-II of Anpara TPS
 - Unit-2 (210MW) & 4 (500MW) of 400 kV Anpara (UP) TPS
4. 400 kV Singrauli TPS is connected with Allahabad (PG) D/C, Rihand D/C, Vindhyachal D/C, Fatehpur (PG) S/C, Anpara S/C, Lucknow S/C. It also have 5 units of 200MW and two units of 500MW, two 100MVA 400/132kV ICT. 400/132kV Singrauli station have DMT (double main transfer breaker) scheme, both 400 kV buses have with sectionaliser.
5. Weather was stormy on 02nd June 2018.
6. On 02nd June 2018, at 15:18 hrs 400 kV Singrauli-Anpara & 400 kV Singrauli-Allahabad ckt-II tripped. Due to breaking of R-Phase CT jumper of 400 kV Anpara-Singrauli ckt led to Bus bar protection operation of 400

kV BUS-I at Singrauli TPS. At the same time 200MW unit#2 & unit#4 at 400 kV Singrauli TPS also tripped.


7. At 15:22 hrs, 765 kV Anpara D-Anpara C tripped. After this at 15:24 hrs 400 kV Singrauli-Allahabad ckt-I & HVDC Vindhyachal pole-I tripped.
8. At 15:26 hrs , 765/400 kV 1000MVA ICT- II at Anpara C tripped due to differential protection operation due to breakage of its Clamp on R and Y Phases & at the same time Unit 2 (210MW) & 4 (500MW) tripped at Anpara TPS.
9. PMU plots:

PMU Plot of phase voltage magnitude at Kanpur (PG)


15:17hrs/02-June-18



15:17hrs/02-June-18




15:21hrs/02-June-18



PMU Plot of phase current magnitude at Kanpur (PG)

15:21hrs/02-June-18




PMU Plot of frequency at Singrauli (NTPC)

15:24hrs/02-June-18




PMU Plot of phase voltage magnitude at Singrauli (NTPC)

15:24hrs/02-June-18




PMU Plot of phase current magnitude at Rihand (NTPC)

15:24hrs/02-June-18




PMU Plot of phase voltage magnitude at Rihand

15:26hrs/02-June-18







PMU Plot of phase current magnitude at Rihand

15:26hrs/02-June-18



10. SCADA Analog data and SoE:





Time (in ms)	S/S Name	Voltage (in kV)	Element Name	Element Type	Status	Remarks
15:17:41,415	SINGRAULI	400kV	08G02	Circuit Breaker	Open	400 kV Singrauli unit-2 tripped
15:17:41,416	SINGRAULI	400kV	07ANPAR1	Circuit Breaker	Open	400 kV Singrauli-Anpara ckt tripped from Singrauli end
15:17:41,420	SINGRAULI	400kV	24BS	Circuit Breaker	Open	400 kV Bus Sectionaliser between 400 kV Bus-2A & 2B
15:24:24,319	SINGRAULI	400kV	09ALBAD1	Circuit Breaker	Open	400 kV Singrauli-Allahabad (PG) ckt-1 tripped from Singrauli end
15:25:58,069	ANPAR_UP	400kV	F_16(VRNSI-1)	Circuit Breaker	Open	400 kV Anpara-Sarnath (PG) ckt-1 tripped from Anpara end
15:25:58,090	ANPAR_UP	400kV	F_12(U04)	Circuit Breaker	Open	400 kV Anpara unit-4 tripped
15:25:59,192	ANPAR_UP	400kV	F_16(VRNSI-1)	Circuit Breaker	Close	400 kV Anpara-Sarnath (PG) ckt-1 closed from Anpara end
15:26:22,164	ANPAC_UP	400kV	F_21(T2)	Circuit Breaker	Open	765/400 kV ICT-2 tripped at Anpara(UP) end (400kV end)
15:26:22,169	ANPAC_UP	765kV	G_13(T2)	Circuit Breaker	Open	765/400 kV ICT-2 tripped at Anpara(UP) end (765kV end)
15:26:22,187	ANPAR_UP	400kV	F_08(U02)	Circuit Breaker	Open	400 kV Anpara unit-2 tripped

11. As per PMU data and SCADA data:

- At 15:18hrs, there is only 0.5 kV dip in all phases of Kanpur PMU. (Rihand PMU was not available). It seems there was no bus fault. Bus bar protection mal-operated.
- At 15:22hrs, 765 kV Anpara D-Anpara C tripped. Observation on Kanpur PMU, there is 11 kV dip in Y-phase & fault clearing time is less than 100ms.
- At 15:24hrs, 400 kV Singrauli-Allahabad ckt-I & HVDC Vindhyachal pole-I tripped. Observation based on Singrauli and Rihand PMU, maximum dip in R-phase & fault clearing time is less than 100ms.
- At 15:26hrs, 765/400 kV 1000MVA ICT- II at Anpara C tripped due to differential protection operation due to breakage of its Clamp on R and Y Phases. At the same time, Unit 2 (210 MW) & 4 (500 MW) tripped at Anpara tripped. Observation based on Rihand PMU, there is 6kV dip in Y-phase & fault clearing time is less than 100ms. The oscillations were also observed at the time event

12. As per POWERGRID details:

[illegible]

- Line tripped from Allahabad (PG) end on Z-2+Carrier from remote end
- Line auto reclosed after 1000ms
- Why all three phase main CB opened at Allahabad (PG) end in antecedent condition.


The screenshot shows the 'Line Data' window with the following data series:

Line	RMS	IntPeak	Phase
LINE_A_IL1	1546.875	2582.695	159.402°
LINE_A_IL2	889.316	-1245.842	328.180°
LINE_A_IL3	267.836	-414.590	216.691°
LINE_A_ILN	1292.767	-1830.025	178.353°
LINE_UL1	229606.461	-325234.305	239.921°
LINE_UL2	242913.483	338029.786	132.984°
LINE_UL3	209652.951	302108.063	1.321°
LINE_UN	73292.646	-101164.939	192.813°

The circular diagram on the right shows the phase relationships between the lines, with angles ranging from 0 to 360 degrees. The bottom section shows a list of events (TRIP, START, etc.) with their corresponding time and phase values.

- Line tripped from Allahabad end on Z-2+Carrier from remote end
- Three phase tripping due to fault in reclaim time of 25second from initial fault occurrence.
- Why all three phase main CB opened at Allahabad (PG) end in antecedent condition.

DR of 400 kV Allahabad (end)-Singrauli ckt-2



- Line tripped from Allahabad end on DT (direct trip) received from remote end

13. Details received from NTPC after PSC Agenda preparation:

As per NTPC report

400kV SSTPS SWITCHYARD LINE TRIPPING REPORT- Allahabad Line-I	SSTPS SWITCHYARD DISTURBANCE/LINE TRIPPING REPORT – Allahabad Line #2
<p>1) DATE AND TIME OF OCCURRENCE: 02.06.2018 , 15:24:20.583 hrs</p> <p>2) BRIEF DESCRIPTION OF OCCURRENCE ALONG WITH FLAG DETAILS: On 02.06.2018 , 400 KV Allahabad line-I was tripped with following relay operation: <u>AT SSTPS END:</u></p> <p><u>Relay:</u> Distance protection relays Main-I and Main-II operated, Three phase trip operated. Relays of 'A, B and C' phase operated, Auto reclose initiated, A/R Lock out operated.]</p> <p><u>AT ALLAHABAD END:</u> Not available</p> <p>3) ANALYSIS: On viewing the D/R, event logger and relay details at SSTPS, it is concluded that a line to ground fault occurred on 'A' phase of the line in zone-1 causing tripping of 'A' phase pole of breaker and closing again on auto-reclose at 15:24:21.618. At 15:24:24.319, all the three poles tripped as the fault again re-appeared within reclaim time resulting in auto reclose lockout and three phase tripping of line. Later line was charged successfully at 16:25:14.616hrs.</p> <p>4) PROBABLE REASON OF TRIPPING: Phase to ground fault</p> <p>5) LINE OUTAGE PERIOD: 61 minutes(approx.)</p> <p>REMEDIAL MEASURE (IF ANY): Nil</p> <p>MICOM FAULT RECORD:-</p> <p>Started ph – A-N Trip ph – A,B,C Trip zone – Z1 Location : 5.477% IA= 12.76 kA , IB =955.4 A , IC =428 A VAN =93.14 kV , VBN= 224.8kV , VCN=221.9 kV Fault Resistance = 276.2 mili Ohms</p>	<p>1) DATE AND TIME OF OCCURRENCE: 02.06.2018 , 15:17:41.443 hrs</p> <p>2) BRIEF DESCRIPTION OF OCCURRENCE ALONG WITH FLAG DETAILS: On 02.06.2018 ,Allahabad-2 line tripped with following relay operation: <u>AT SSTPS END:</u> Bus bar protection relay of 400 kV Allahabad#2 line bay 396 operated.</p> <p>3) ANALYSIS: On viewing the relay details and site at SSTPS switchyard, it is concluded that R phase CT clamp for jumper connection of Anpara line broke due to heavy storm and crossed the CT and further came in contact with the IPS thereby bypassing the CT. This has resulted in the operation of bus bar protection supervision relays(95 A and 95 CH along with 95AX and 95 CHX) resulting in Bus bar protection of bus#1 main zone and check zone relays resulting in the tripping of the line along with other 400 kV bays in Bus#1 . Later line was charged successfully at 16:33:15.050 hrs from Singrauli end.</p> <p>4) LINE OUTAGE PERIOD: Approximately 76 minutes</p> <p>5) PROBABLE REASON OF TRIPPING: Bus bar protection operated.</p> <p>6) REMEDIAL MEASURE (IF ANY): nil</p> <p>*Note: Bus bar supervision relays got operated due to bypassing of 'R' phase CT of Anpara line which resulted in break of current contribution to bus bar protection while actual current continued to flow in the main circuit of 'R' phase of Anpara line due to Jumper coming in contact with the other side of CT.</p>

NTPC Singrauli Plant SoE

Date: 2018-06-02									
No.	Status	Time	Point	Event					
1	Alarm	15:17:29:425	276	400KV B/B PROT ZONE-C CT BUS WIRE FLT	32	Alarm	15:24:20:556	205	ALLAHABAD LINE-1 MAIN-2 PROT MICOM P442 R-N OPTD
2	Alarm	15:17:29:425	272	400KV B/B PROT ZONE-A CT BUS WIRE FLT	33	Alarm	15:24:20:583	25	ALLAHABAD LINE-1 BKR 952 R-PH OPENED
3	Normal	15:17:29:666	272	400KV B/B PROT ZONE-A CT BUS WIRE HEALTHY	34	Normal	15:24:20:605	205	ALLAHABAD LINE-1 MAIN-2 PROT MICOM P442 R-N NORMAL
4	Alarm	15:17:41:406	277	400KV B/B PROT CHK ZONE CT BUS WIRE FLT	35	Normal	15:24:20:606	197	ALLAHABAD LINE-1 MAIN-1 PROT MICOM P442 R-N NORMAL
5	Alarm	15:17:41:416	288	400KV B/B PROT T/R 896 OPTD	36	Normal	15:24:21:618	25	ALLAHABAD LINE-1 BKR 952 R-PH CLOSED
6	Alarm	15:17:41:428	301	BUS SECTION-1 BKR 1352A R-PH OPENED	37	Alarm	15:24:24:293	197	ALLAHABAD LINE-1 MAIN-1 PROT MICOM P442 R-N OPTD
7	Alarm	15:17:41:432	134	ALLAHABAD LINE-2 A/R LOCKOUT	38	Alarm	15:24:24:293	205	ALLAHABAD LINE-1 MAIN-2 PROT MICOM P442 R-N OPTD
8	Alarm	15:17:41:439	303	BUS SECTION-1 BKR 1352A B-PH OPENED	39	Alarm	15:24:24:310	229	ALLAHABAD LINE-1 A/R LOCKOUT
9	Alarm	15:17:41:440	302	BUS SECTION-1 BKR 1352A Y-PH OPENED	40	Alarm	15:24:24:319	25	ALLAHABAD LINE-1 BKR 952 R-PH OPENED
10	Alarm	15:17:41:443	8	ALLAHABAD LINE-2 BKR 352 Y-PH OPENED	41	Alarm	15:24:24:342	27	ALLAHABAD LINE-1 BKR 952 B-PH OPENED
11	Alarm	15:17:41:444	34	ICT-1 BKR 1252 R-PH OPENED	42	Normal	15:24:24:343	205	ALLAHABAD LINE-1 MAIN-2 PROT MICOM P442 R-N NORMAL
12	Alarm	15:17:41:444	7	ALLAHABAD LINE-2 BKR 352 R-PH OPENED	43	Alarm	15:24:24:343	26	ALLAHABAD LINE-1 BKR 952 Y-PH OPENED
13	Alarm	15:17:41:445	36	ICT-1 BKR 1252 B-PH OPENED	44	Normal	15:24:24:343	197	ALLAHABAD LINE-1 MAIN-1 PROT MICOM P442 R-N NORMAL
14	Alarm	15:17:41:445	9	ALLAHABAD LINE-2 BKR 352 B-PH OPENED	45	Normal	15:51:40:797	288	400KV B/B PROT T/R 896 RESET
15	Alarm	15:17:41:445	13	BUS COUPLER-1 BKR 552 R-PH OPENED	46		16:00:00:000		DATE & TIME
16	Alarm	15:17:41:445	23	GEN-2 BKR 852 Y-PH OPENED	47	Normal	16:00:07:257	229	ALLAHABAD LINE-1 A/R NORMAL
17	Alarm	15:17:41:445	35	ICT-1 BKR 1252 Y-PH OPENED	48	Normal	16:02:55:483	15	BUS COUPLER-1 BKR 552 B-PH CLOSED
18	Alarm	15:17:41:446	20	ANPARA LINE BKR 752 Y-PH OPENED	49	Normal	16:02:55:487	13	BUS COUPLER-1 BKR 552 R-PH CLOSED
19	Alarm	15:17:41:446	15	BUS COUPLER-1 BKR 552 B-PH OPENED	50	Normal	16:02:55:493	14	BUS COUPLER-1 BKR 552 Y-PH CLOSED
20	Alarm	15:17:41:446	14	BUS COUPLER-1 BKR 552 Y-PH OPENED	51	Normal	16:07:22:685	35	ICT-1 BKR 1252 Y-PH CLOSED
21	Alarm	15:17:41:447	24	GEN-2 BKR 852 B-PH OPENED	52	Normal	16:07:22:692	36	ICT-1 BKR 1252 B-PH CLOSED
22	Alarm	15:17:41:448	19	ANPARA LINE BKR 752 R-PH OPENED	53	Normal	16:07:25:675	34	ICT-1 BKR 1252 R-PH CLOSED
23	Alarm	15:17:41:448	21	ANPARA LINE BK	54	Alarm	16:07:25:686	34	ICT-1 BKR 1252 R-PH OPENED
24	Alarm	15:17:41:449	22	GEN-2 BKR 852 R-PH OPENED	55	Normal	16:07:26:793	34	ICT-1 BKR 1252 R-PH CLOSED
25	Alarm	15:17:41:515	10	GEN-4 BKR 452 R-PH OPENED	56	Alarm	16:07:26:804	34	ICT-1 BKR 1252 R-PH OPENED
26	Alarm	15:17:41:517	12	GEN-4 BKR 452 B-PH OPENED	57	Normal	16:07:40:696	34	ICT-1 BKR 1252 R-PH CLOSED
27	Alarm	15:17:41:518	11	GEN-4 BKR 452 Y-PH OPENED	58	Alarm	16:07:40:707	34	ICT-1 BKR 1252 R-PH OPENED
28	Normal	15:17:41:711	277	400KV B/B PROT CHK ZONE CT BUS WIRE HEALTHY	59	Normal	16:07:53:633	34	ICT-1 BKR 1252 R-PH CLOSED
29	Alarm	15:17:41:825	332	BUS SECTION-1 BKR 1352A T/C-2 FLT	60	Alarm	16:07:53:644	34	ICT-1 BKR 1252 R-PH OPENED
30	Alarm	15:17:41:864	331	BUS SECTION-1 BKR 1352A T/C-1 FLT	61	Normal	16:07:53:956	34	ICT-1 BKR 1252 R-PH CLOSED
31	Alarm	15:24:20:554	197	ALLAHABAD LINE-1 MAIN-1 PROT MICOM P442 R-N	62	Alarm	16:07:53:967	34	ICT-1 BKR 1252 R-PH OPENED
					63	Normal	16:07:54:188	34	ICT-1 BKR 1252 R-PH CLOSED
					64	Alarm	16:07:54:200	34	ICT-1 BKR 1252 R-PH OPENED
					65	Normal	16:07:54:274	34	ICT-1 BKR 1252 R-PH CLOSED
					66	Alarm	16:07:54:285	34	ICT-1 BKR 1252 R-PH OPENED
					67	Normal	16:07:59:611	34	ICT-1 BKR 1252 R-PH CLOSED
					68	Alarm	16:07:59:633	34	ICT-1 BKR 1252 R-PH OPENED
					69	Normal	16:08:00:184	34	ICT-1 BKR 1252 R-PH CLOSED
					70	Alarm	16:08:00:195	34	ICT-1 BKR 1252 R-PH OPENED
					71	Normal	16:10:01:754	34	ICT-1 BKR 1252 R-PH CLOSED
					72	Alarm	16:10:01:778	34	ICT-1 BKR 1252 R-PH OPENED
					73	Normal	16:10:01:897	34	ICT-1 BKR 1252 R-PH CLOSED

NTPC Singrauli Plant SoE

74	Alarm	16:10:02:467	34	ICT-1 BKR 1252 R-PH OPENED					
75	Normal	16:10:02:479	34	ICT-1 BKR 1252 R-PH CLOSED					
76	Alarm	16:10:02:507	34	ICT-1 BKR 1252 R-PH OPENED					
77	Normal	16:10:02:518	34	ICT-1 BKR 1252 R-PH CLOSED					
78	Alarm	16:10:02:547	34	ICT-1 BKR 1252 R-PH OPENED					
79	Normal	16:10:02:705	34	ICT-1 BKR 1252 R-PH CLOSED					
80	Alarm	16:10:02:753	34	ICT-1 BKR 1252 R-PH OPENED					
81	Normal	16:10:02:819	34	ICT-1 BKR 1252 R-PH CLOSED					
82	Alarm	16:10:03:191	34	ICT-1 BKR 1252 R-PH OPENED					
83	Normal	16:10:03:646	34	ICT-1 BKR 1252 R-PH CLOSED					
84	Alarm	16:10:03:663	34	ICT-1 BKR 1252 R-PH OPENED					
85	Normal	16:10:03:674	34	ICT-1 BKR 1252 R-PH CLOSED					
86	Alarm	16:10:03:706	34	ICT-1 BKR 1252 R-PH OPENED					
87	Normal	16:10:03:742	34	ICT-1 BKR 1252 R-PH CLOSED					
88	Alarm	16:10:03:983	34	ICT-1 BKR 1252 R-PH OPENED	123	Normal	16:33:15:049	8	ALLAHABAD LINE-2 BKR 352 Y-PH CLOSED
89	Normal	16:10:04:004	34	ICT-1 BKR 1252 R-PH CLOSED	124	Normal	16:33:15:050	9	ALLAHABAD LINE-2 BKR 352 B-PH CLOSED
90	Alarm	16:10:04:016	34	ICT-1 BKR 1252 R-PH OPENED	125	Alarm	16:34:00:058	8	ALLAHABAD LINE-2 BKR 352 Y-PH OPENED
91	Normal	16:10:04:031	34	ICT-1 BKR 1252 R-PH CLOSED	126	Alarm	16:34:00:060	7	ALLAHABAD LINE-2 BKR 352 R-PH OPENED
92	Alarm	16:10:04:053	34	ICT-1 BKR 1252 R-PH OPENED	127	Alarm	16:34:00:067	9	ALLAHABAD LINE-2 BKR 352 B-PH OPENED
93	Normal	16:10:04:583	34	ICT-1 BKR 1252 R-PH CLOSED	128	Normal	16:37:14:455	7	ALLAHABAD LINE-2 BKR 352 R-PH CLOSED
94	Alarm	16:10:04:632	34	ICT-1 BKR 1252 R-PH OPENED	129	Normal	16:37:14:455	8	ALLAHABAD LINE-2 BKR 352 Y-PH CLOSED
95	Normal	16:10:04:934	34	ICT-1 BKR 1252 R-PH CLOSED	130	Normal	16:37:14:456	9	ALLAHABAD LINE-2 BKR 352 B-PH CLOSED
96	Alarm	16:10:05:185	34	ICT-1 BKR 1252 R-PH OPENED	131	Alarm	16:42:26:194	334	BUS SECTION-1 BKR 1352A CB OPERATION LOCKOUT
97	Normal	16:10:05:316	34	ICT-1 BKR 1252 R-PH CLOSED	132	Normal	16:42:26:222	334	BUS SECTION-1 BKR 1352A CB OPERATION NORMAL
98	Alarm	16:10:05:330	34	ICT-1 BKR 1252 R-PH OPENED	133	Normal	16:42:26:250	331	BUS SECTION-1 BKR 1352A T/C-1 HEALTHY
99	Normal	16:10:05:391	34	ICT-1 BKR 1252 R-PH CLOSED	134	Alarm	16:42:27:087	334	BUS SECTION-1 BKR 1352A CB OPERATION LOCKOUT
100	Alarm	16:10:05:405	34	ICT-1 BKR 1252 R-PH OPENED	135	Normal	16:42:27:110	334	BUS SECTION-1 BKR 1352A CB OPERATION NORMAL
101	Normal	16:10:05:417	34	ICT-1 BKR 1252 R-PH CLOSED	136	Normal	16:42:46:391	332	BUS SECTION-1 BKR 1352A T/C-2 HEALTHY
102	Alarm	16:10:05:483	34	ICT-1 BKR 1252 R-PH OPENED	137	Normal	16:44:10:019	276	400KV B/B PROT ZONE-C CT BUS WIRE HEALTHY
103	Normal	16:10:05:506	34	ICT-1 BKR 1252 R-PH CLOSED	138		17:00:00:000		DATE & TIME
104	Alarm	16:10:05:769	34	ICT-1 BKR 1252 R-PH OPENED	139	Alarm	17:27:57:365	331	BUS SECTION-1 BKR 1352A T/C-1 FLT
105	Normal	16:10:06:796	34	ICT-1 BKR 1252 R-PH CLOSED	140	Alarm	17:28:02:514	332	BUS SECTION-1 BKR 1352A T/C-2 FLT
106	Alarm	16:10:06:807	34	ICT-1 BKR 1252 R-PH OPENED					
107	Normal	16:10:08:323	34	ICT-1 BKR 1252 R-PH CLOSED					
108	Alarm	16:10:08:338	34	ICT-1 BKR 1252 R-PH OPENED					
109	Normal	16:10:08:365	34	ICT-1 BKR 1252 R-PH CLOSED					
110	Alarm	16:10:08:442	34	ICT-1 BKR 1252 R-PH OPENED					
111	Normal	16:10:08:465	34	ICT-1 BKR 1252 R-PH CLOSED					
112	Alarm	16:10:08:482	34	ICT-1 BKR 1252 R-PH OPENED					
113	Normal	16:10:08:496	34	ICT-1 BKR 1252 R-PH CLOSED					
114	Alarm	16:10:09:762	34	ICT-1 BKR 1252 R-PH OPENED					
115	Normal	16:10:09:787	34	ICT-1 BKR 1252 R-PH CLOSED					
116	Alarm	16:10:09:809	34	ICT-1 BKR 1252 R-PH OPENED					
117	Normal	16:10:09:820	34	ICT-1 BKR 1252 R-PH CLOSED					
118	Normal	16:20:02:087	134	ALLAHABAD LINE-2 A/R NORMAL					
119	Normal	16:25:14:615	27	ALLAHABAD LINE-1 BKR 952 B-PH CLOSED					
120	Normal	16:25:14:616	25	ALLAHABAD LINE-1 BKR 952 R-PH CLOSED					
121	Normal	16:25:14:616	26	ALLAHABAD LINE-1 BKR 952 Y-PH CLOSED					
122	Normal	16:33:15:046	7	ALLAHABAD LINE-2 BKR 352 R-PH CLOSED					

- At 15:17:41hrs, 400 kV Bus Bar Protection operated for Singrauli Bus-1 due to CT Jumper breaking and touching with CT dome results in bypassing of Current from CT. Connected feeders from Bus-1 tripped. Feeders are Anpara Line, Allahabad #2 line, 200MW U#2, 200MW U#4, ICT#1, Bus coupler-1 and Bus Section-1.
- On viewing the relay details and site at SSTPS switchyard, it is concluded that R phase CT clamp for jumper connection of Anpara line broke due to heavy storm and crossed the CT and further came in contact with the IPS thereby bypassing the CT. This has resulted in the operation of bus bar protection supervision relays(95 A and 95 CH along with 95AX and 95 CHX) resulting in Bus bar protection of bus#1 main zone and check zone relays resulting in the tripping of the line along with other 400 kV bays in Bus#1.
- At 15:24:20hrs, 400 kV Singrauli-Allahabad Line # 1 tripped single pole for R phase to Neutral Fault. After auto reclosing, fault reappeared at 15:24:24 (in breaker reclaim time of 25second) and all 3 pole of the line tripped. There is no any relation of Bus Bar protection tripping with this line.
- Physical Inspection carried out of 400kV Bus-1 and after confirming initiation from Anpara Feeder, system normalized:
 - 16:02 Bus Coupler-1 closed and Charged 400kV Singrauli Bus-1.
 - 16:07 ICT#1 Charged
 - 16:25 Allahabad Line-1 Charged
 - 16:38 Allahabad Line-2 Charged
 - 18:23 BusSection-1 Charged
 - 20:16 U#2 Synchronised
 - 20:23 U#4 Synchronised.
- Remedial Measures suggested in NTPC report:
 - It was concluded that due to hanging type wave trap just above CT, Stress occurred due to sway of wave trap during heavy wind. This resulted in Bus Fault. This problem referred to NTPC CC Engg and suggested to shift wave trap at suitable location (near CVT). Also suggestion given for base mounted Wave trap.

NTPC/POWERGRID/UPPTCL representative informed during the meeting:

1. *Bus configuration in antecedent condition at 400 kV Singrauli and Anpara TPS needs to be looked into:* NTPC and UPPTCL would separately check and inform.

2. *Reason of multiple element tripping at 400/132kV Singrauli TPS:* NTPC representative informed that Bus Bar protection operated at 400 kV Singrauli TPS due to CT bypassing for one of the line CT. POWERGRID representative informed that differential pickup setting of bus bar differential protection should be less than minimum fault current and above than full load current of maximum loaded line from the station. NRPC suggested NTPC to review the bus bar differential setting, CT supervision relay and its setting etc for healthy bus bar protection at 400 kV Singrauli TPS
3. *Reason of tripping of unit-2 & 4 at Singrauli TPS still awaited:* These units are connected on 400 kV Bus-1 of Singrauli TPS. After operation of bus bar protection, all the elements connected to that bus would trip.
4. *As per SCADA SoE, reason of opening of bus sectionaliser of Bus-2A and Bus-2B needs to be looked into (as bus bar operation at 400 kV Bus-1 operated):* NTPC representative informed that this point would be checked and revert back.
5. *At 15:17hrs during operation of bus bar protection at 400 kV Singrauli TPS, exact location of fault to be reported:* No fault in the system, line CT of 400 kV Singrauli (end)-Anpara ckt bypassed due to opening of jumper from wave trap and touched to the dome
6. *Reason of multiple element tripping at 400kV Anpara TPS:* No representative from UPRVUNL was presented in the meeting.
7. *Reason of tripping of unit-2 & 4 at Anpara TPS still awaited:* No representative from UPRVUNL was presented in the meeting.
8. *Protection co-ordination of unit protection with line distance protection needs to be looked into at 400 Singrauli and Anpara TPS:* Singrauli unit tripped due to bus bar protection operation, reason of tripping of Anpara TPS is still awaited.
9. *At 15:26 hrs, from SOE it can be gathered that 400 kV Anpara-Sarnath ckt-1 successfully reclosed from Anpara end after 1000ms. Details needs to be looked into:*
10. *Tripping of Vindhyachal BtB during fault in AC system needs to be looked into:* Sensitive setting of HVDC over current protection resulted into tripping of HVDC Vindhyachal BtB during fault in the HVAC line.
11. *Why all three phase main CB opened at Allahabad (PG) end of 400 kV Allahabad-Singrauli ckt-1 in antecedent condition:* POWERGRID would check and revert back. It may be the signal mapping issue or outage of main bay.
12. *Detailed report and supporting DR/EL needs to be submitted by NTPC and UPPTCL:* Details received from NTPC but still awaited from UPPTCL.

13. 400 kV Bus Bar Protection mal operation at 400kV Singrauli station needs to be checked and corrected: NTPC would check the further details on the basis of input received in the meeting and revert back.

Discussion could not concluded due to lack of information and NRPC requested all the utilities for timely submission of details during the meeting. This point would again discussed in next PSC meeting.

J. Multiple Element tripping at 400kV Singrauli (NTPC) Station at 15:05hrs of 10nd Jun 2018

Event category: GD-1

Generation loss: 1100MW (As per NTPC report)

Loss of load: Nil

Energy Loss: ____MU

Data Summary received/available at NRLDC:

Description		Fault Info	Remarks
Fault Clearance Time		100ms	As per PMU data
Phase of the fault		Y-N fault	As per PMU data


Description	Utilities	Present Status	Remarks
Availability of Digital Data (SCADA Data)	NTPC	Available (Partial)	
DR/ EL	NTPC	Received	After PSC Agenda
	UP	Not Received	
Preliminary Report	NTPC	Not Received	
	UP	Received	After PSC Agenda
Detailed Report	NTPC	Not Received	
	UP	Not Received	


Description	Clauses	Utility	Remarks
-------------	---------	---------	---------

<p>Violation of Clauses</p>	<ol style="list-style-type: none"> 1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA grid Standard 15.3 3. CEA (Technical standards for connectivity to the Grid) Regulation, 2007-6. 4. 43.4.A of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; 5. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3) 	<p>NTPC & Uttar Pradesh</p>	<ol style="list-style-type: none"> 1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Adequately Sectionalized and graded protective relaying system
------------------------------------	---	--	--

Based on above information description of the events is:

1. Connectivity Diagram & SLD of Singrauli TPS:





2. In antecedent condition, weather was stormy.
3. Name of the tripped element:
 - 400 kV Singrauli-Anpara ckt
 - 200MW Unit-1 of 400 kV Singrauli TPS
 - 500MW Unit-6 of 400 kV Singrauli TPS
 - 500MW Unit-7 of 400 kV Singrauli TPS
4. 400 kV Singrauli TPS is connected with Allahabad (PG) D/C, Rihand D/C, Vindhyaachal D/C, Fatehpur (PG) S/C, Anpara S/C, Lucknow S/C. It also have 5 units of 200MW and two units of 500MW, two 100MVA 400/132kV ICT. 400/132kV Singrauli station have DMT (double main transfer breaker) scheme, both 400 kV buses have with sectionaliser.
5. At 15:05hrs, 400 kV Singrauli-Anpara ckt tripped. 400 kV unit-1, 6 & 7 also tripped.
6. PMU plots:


PMU Plot of frequency at Singrauli(NTPC)

15:05hrs/10-June-18




PMU Plot of phase voltage magnitude at Singrauli (NTPC)

15:05hrs/10-June-18



7. SCADA Analog data and SoE:



Time	S/S Name	Voltage Level (in kV)	Element Name	Element Type	Status
15:05:23,937	SINGRAULI	400kV	07ANPAR1	Circuit Breaker	Close

Unit tripping details not captured in SCADA SoE

8. As per PMU data and SCADA data:

- Y-N fault observed at 15:05:22.880hrs
- Voltage dip observed in Yellow phase.
- Fault clearance time 100ms
- Unit tripping details not captured in SCADA SoE.

9. NTPC submitted the details after PSC agenda, As per NTPC report:

- Weather condition: Heavy wind and Rainy

- On 10/06/2018 at 14:44 Hrs 400kV Allahabad Line # 2 Tripped for R phase fault at location 51.09% from Singrauli. Fault current in relay for R phase was 18.46kA and voltage was 18.75kV. during this incidence heavy rain was there.
- Further at 14:58 Hrs, 132kV Bus -1 tripped on Bus Bar protection for B phase to ground fault. Connected feeder to 132 kV bus -1 tripped. Feeders are ICT#2, Station Transformer # 1 & 3, CW Transformer # 2 & 4, Colony Transformer # 2, Renusagar (Pipari) Line, Bus coupler and Solar Line (Vector Surge Protection).
- This resulted in Loss of Cooling Water SWGR supply (CW System) resulted in tripping of 500MW U#7 (at 14:59 Hrs), 500MW U#6 (At 15:02 Hrs) and 200MW U#1 (at 15:08 Hrs).
- At 15:05 Hrs 400kV Anpara Line tripped on Y phase fault and auto reclose was unsuccessful. Fault current recorded in relay for Y phase is 19 kA and 30kV. Fault Location was 2.338kM from Singrauli in forward direction. This Line tripping was not related with 132kV Bus Bar Protection Tripping. After Physical inspection of Bus and confirming bus healthiness normalization started
- Normalization time:
 - 400 kV Side of ICT # 2 Charged.
 - 16:23 132 kV Side of ICT # 2 Charged (132kV Bus-1 Charged)
 - 16:29 Station Transformer # 3 charged
 - 16:31 Station Transformer # 1 charged
 - 16:51 CW Transformer # 2 Charged
 - 16:53 CW Transformer # 4 Charged
 - 17:02 132kV Bus coupler Synchronised
 - 17:00 Allahabad Line-2 Synchronised
 - 18:44 Anpara Line Synchronised
 - 22:08 200MW U#1 Synchronised
 - 11/06/18 02:00 500 MW U#7 Synchronised
 - 11/06/18 03:51 500MW U#6 Synchronised
- Remedial Measures: In 132kV Bus-1 some metal wire found in below B phase bus in melted condition. Hence for 132kV/ 400 kV SWYD Bay and near area picking up of metal wire to be carried on daily basis.

NTPC Singrauli Plant SoE

Date		2018-06-10			
No.	Status	Time	Point	Event	
1		01:00:00:000		DATE & TIME	
2		02:00:00:000		DATE & TIME	
3		03:00:00:000		DATE & TIME	
4		04:00:00:000		DATE & TIME	
5		05:00:00:000		DATE & TIME	
6		06:00:00:000		DATE & TIME	
7		07:00:00:000		DATE & TIME	
8		08:00:00:000		DATE & TIME	
9		09:00:00:000		DATE & TIME	
10		10:00:00:000		DATE & TIME	
11		11:00:00:000		DATE & TIME	
12		12:00:00:000		DATE & TIME	
13		13:00:00:000		DATE & TIME	
14		14:00:00:000		DATE & TIME	
15	Alarm	14:43:33.984	95	ALLAHABAD LINE-2 MAIN-1 PROT REL 670 R-N OPTD	
16	Alarm	14:43:34.011	7	ALLAHABAD LINE-2 BKR 352 R-PH OPENED	
17	Alarm	14:43:34.023	103	ALLAHABAD LINE-2 MAIN-2 PROT MICOM P442 R-N OPTD	
18	Normal	14:43:34.045	103	ALLAHABAD LINE-2 MAIN-2 PROT MICOM P442 R-N NORMAL	
19	Normal	14:43:34.149	95	ALLAHABAD LINE-2 MAIN-1 PROT REL 670 R-N RESET	
20	Alarm	14:43:34.961	133	ALLAHABAD LINE-2 A/R OPERATED	
21	Normal	14:43:35.037	7	ALLAHABAD LINE-2 BKR 352 R-PH CLOSED	
22	Normal	14:43:35.074	133	ALLAHABAD LINE-2 A/R RESET	
23	Alarm	14:43:46.256	133	ALLAHABAD LINE-2 A/R OPERATED	
24	Normal	14:43:46.368	133	ALLAHABAD LINE-2 A/R RESET	
25	Alarm	14:43:57.718	133	ALLAHABAD LINE-2 A/R OPERATED	
26	Normal	14:43:57.831	133	ALLAHABAD LINE-2 A/R RESET	
27	Alarm	14:44:09.017	133	ALLAHABAD LINE-2 A/R OPERATED	
28	Normal	14:44:09.127	133	ALLAHABAD LINE-2 A/R RESET	
29	Alarm	14:44:14.706	95	ALLAHABAD LINE-2 MAIN-1 PROT REL 670 R-N OPTD	
30	Alarm	14:44:14.725	134	ALLAHABAD LINE-2 A/R LOCKOUT	
31	Alarm	14:44:14.733	7	ALLAHABAD LINE-2 BKR 352 R-PH OPENED	
32	Alarm	14:44:14.739	103	ALLAHABAD LINE-2 MAIN-2 PROT MICOM P442 R-N OPTD	
33	Alarm	14:44:14.756	9	ALLAHABAD LINE-2 BKR 352 B-PH OPENED	
34	Alarm	14:44:14.757	8	ALLAHABAD LINE-2 BKR 352 Y-PH OPENED	
35	Normal	14:44:14.760	103	ALLAHABAD LINE-2 MAIN-2 PROT MICOM P442 R-N NORMAL	
36	Normal	14:44:14.872	95	ALLAHABAD LINE-2 MAIN-1 PROT REL 670 R-N RESET	
37	Alarm	14:58:57.956	358	ICT-2 GROUP-1 PROT TRIP RELAY OPTD	
38	Alarm	14:58:57.956	359	ICT-2 GROUP-2 PROT TRIP RELAY OPTD	
39	Alarm	14:58:57.982	308	ICT-2 400 KV BKR 1452 Y-PH OPENED	
40	Alarm	14:58:57.984	309	ICT-2 400 KV BKR 1452 B-PH OPENED	
41	Alarm	14:58:57.987	307	ICT-2 400 KV BKR 1452 R-PH OPENED	
42	Alarm	14:59:45.924	329	GEN-7 BKR 2152 Y-PH OPENED	
43	Alarm	14:59:45.926	328	GEN-7 BKR 2152 R-PH OPENED	
44	Alarm	14:59:45.927	330	GEN-7 BKR 2152 B-PH OPENED	
45		15:00:00:000		DATE & TIME	
46	Alarm	15:02:56.582	322	GEN-6 BKR 1952 R-PH OPENED	
47	Alarm	15:02:56.582	323	GEN-6 BKR 1952 Y-PH OPENED	
48	Alarm	15:02:56.582	324	GEN-6 BKR 1952 B-PH OPENED	
49	Alarm	15:05:22.974	160	ANPARA LINE MAIN-1 PROT MICOM P442 Y-N OPTD	
50	Alarm	15:05:22.974	170	ANPARA LINE MAIN-2 PROT MICOM P442 Y-N OPTD	
51	Alarm	15:05:23.001	20	ANPARA LINE BKR 752 Y-PH OPENED	
52	Normal	15:05:23.020	170	ANPARA LINE MAIN-2 PROT MICOM P442 Y-N RESET	
53	Normal	15:05:23.021	160	ANPARA LINE MAIN-1 PROT MICOM P442 Y-N NORMAL	
54	Normal	15:05:23.966	20	ANPARA LINE BKR 752 Y-PH CLOSED	
55	Alarm	15:08:10.202	28	GEN-1 BKR 1052 R-PH OPENED	
56	Alarm	15:08:10.203	30	GEN-1 BKR 1052 B-PH OPENED	
57	Alarm	15:08:10.206	29	GEN-1 BKR 1052 Y-PH OPENED	
58	Alarm	15:08:10.331	232	GEN-1 BKR 1052 T/C-1 FLTY	
59	Alarm	15:08:10.331	233	GEN-1 BKR 1052 T/C-2 FLTY	
60	Normal	15:08:10.362	233	GEN-1 BKR 1052 T/C-2 HEALTHY	
61	Normal	15:08:10.363	232	GEN-1 BKR 1052 T/C-1 HEALTHY	
62		16:00:00:000		DATE & TIME	
63	Normal	16:11:15.639	359	ICT-2 GROUP-2 PROT TRIP RELAY RESET	
64	Normal	16:11:19.031	358	ICT-2 GROUP-1 PROT TRIP RELAY RESET	
65	Normal	16:19:43.837	307	ICT-2 400 KV BKR 1452 R-PH CLOSED	
66	Normal	16:19:43.839	309	ICT-2 400 KV BKR 1452 B-PH CLOSED	
67	Normal	16:19:43.840	308	ICT-2 400 KV BKR 1452 Y-PH CLOSED	
68	Normal	16:55:40.152	134	ALLAHABAD LINE-2 A/R NORMAL	
69		17:00:00:000		DATE & TIME	
70	Normal	17:00:58.247	7	ALLAHABAD LINE-2 BKR 352 R-PH CLOSED	
71	Normal	17:00:58.247	8	ALLAHABAD LINE-2 BKR 352 Y-PH CLOSED	
72	Normal	17:00:58.248	9	ALLAHABAD LINE-2 BKR 352 B-PH CLOSED	
73		18:00:00:000		DATE & TIME	
74		19:00:00:000		DATE & TIME	
75	Alarm	19:12:21.743	276	400KV B/B PROT ZONE-C CT BUS WIRE FLTY	
76	Normal	19:12:21.815	276	400KV B/B PROT ZONE-C CT BUS WIRE HEALTHY	
77		20:00:00:000		DATE & TIME	
78		21:00:00:000		DATE & TIME	
79		22:00:00:000		DATE & TIME	
80	Normal	22:08:50.311	28	GEN-1 BKR 1052 R-PH CLOSED	
81	Normal	22:08:50.313	29	GEN-1 BKR 1052 Y-PH CLOSED	
82	Normal	22:08:50.314	30	GEN-1 BKR 1052 B-PH CLOSED	
83		23:00:00:000		DATE & TIME	

Points for Discussion:

1. Reason of multiple element tripping at 400/132kV Singrauli TPS.
2. Exact location of fault to be reported.
3. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.
4. Three phase tripping of 400 kV Anpara (end)-Singrauli ckt during single phase to earth fault (R-N fault) in the line needs to be looked into. (As per DR details Singrauli end A/R successfully)
5. Reason of different time of tripping of units at 400/132 kV Singrauli TPS.
6. Detailed report and supporting DR/EL needs to be submitted.
7. Unit tripping not captured in SCADA SoE. Availability of digital data needs to be looked into

NTPC representative informed following during the meeting:

1. Units tripping was due to fault at 132 kV bus of 400/132kV Singrauli TPS and subsequent tripping of cooling water auxiliary supply failure.

2. Automatic changeover of stage-2 units (unit-6 & 7) were also not occurred and it resulted into unit outage.
3. Automatic changeover facility is not available in stage-I auxiliary supply of 400/132 kV Singrauli TPS. Unit-1 of 400/132 kV Singrauli TPS was tripped due to auxiliary supply failure after 132 kV bus fault.
4. Line fault in 400 kV Singrauli-Anpara ckt is altogether different fault from 132 kV bus fault at Singrauli TPS. It have not any relation with unit tripping at Singrauli TPS.
5. As per DR details of Singrauli end, B-N fault occurred in 400 kV Singrauli-Anpara ckt. Line successfully A/R from Singrauli end but Anpara end didn't A/R on transient fault.
6. *Reason of multiple element tripping at 400/132kV Singrauli TPS:* Fault was at 132 kV bus-1 at Singrauli TPS and it resulted into auxiliary supply failure. It resulted into multiple unit tripping. Unit-6 & 7 tripped due to failure of automatic changeover of auxiliary supply of unit-6 & 7.
7. *Exact location of fault to be reported:* Fault was at 132 kV bus-1 at Singrauli TPS
8. *Three phase tripping of 400 kV Anpara (end)-Singrauli ckt during single phase to earth fault (R-N fault) in the line needs to be looked into. (As per DR details Singrauli end A/R successfully):* Anpara end details to be confirmed by UPPTCL.
9. *Unit tripping not captured in SCADA SoE. Availability of digital data needs to be looked into:* Separately take up with SCADA team.

NRLDC representative informed that unit-1 tripped after some time and unit- 6 & 7 tripped immediately during fault at 132 kV bus of Singrauli TPS. It needs to be relooked. Reason of the same needs to be updated.

Exact reason of tripping and sequence of unit tripping at Singrauli TPS needs to be informed in further detailed report to be submitted by NTPC.

K. Complete outage of 400kV Merta(RRVPNL) at 16:22hrs of 19th June 2018

Event category: GD-1

Generation loss: Nil (Rajasthan may confirm)

Loss of load: Nil (Rajasthan may confirm)

Energy Loss: __ MU (Rajasthan may confirm)

Data Summary received/available at NRLDC:

Description	Reference	Fault Info	Remarks
-------------	-----------	------------	---------


Fault Clearance Time	PMU data	400ms	As per PMU data
Phase of the fault	PMU data	R-N fault	As per PMU data

Description	Utilities	Status	Remarks
Availability of Digital Data (SCADA Data)	Rajasthan	Available (Partial)	
DR/EL	Rajasthan	Received	After PSC discussion
Preliminary Report	Rajasthan	Received	Within 24hrs
Detailed Report	Rajasthan	Received	After PSC discussion


Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3) CEA (Technical standard for connectivity to the Grid, Amendment Regulation 2013), part-II, B2 4. CEA Grid Standard 3.1.e 5. CEA Transmission Planning Criteria	Rajasthan	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Correct operation of Protection System 4. Delayed Clearance of fault 5. Adequately Sectionalized and graded protective relaying system

Based on above information description of the events is:

1. Connectivity Diagram:





Single Line Diagram: **Merta(RRVPNL), 400kV side**




- Merta has following elements at 400kV: Kota-Merta S/C, Sh. Cement-Merta S/C, Jodhpur-Merta D/C, Heerapura-Merta S/C, Ratangarh-Merta S/C, Bikaner-Merta S/C, 400/220kV 315MVA ICT #1 and #2; At 220kV four S/C to Kuchera, Bhopalgarh, Pushkar and Makrana are present.
- Bus bar protection operated at 400/220kV Merta (RVPNL) due to blast in R-Phase main breaker of 400/220kV ICT-2.
- It further led to tripping of all 400kV lines and 315 MVA ICT 1 & ICT 2 at 400/220kV Merta (RVPNL).
- At Jodhpur, 400kV Jodhpur-Merta D/C tripped in Z-2 distance protection.
- As per jodhpur, Rajasthan Report:

S.N	NAME OF ELEMENT	TRIPPING DATE	TRIPPING TIME	CLOSING DATE	CLOSING TIME	INDICATION	REMARKS
1	400kV Surpura-Merta-I CKT	19.06.2018	16:15 Hrs			At Jodhpur end:- Dist. Protection Optd, Z2, R,Y,B PHASE trip	
2	400kV Surpura-Merta-II CKT	19.06.2018	16:25 Hrs			Main-I :- Distance Prot. optd. Z2, R,Y,B phase trip, Relay 186A Main II:- Dist. Prot.optd Z2, R,Y,B phase trip, Relay 186B Dist. 105.2 km	

7. PMU plots:





8. As per SCADA data:

Rajasthan/**PG** SoE

Time (in hrs)	Station	Voltage	Element	Device	Status
16:22:18,899	MAKRANA	220kV	E_05(MERTA-1)	CB	Open
16:22:18,984	KOTA	400kV	2MER1SCM	CB	Open
16:22:18,985	KOTA	400kV	3MERTA1	CB	Open
16:22:31,269	SHREE CEMENT	400kV	1MERTA	CB	Open
16:22:31,491	SHREE CEMENT	400kV	2G1MER	CB	Open

9. As per PMU & SCADA data:

- R-N fault occurred at 16:22:18.520hrs and cleared with delay in 400ms.

- 220kV Makrana-Merta, 400kV Kota-Merta D/C tripped from remote end with a delay of ~350ms & ~450ms from time of fault (as observed from PMU) respectively.
10. Preliminary Report is received from Jodhpur (RRVPNL) end but Merta end report is still awaited. Rajasthan submitted the details after PSC discussion.


Points for Discussion:

1. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared.
2. Reason for complete outage of 400/220kV Merta (RRVPNL) and tripping of both 400kV buses.
3. Reason for delayed clearance of fault to be shared.
4. Reason for tripping of 400kV Kota-Merta D/C, 400kV Jodhpur-Merta D/C and 220kV Merta-Makhrana from remote end to be shared.

Rajasthan representative informed following during the meeting:

1. At 16.17 Hrs. 400kV Merta-Bikaner line and 400kV Merta-Jodhpur-1 line tripped on distance protection operation from both end due heavy wind storm. Both lines tripped in Z1 from Merta end and Z2 from remote end.
2. After few minutes R-phase pole of ILT-2 main CB, CT and Isolator damaged. It was a fault in ICT differential zone but iCT differential protection was not operated.
3. All remaining line tripped from remote end in Z-2 distance protection except 400kV Kota line which is tripped on REF relay operation from Merta end and DT received at Kota end.
4. Transformer differential protection was not operated. Both transformers tripped on back up E/F protection after time delay as per characteristics curve and LV side CB tripped on inter trip relay operation.
5. The above fault clears in 400 msec approximately.
6. Bus bar was not operated because sufficient clearances remains from 400kV bus (No bus fault).
7. At 16.25 Hrs. R-phase pole Main CB of ILT-2 damaged due to heavy storm. The following lines/transformers tripped due this reason.
 - a. 400kV Kota (PG) line tripped on REF relay operation of 50MVAR line reactor of Merta end of 400 kV Kota (PG)-Merta ckt. REF relay operate due to stabilizing resistance of REF circuit wire broken and looped with earthed strip. Kota end tripped due to DT received.
 - b. 400kV Ratangarh line tripped in Z2 from remote end.
 - c. 400kV Heerapura line tripped in Z2 from remote end.

- d. 400kV Jodhpur-2 line tripped in Z2 from remote end.
- e. 400kV Beawar (SCL) line tripped in Z2 from remote end.
- f. 400/220kV 315 MVA ILT-1 tripped on back up E/F over current protection
- g. 400/220kV 315 MVA,ILT-2 tripped on back up E/F over current protection
- h. 125MVAR bus reactor tripped on back up impedance protection



8. Due to heavy storm 400kV Merta-Bikaner and 400kV Merta-Jodhpur-1 line tripped on distance protection from both end. It was tripped 10 minutes

NRLDC representative informed that as per location of fault, this fault would come in the bus bar differential zone instead of ICT differential protection. POWERGRID representative also supported the views of NRLDC.

NRPC also suggested to Rajasthan to review the non-operation of bus bar protection.

Rajasthan may please relooked the location of fault and reason of non-operation of bus bar protection at 400 kV Merta (Raj).

L. Multiple element tripping at 400/220kV Agra (UP) Station at 15:13hrs of 21st Jun 2018

Event category: GD-1

Generation loss: Nil

Loss of load: 550MW (UP may confirm about load loss)

Energy Loss: _____MU (UP may confirm)

Data Summary received/available at NRLDC:


Description		Fault Info	Remarks
Fault Clearance Time		NA	As per PMU data
Phase of the fault		NA	As per PMU data

Description	Utilities	Present Status	Remarks
Availability of Digital Data (SCADA Data)	Uttar Pradesh	Available (Partial)	
DR/ EL	Uttar Pradesh	Received	After 24hrs
	POWERGRID	Not Received	
Preliminary Report	Uttar Pradesh	Not Received	After 24hrs
	POWERGRID	Not Received	
Detailed Report	Uttar Pradesh	Received	After PSC meeting


Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3) CEA (Technical standard for connectivity to the Grid, Amendment Regulation 2013), part-II, B2	Uttar Pradesh & POWERGRID	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report 3. Correct operation of Protection System 4. Adequately Sectionalized and graded protective relaying system 5. Incorrect/ mis-operation / unwanted operation of Protection system

Based on above information description of the events is:

1. Single Line Diagram of 400 kV Agra (UP):




2. 400 kV Agra (UP) is connected with Fatehabad (UP) D/C, Agra (PG) S/C and Unnao S/C. It also have three 400/220 kV ICTs (2*500MVA+1*315MVA).
3. 400 kV Agra (UP) has double main and transfer scheme.
4. 400kV Agra(UP)-Unnao(UP) under planned S/D from 29-Apr-18 to 22-Jun-18 for Diversion of line (Tower no 591 - 596) due to Firozabad bypass Road of NHAI.
5. As reported, bus bar protection mal-operated at 400kV Agra (UP). All 400kV connected elements tripped.
6. Tripped elements:
 - 400kV Agra(UP)-Fatehabad(UP) D/C
 - 400kV Agra(UP)-Agra(PG)
 - 400kV/220kV 500MVA ICT #1, #2 at Agra(UP)
 - 400kV/220kV 315MVA ICT #3 at Agra(UP)
7. PMU plots:



8. SCADA SoE:

Time (in hrs)	Station	Voltage	Element	Device	Status
15:13:33,405	AGRA1_UP	400kV	F_85(T5)	CB	Open
15:13:33,405	AGRA1_UP	220kV	E_85(T5)	CB	Open
15:13:57,874	AGRA1_UP	400kV	F_04(T2)	CB	Open
15:13:57,875	AGRA1_UP	400kV	F_09(AGRA_-1)	CB	disturbe

9. SCADA Analog data of UP demand met:



10. As per PMU data and SCADA SoE:

- No fault observed.
- Rise in 400kV voltage at Agra(UP) observed at 15:13:58.640hrs. Rise in voltage was due to load loss in the system
- 400/220kV 315MVA ICT #3 tripped at 15:13:33.405hrs whereas 500MVA ICT #2 tripped after 24sec at 15:13:57.874hrs.
- No other element tripping captured in SCADA SoE

UPPTCL representative informed during the meeting:

1. The bistable CT relay (RXPSV-14) of ICT-III started chattering and caught fire in the wiring of DC which causes the shorting of DC which goes to master trip relay of Bus bar protection. The Master trip relay operated and issued the tripping command to all elements for tripping .
2. Healthiness of bus bar protection is not good. The bus bar protection is out of service . As an alternative the settings of Zone -4 has been set 160 ms.
3. The Chatterings in relays and burning of DC wiring causes shorting and the main cause of tripping .
4. SOE is enclosed herewith.
5. Time synchronization of digital SCADA is being taken in to.
6. Report is enclosed herewith.
7. DR/EL are not available as the tripping is not done by relay and no fault was observed by any relay.

[illegible]

21/06/18 15:21:24.926	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-E	MITAI TC-1	HEALTHY
21/06/18 15:21:24.370	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-E	MITAI TC-1	FAULTY
21/06/18 15:21:24.370	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-D	MITAI TC-2	HEALTHY
21/06/18 15:21:24.362	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-D	MITAI TC-2	FAULTY
21/06/18 15:14:54.455	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-N	FTBD-I M-2 Carr fail	NORMAL
21/06/18 15:14:53.279	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-N	FTBD-I M-1 Carr Fail	NORMAL
21/06/18 15:14:12.684	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-N	FTBD-I M-2 Carr fail	ALARM
21/06/18 15:14:12.677	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-N	FTBD-I M-1 Carr Fail	ALARM
21/06/18 15:13:58.671	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-I	ICT_1 TC-1/TC-2 400KV	HEALTHY
21/06/18 15:13:58.666	UPPTCL/AGRA/400kV/ELA SIGNALS/ELA SLOT-I	ICT_1 TC-1/TC-2 400KV	FAULTY
21/06/18 15:13:58.665	UPPTCL/AGRA/400kV/ELB SIGNALS/ELB SLOT-N	AGRA2 A/R Unsuccessful	NORMAL
21/06/18 15:13:58.655	UPPTCL/AGRA/400kV/ELB SIGNALS/ELB SLOT-N	AGRA2 A/R Unsuccessful	ALARM
21/06/18 15:13:13.266	UPPTCL/AGRA/400kV/ELC SIGNALS/ELC SLOT-H	ICT_3 CB TROUBLE 220KV	NORMAL
21/06/18 15:13:13.241	UPPTCL/AGRA/400kV/ELC SIGNALS/ELC SLOT-H	ICT_3 CB TROUBLE 220KV	ALARM
21/06/18 15:12:44.000	UPPTCL/AGRA/400kV/ELB SIGNALS/ELB SLOT-N	AGRA2 A/R Unsuccessful	NORMAL
21/06/18 15:12:31.158	UPPTCL/AGRA/400kV/ELB SIGNALS/ELB SLOT-N	AGRA2 A/R Unsuccessful	ALARM
21/06/18 15:12:29.337	UPPTCL/AGRA/400kV/ELB SIGNALS/ELB SLOT-N	AGRA2 A/R Unsuccessful	NORMAL
21/06/18 15:12:29.328	UPPTCL/AGRA/400kV/ELB SIGNALS/ELB SLOT-N	AGRA2 A/R Unsuccessful	ALARM
21/06/18 15:12:29.315	UPPTCL/AGRA/400kV/ELB SIGNALS/ELB SLOT-N	AGRA2 A/R Unsuccessful	NORMAL
21/06/18 15:12:29.310	UPPTCL/AGRA/400kV/ELB SIGNALS/ELB SLOT-N	AGRA2 A/R Unsuccessful	ALARM

1. Reason of complete outage may be due to bus tied operation at 400 kV Agra (UP).
2. 400/220 kV ICT-3 at Agra (UP) was manually opened, breaker didn't open due to DC supply failure.
3. Static Bus Bar Protection of 400 kV Agra (UP) would be replaced with new numerical bus bar protection in the month of November 2018.
4. *Reason for tripping of all elements at 400 kV Agra (UP) to be shared: Mal-operation of 400 kV bus bar protection and bus tied operation at 400 kV Agra (UP)*
5. *As per SCADA SoE, difference of around 24 seconds observed between tripping of 400/220kV ICT #2 and #3. Reason for the same to be shared: It would be separately checked*
6. *As per PMU, Rise in 3-phase voltage occurred at 15:13:58.640hrs whereas tripping of relevant elements in SCADA SoE occurred at 15:13:33.405hrs and 15:13:57.874hrs. Time synchronization of digital SCADA status at 400kV Agra (UP) to be looked into: It would be informed to SCADA and telecommunication and would be checked separately.*
7. *Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared: Exact sequence of event could not conclude due to non-availability of time synchronized data from 400 kV Agra (UP)*

8. *Preliminary Report, DR/EL and detailed report is still awaited from UPPTCL: Submitted at the time of PSC meeting*

Exact sequence of event could not conclude due to non-availability of time synchronized data from 400 kV Agra (UP) however as per information received, complete station outage shall be due to mal-operation of 400 kV bus bar protection and bus tied operation at 400 kV Agra (UP).

NRLDC raised concern about non-availability of time synchronized data (DR/EL) from most of the NR utilities and continuous non-compliance of earlier decision of NRPC-PSC meeting.

NRPC raised concern about non-compliance of CEA Grid standard at 400 kV station in the grid as static bus bar protection was implemented instead of numerical bus bar protection.

M. Multiple element tripping at 400/220 kV Sultanpur (UP) at 20:45hrs of 08th July 2018

Event category: GD-1

Generation loss: Nil (UP may confirm)

Loss of load: 338MW (UP may confirm)

Energy Loss: __ MU (UP may confirm)

Data Summary received/available at NRLDC:


Description	Reference	Fault Info	Remarks
Fault Clearance Time	PMU data	2040ms	
Phase of the fault	PMU data	Y-B phase to earth fault	


Description	Utilities	Present Status	Remarks
Availability of Digital Data (SCADA Data)	Uttar Pradesh	Available (Partial)	
DR/ EL	Uttar Pradesh	Not Received	Submitted Flag details
	POWERGRID	Not Received	
Preliminary Report	Uttar Pradesh	Received	Within 24hrs
	POWERGRID	Not Received	
Detailed Report	Uttar Pradesh	Received	

Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3)	Uttar Pradesh & POWERGRID	1. DR/EL, Preliminary report within 24hrs 2. Correct operation of Protection System 3. Adequately Sectionalized and graded protective relaying system

Based on above information description of the events is:

1. Connectivity Diagram:





2. 400 kV Sultanpur (UP) is connected with Azamgarh (UP) S/C, Lucknow (PG) S/C, Obra (UP) S/C and it also have three ICTs (2*315MVA+1*240MVA). 220 kV Sultanpur (UP) is connected with 220 kV Tanda S/C, 220 kV New Tanda S/C, 220 kV Pratapgarh S/C and 220kV Sohawal (UP) S/C. 220 kV Sultanpur (UP) also have two ICTs (1*200MVA+1*160MVA).
3. 400/220 kV Sultanpur (UP) have DMT (double main transfer breaker) scheme.
4. At 220kV substation Sultanpur (UP), main bus B was under shutdown.
5. After returning the shutdown at 20:16hrs, both 200MVA and 160MVA, 220/132kV transformers were taken on 220kV bus B and then 220kV side of 315MVA ICT- 3 was being transferred to 220kV bus B with closing of bus side isolator manually.
6. During the closing of isolator, flashing occurred between isolator contacts which increased further. Upon seeing heavy flashing, operator moved away from the site of isolator and informed control room.
7. After checking, it was found that during closing of isolator, high flashing occurred between jaws and operator stopped further operation of isolator. Intensity of flashing increased further after opening of 220kV bus coupler at 220kV substation Sultanpur which completely damaged the jaws and molten metal touched the structure which created fault. Spots were observed on isolator structures of Y & B phases. Fault current were also found in Y & B phases. This resulted into tripping of all 3 lines from other end in zone-3. 400/220kV ICTs did not trip. It was analysed that in such

magnitude of fault current, operating time of IDMT relay for backup protection could have been more than zone-3 operating time.


8. At 220kV substation, all charged 220kV lines and transformers were tripped manually

9. Name of the tripped elements are as below:

- 400 kV Sultanpur (UP)-Obra (UP)
- 400 kV Sultanpur (UP)-Lucknow (PG)
- 400 kV Sultanpur (UP)-Azamgarh (UP)
- 400/220 kV three ICTs (2*315MVA+1*240MVA)
- 220 kV Sultanpur (UP)-Tanda
- 220 kV Sultanpur (UP)-New Tanda
- 220 kV Sultanpur (UP)-Sohawal (UP)
- 220 kV Sultanpur (UP)-Pratapgarh (UP)

10. As per UP report:

Sl. No.	Name of element	Date & time of Normalization		Remark
1.	400KV Obra line	09.07.2018	00:10	Protection tripping
2.	400KV Azamgarh line	08.07.2018	22:35	Tripped at 400KV Azamgarh end Zone-III Protection
3.	400KV PGCIL Lucknow	08.07.2018	21:58	Tripped at 400KV PGCIL end Zone-III Protection
4.	315MVA ICT-I	08.07.2018	23:27	Hand tripped
5.	240MVA ICT-II	08.07.2018	23:06	Hand tripped
6.	315MVA ICT-III	09.07.2018	00:31	Hand tripped
7.	220KV Sohawal	08.07.2018	21:32	Hand tripped
8.	220KV New Tanda	08.07.2018	22:32	Hand tripped
9.	220KV Pratapgarh	08.07.2018	21:54	Hand tripped
10.	220KV Tanda TPS	08.07.2018	23:43	Under s/d from 06.07.2018 at 12:02



A. Introduction

1. Time & Date of Event: 20:45 hrs on 08.07.2018
2. Substation(s) affected along with voltage level: 400kV substation, Sultanpur and 220kV substation Sultanpur
3. Brief Event Summary: At 220kV substation Sultanpur, main bus B was under shutdown. After returning the shutdown at 20:16hrs, both 200MVA and 160MVA, 220/132kV transformers were taken on 220kV bus B and then 220kV side of 315MVA ICT-3 was being transferred to 220kV bus B with closing of bus side isolator manually. During the closing of isolator, flashing occurred between isolator contacts which increased further. Upon seeing heavy flashing, operator moved away from the site of isolator and informed control room. At the occurrence of flashing, all 3 numbers 400kV line at 400kV substation tripped from other end and 3 numbers 400/220kV ICTs were tripped manually. At 220kV substation, all charged 220kV lines and transformers were tripped manually. Which caused total outage of both substations.

B. Antecedent Conditions

1. Weather Information: Clear.
2. Additional relevant information viz. power flow, shutdowns etc: 220kV Main bus-B and 220kV Tanda Thermal line were under shutdown.

C. Event data

1. Change in Frequency: Not known.
2. Generation Loss/Load Loss: Total 338MW export on 220kV and 132kV lines and 132/33kV transformers.
3. Single Line Diagram (SLD) of affected Area: SLD depicting bus scheme/configuration of all the affected stations along with digital open/close status of all CB/Isolator of affected voltage level buses indicating availability of various elements viz. Buses, Lines, ICT, Reactor etc. enclosed.

4. Name and time of the tripped elements in time chronology: Based upon time stamped event log, DR etc.:

Time of tripping 20:45hrs

At 400kV substation Sultanpur:

- (i) 400kV PGCIL Lucknow line
- (ii) 400kV Obra line
- (iii) 400kV Azamgarh line
- (iv) 400/220kV 315MVA ICT-1 (Manually opened)
- (v) 400/220kV 240MVA ICT-2 (Manually opened)
- (vi) 400/220kV 315MVA ICT-3 (Manually opened)

At 220kV substation Sultanpur: Manually opened:

- (i) 220kV Pratapgarh
 - (ii) 220kV New Tanda
 - (iii) 220kV Tanda Thermal
 - (iv) 220kV Sohawal
 - (v) 220kV Bus Coupler
 - (vi) 160MVA 132/33kV Transformer
 - (vii) 200MVA 132/33kV Transformer
- And all 132kV lines(6nos.) and 132/33kV Transformers(3nos.)

5. Location and type of fault: Location of fault was on 220kV bus side isolator of 315MVA 400/220kV ICT-3.

6. Flag Details, DR and EL for each affected element: Flag details enclosed. DR not triggered due to no tripping of lines and ICTs at 400kV substation Sultanpur. Only Reactor of 400kV Obra line tripped which sent direct trip to Obra. Static relay is installed for Reactor protection. DR snapshot obtained from PG Lucknow is enclosed. EL shows no event.

7. Appropriate Graphical Plot: Including SCADA data/ print out of DR and EL details. It may be separately annexed:

D. Event Description/ Analysis of the Event

9. Description: Detailed description including the reference of DR/EL and explanation based on *pt. C. Event data.*: After checking, it was found that during closing of isolator, high flashing occurred between jaws and operator stopped further operation of isolator. Intensity of flashing increased further after opening of 220kV bus coupler at 220kV substation Sultanpur which completely damaged the jaws and molten metal touched the structure which created fault. Spots were observed on isolator structures of Y and B phase. Fault current was also found in Y and B phase. This resulted into tripping of all three lines at other end in zone-3. 400/220kV ICTs did not trip. It was analysed that in such magnitude of fault current, operating time of IDMT relay for backup protection could have been more than zone-3 operating time.

E. Restoration

10. Restoration time of tripped elements in time chronology.

At 400kV substation Sultanpur:

- | | |
|---------------------------------------|------------------------------------|
| 1. 400 KV Sultanpur – PG Lucknow line | at 21:58 hrs |
| 2. 400 KV Sultanpur – Azamgarh line | at 22:35 hrs |
| 3. 400/220kV 240 MVA T/F –2 | at 23:06 hrs |
| 4. 400/220kV 315 MVA T/F –II | at 23:27 hrs through transfer bus. |
| 5. 400kV Sultanpur – Obra line | at 00:10hrs (on 09.07.2018) |
| 6. 400/220kV 315 MVA T/F –II | at 00:31hrs (on 09.07.2018) |

At 220kV substation Sultanpur:

- | | |
|------------------------------------|--------------|
| 1. 220kV Sultanpur – Sohawal line | at 21:32 hrs |
| 2. 220/132kV 200MVA T/f | at 21:32 hrs |
| 3. 220/132kV 160MVA T/f | at 21:32 hrs |
| 4. 220kV Sultanpur - Pratapgarh | at 21:54 hrs |
| 5. 220kV Sultanpur – New Tanda | at 22:14 hrs |
| 6. 220kV Sultanpur – Tanda Thermal | at 23:43 hrs |

F. Remedial Action


- Remedial Action Taken: Isolator is being replaced.
- Remedial Action to be taken along with time frame.

G. Lesson Learnt: In this case sticking of isolator during closing operation and increase in severity of fault with the opening of 220kV Bus coupler at 220kV substation caused total outage at 400kV and 220kV substations. Motorised operation of isolator has been recommended.

11. PMU plots:


PMU Plot of frequency at Lucknow(PG)

20:45hrs/08-July-18




PMU Plot of phase voltage magnitude at Sultanpur(UP)

20:45hrs/08-July-18




PMU Plot of phase voltage magnitude at Lucknow(PG)

20:45hrs/08-July-18



400 kV Sultanpur (UP)-Lucknow (PG) fault current




12. Flag details received from UP:

Sl.no.	Name of transmission line	Time of tripping	Time of closing	Line length	Flags detail	
					At Sultanpur end	At other end
1	400kV Sultanpur - PGCIL, Lucknow	20:45hrs	21:58hrs	163.6km	no flag	Main protection trip, A/R unsuccessful, CB trip. Zone-III, B phase, distance 464km, Fault current= 1.332kA
2	400kV Sultanpur - Azamgarh	20:45hrs	22:35hrs	123.2km	no flag	Gen trip, Y-ph pickup, B-pickup, Zone-III, 86 Main & I/C breaker, over voltage alarm, Fault current= 1.14kA, IL3= 1.33kA
3	400kV Sultanpur - Obra	20:45hrs	00:31hrs (09.07.2018)	230km	no flag on line protection. Reactor protection operated 86R.	Main I&II Definitive trip, A/R block, L2-E ON, L3-E ON, Dist loop L2-3f, Dist 139.1%, IL1= 0.53kA IL2= 1.69kA IL3 = 1.54kA

13. As per SCADA Analog data:

UP Demand pattern during tripping

UP Demand Met



14. Sequence of events (As per SCADA data):

Time (in hrs)	Station	Voltage	Element	Device	Status
20:46:09.026	AZAM1_UP	400kV	5T2SU1	CB	Open
20:46:16.944	AZAM1_UP	400kV	4GRK1SU1	CB	Open

15. As per PMU & SCADA data:

- Y-B fault occurred at 20:45:51.440hrs and cleared at 20:45:53.480hrs. Hence. Delayed clearance of fault in 2040ms observed.
- Opening of both Sultanpur CBs (Azamgarh station has ring main bus scheme) from Azamgarh is observed at 20:46:09.026hrs and 20:46:16.944hrs.
- No other tripping captured in SoE.

16. Preliminary Report DR/EL and Detailed Report received from UPPTCL.

UPPTCL representative informed during PSC meeting:

1. The fault seems to be a bus fault. Hence, availability of bus bar protection at 220 kV Sultanpur (UP) and its operation at the time of tripping to be confirmed: This was not a 220 kV bus fault. Only 200 MVA and 160 MVA (220/132 kV) transformers have been connected to bus B after returning of shutdown of bus B and 220 kV side of 315 MVA 400/220 kV ICT-3 was being transferred to 220 kV bus B. After opening of 220 kV bus coupler, no other source was available on bus B. Hence bus bar fault condition did not arise. ERL make Bus bar protection is commissioned at 220 kV substation Sultanpur but presently inoperative due to alarm. M/s ERL engineer is being pursued to rectify the fault till then interim arrangement as alternative to bus bar protection has been made
2. Setting of backup overcurrent protection of 400/220kV ICTs at Sultanpur to be shared. The setting needs to be revised and coordinated with distance protection of 400kV lines:
Backup overcurrent setting of 440/220kV ICTs are: P.S.1.0 and TMS 0.35.
Total fault current observed on 400kV lines = 4.2kA
Fault current distribution on 315MVA ICTs = 1520A and on 240MVA ICT = 1160A
HV CTR = 500/1A
Hence for above backup overcurrent setting and with IDMT normal inverse, tripping time is more than 2seconds which is more than zone-3 time.
3. Non-tripping of 220kV lines in Z-2/3, Reverse zone to be looked into:
Initially only arc formed between jaws of 220kV isolator which did not create fault. Therefore tripping did not occur in zone-2/3 or in reverse zone. But all 220kV lines were opened manually and intensity of arc increased after opening of 220kV bus coupler

4. Reason for fault clearance if all the 400/220kV ICTs and 220kV lines were manually opened to be shared: As said earlier, intensity of arc between isolator jaws increased after opening of 220kV bus coupler because load of 132/33kV transformer came on this isolator which created fault on isolator structures and 400kV lines tripped at other end in zone-3
5. Exact sequence of events in view of cause of event; protection operation/non-operation; opening, closing of breaker, isolator; relevant alarms and any other relevant detail to be shared:
 - a. On 08.07.2018 at 16:20hrs, shutdown of main bus B was taken. All elements were shifted to main bus a 220kV NTPC Tanda line was already under shutdown.
 - b. At 20:16hrs, main bus B was charged and 200 MVA and 160 MVA 132/33 kV transformers were shifted to main bus B.
 - c. 220 kV isolator (885B) was being closed for taking 220 kV side of 315 MVA 400/220 kV ICT-3 on bus B.
 - d. Arc and flashing observed between jaws and operator stopped further closing of isolator.
 - e. Operator informed 220 kV control room. All the charged 220 kV lines were hand tripped and bus coupler opened.
 - f. Intensity of arc increased and molten jaws fell on the structure. Spots were later seen on maximum on B phase and traces on Y phase.
 - g. At 400 kV substation Sultanpur, 400 kV lines tripped at other ends in zone-3. 400kV Obra line tripped at Sultanpur due to operation of reactor protection. 400/220 kV ICTs were hand tripped.
 - h. Supply was restored from 220 kV Sohawal.
6. Availability of DR/EL and extracting software at 400/220 kV Sultanpur(UP) needs to be looked into: Event logger is available at 400kV Sultanpur. DR did not trigger in relays installed on 400kv lines at Sultanpur (UP).
7. Fault developed due to human error, if isolator opening was proper, this fault may be prevented.

NRPC/NRLDC raised concern for human error during maintenance activity, mal-operation of line reactor of 400 kV Sultanpur (end)-Obra ckt and protection co-ordination of Sultanpur 400/220 kV ICTs and Z-3 protection of remote end of 400kV Sultanpur (UP).

N. Multiple Element tripping at 400kV Rajpura (Punjab) on 23rd July 2018 at 03:15hrs

Event category: GD-1
 Generation loss: 650MW
 Loss of load: Nil (As per Punjab Report)
 Energy Loss: Nil MU (As per Punjab Report)

Data Summary received at NRLDC:



Description	Reference	Fault Info	Remarks
Fault Clearance Time	As per PMU data	100ms	
Phase of the fault	As per PMU data	Dip in all three phase	Bus Fault


Description	Utilities	Present Status	Remarks
Availability of Digital Data (SCADA Data)	Punjab	Available	
DR/ EL	Punjab	Received	After 24hrs (some DR pending)
	BBMB	Not Received	
Preliminary Report	Punjab	Received	After 24hrs
	BBMB	Not Received	
Detailed Report	Punjab	Received	

Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3)	Punjab	1. DR/EL, Preliminary report within 24hrs 2. Correct operation of Protection System 3. Adequately Sectionalized and graded protective relaying system 4. Incorrect/ mis-operation / unwanted operation of Protection system
	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA grid Standard 15.3	BBMB	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report


Based on above information description of the events is:

1. Connectivity Diagram:






2. 400 kV Rajpura (PSTCL) is connected with Rajpura TPS D/C, Dhuri D/C, Dehar S/C and Bhiwani S/C. It also have two 400/220 kV 500MVA ICTs and one and half breaker scheme.
3. At Rajpura (PSTCL), optical cable wire broke and fell on 400kV bus-2 at 400/220 kV Rajpura (PSTCL).
4. This resulted in operation of bus bar protection for 400 kV bus-2 and all CBs connected to 400 kV Rajpura (PSTCL) bus-2 tripped.
5. At the same time, tie CBs of feeders also tripped mainly due to wrong mapping of function in relay. The same has been reportedly corrected.
6. In antecedent condition:
 - Tie CB of 400/220kV ICT #3 already open (Dia not completed as future bay).
7. Name of the tripped elements:
 - Unit 1 and 2 of 700MW at Rajpura Thermal
 - 400kV Rajpura-Rajpura Thermal D/C
 - 400kV Rajpura-Bhiwani
 - 400kV Rajpura-Dehar
 - 500MVA ICT 3&4 at Rajpura
8. PMU plot of frequency, df/dt and phase voltages:



PMU Plot of phase voltage magnitude at Bhiwani(BBMB)

03:15hrs/23-July-18



1. As per SCADA SoE:


Time	Time Duration (in ms)	S/S Name	Voltage Level (in kV)	Element Name	Element Type	Status	Remarks
03:14:55:000	0ms	PMU data					Reference Time
03:14:55:085	85ms	RAJPURA	400kV	21BHIWNI	Circuit Breaker	disturbe	
03:14:55:088	90ms	RAJPURA	400kV	24DEHAR	Circuit Breaker	disturbe	
03:14:55:097	95ms	RAJPURA	400kV	21BHIWNI	Circuit Breaker	Open	Main CB of 400 kV Rajpura(end)-Bhiwani opens
03:14:55:098	100ms	RAJPURA	400kV	24DEHAR	Circuit Breaker	Open	Main CB of 400 kV Rajpura(end)-Dehar opens
03:14:55:104	105ms	RAJPURA	400kV	20LI1BWN	Circuit Breaker	disturbe	
03:14:55:108	110ms	RAJPURA	400kV	23LI2DHR	Circuit Breaker	disturbe	
03:14:55:115	115ms	RAJPURA	400kV	20LI1BWN	Circuit Breaker	Open	Tie CB of 400 kV Rajpura(end)-Bhiwani opens { 400 kV Rajpura(end)-Bhiwani opens }
03:14:55:120	120ms	RAJPURA	400kV	23LI2DHR	Circuit Breaker	Open	Tie CB of 400 kV Rajpura(end)-Dehar opens { 400 kV Rajpura(end)-Dehar opens }
03:14:55:140	140ms	RAJPURA	400kV	F_6 (BUS	Circuit Breaker	disturbe	
03:14:55:143	145ms	RAJPURA	400kV	F_6 (BUS	Circuit Breaker	disturbe	
03:14:55:146	145ms	RAJPURA	400kV	F_6 (BUS	Circuit Breaker	Open	
03:14:55:148	150ms	RAJPURA	400kV	F_6 (BUS	Circuit Breaker	Open	
03:14:55:248	250ms	RAJPURA	400kV	18RAJPR1	Circuit Breaker	Open	Main CB of 400 kV Rajpura(end)-Rajpura(TH) Ckt-1 opens
03:14:55:333	335ms	RAJPURA	400kV	14DHRJP2	Circuit Breaker	Open	Tie CB of 400 kV Rajpura(end)-Rajpura(TH) Ckt-2 opens
03:14:55:370	370ms	RAJPURA	400kV	15RAJPR2	Circuit Breaker	Open	Main CB of 400 kV Rajpura(end)-Rajpura(TH) Ckt-2 opens { 400 kV Rajpura(end)-Rajpura(TH) Ckt-2 opens }
03:14:55:666	665ms	RAJPURA	400kV	17DHRJP1	Circuit Breaker	Open	Tie CB of 400 kV Rajpura(end)-Rajpura(TH) Ckt-1 opens { 400 kV Rajpura(end)-Rajpura(TH) Ckt-1 opens }
03:14:57:137	2135ms	RAJPURA	220	5T3	Circuit Breaker	disturbe	
03:14:57:138	2140ms	RAJPURA	400kV	F_5 (K'D	Circuit Breaker	disturbe	
03:14:57:139	2140ms	RAJPURA	400kV	F_5 (K'D	Circuit Breaker	Open	
03:14:57:143	2145ms	RAJPURA	220	5T3	Circuit Breaker	Open	Main CB of 220kV Side of 500MVA ICT3 opens
03:14:57:145	2145ms	RAJPURA	220	6T4	Circuit Breaker	disturbe	
03:14:57:146	2145ms	RAJPURA	220	6T4	Circuit Breaker	Open	Main CB of 220kV Side of 500MVA ICT4 opens

9. As per PMU and SCADA data:


- 3-phase fault observed at 03:14:55.000hrs and got timely cleared.
- Tripping of main Tie CBs of all tripped ckts captured in SoE except 400kV side CBs of ICTs.
- It seems CB of bay 414, 415, 417 & 418 opened with time delay

10. As per DR details:


DR: 400/220kV ICT #3 at Rajpura (PSTCL)




DR: 400/220kV ICT #4 at Rajpura




DR: 400kV Rajpura(end)-Rajpura TPS-1



DR: 400kV Rajpura(end)-Rajpura TPS-2




DR: bay 411 (Tie CB of ICT #4) at Rajpura



DR: bay 414 (Tie of Rajpura TPS-2 & Dhuri-2) at Rajpura



DR: bay 417 (Tie of Rajpura TPS-1 & Dhuri-1) at Rajpura



Event Log: Bay 415 (Rajpura TPS-2, main)

Event Log - 23-07-18 - 400KV RAJPURA / 400KV / 415 / BCU_415/6MD663 V04.83.03(3)						
Number	Indication	Value	Date and time	Cause		State
170.0065.01	25 voltage V1 too low	ON	23.07.2018 06:33:48.937	Spontaneous Com. Issued=AutoLocal		
170.0043.01	>25 funct.group 1 measurement only	ON	23.07.2018 06:33:48.932	Spontaneous Com. Issued=AutoLocal		
52 CB		CLOSE	23.07.2018 06:33:39.295	Select before Operate Positiv Command Issued=SICAM		
52 CLIL		ON	23.07.2018 05:37:12.492	Spontaneous Com. Issued=AutoLocal		
86.2 Optd		OFF	23.07.2018 05:37:12.456	Spontaneous		
86.1 Optd		OFF	23.07.2018 05:37:11.008	Spontaneous		
86B OprCnt		62	23.07.2018 05:31:40.185	Spontaneous Com. Issued=AutoLocal		
86B ISO		CLOSE	23.07.2018 05:31:40.177	Spontaneous		
86B ISO		Intermediate Position	23.07.2018 05:31:37.717	Spontaneous		
86B OprCnt		61	23.07.2018 05:06:42.735	Spontaneous Com. Issued=AutoLocal		
86B ISO		OPEN	23.07.2018 05:06:42.735	Spontaneous		
86B ISO		Intermediate Position	23.07.2018 05:06:38.951	Spontaneous		
CB OprCnt		169	23.07.2018 03:14:55.375	Spontaneous Com. Issued=AutoLocal		
86B CLIL		ON	23.07.2018 03:14:55.371	Spontaneous Com. Issued=AutoLocal		
86B OPIL		ON	23.07.2018 03:14:55.371	Spontaneous Com. Issued=AutoLocal		
86A OPIL		ON	23.07.2018 03:14:55.371	Spontaneous Com. Issued=AutoLocal		
86A CLIL		ON	23.07.2018 03:14:55.371	Spontaneous Com. Issued=AutoLocal		
52 CLIL		OFF	23.07.2018 03:14:55.370	Spontaneous Com. Issued=AutoLocal		
52 CB		OPEN	23.07.2018 03:14:55.370	Spontaneous Com. Issued=AutoLocal		

Event Log - 23-07-18 - 400KV RAJPURA / 400KV / 415 / BCU_415/6MD663 V04.83.03(4)						
Number	Indication	Value	Date and time	Cause		State
02703	>BLOCK 79	ON	23.07.2018 03:14:55.369	Spontaneous Com. Issued=AutoLocal		
02783	79: Auto recloser is blocked	ON	23.07.2018 03:14:55.370	Spontaneous Com. Issued=AutoLocal		
	CB Y OprCnt	176	23.07.2018 03:14:55.115	Spontaneous Com. Issued=AutoLocal		
	52 CB YPH	OPEN	23.07.2018 03:14:55.106	Spontaneous		
	CB B OprCnt	182	23.07.2018 03:14:55.105	Spontaneous Com. Issued=AutoLocal		
	CB R OprCnt	182	23.07.2018 03:14:55.105	Spontaneous Com. Issued=AutoLocal		
	86.1 Optd	ON	23.07.2018 03:14:55.105	Spontaneous		
	86.2 Optd	ON	23.07.2018 03:14:55.103	Spontaneous		
	52 CB BPH	OPEN	23.07.2018 03:14:55.103	Spontaneous		
	52 CB RPH	OPEN	23.07.2018 03:14:55.103	Spontaneous		

CB open
indication at
03:14:55.370hrs

Individual phases
opened at
03:14:55.105hrs

Event Log: Bay 418 (Rajpura TPS-1, main)

Event Log - 23-07-18 - 400KV RAJPURA / 400KV / 418 / BCU_418/6MD663 V04.83.03(8)

Number	Indication	Value	Date and time	Cause	State
	CBLWOILAL	OFF	23.07.2018 03:14:57.046	Spontaneous	
	CBLWOILAL	ON	23.07.2018 03:14:57.028	Spontaneous	
	CBLWOILAL	OFF	23.07.2018 03:14:56.974	Spontaneous	
	CBLWOILAL	ON	23.07.2018 03:14:56.957	Spontaneous	
	CBLWOILAL	OFF	23.07.2018 03:14:56.822	Spontaneous	
	CBLWOILAL	ON	23.07.2018 03:14:56.814	Spontaneous	
	CBLWOILAL	OFF	23.07.2018 03:14:56.752	Spontaneous	
	CBLWOILAL	ON	23.07.2018 03:14:56.736	Spontaneous	
	CBLWOILAL	OFF	23.07.2018 03:14:56.602	Spontaneous	
	CBLWOILAL	ON	23.07.2018 03:14:56.588	Spontaneous	
	CBLWOILAL	OFF	23.07.2018 03:14:56.530	Spontaneous	
	CBLWOILAL	ON	23.07.2018 03:14:56.517	Spontaneous	
	416 LCVT SEL	OFF	23.07.2018 03:14:56.193	Spontaneous Com.Issued=AutoLocal	
	89L OPIL	ON	23.07.2018 03:14:56.192	Spontaneous Com.Issued=AutoLocal	
	89L CLIL	ON	23.07.2018 03:14:56.192	Spontaneous Com.Issued=AutoLocal	
	.417 CB	OPEN	23.07.2018 03:14:55.688	Spontaneous Com.Issued=AutoLocal	

Tie CB (417)
 opened at
 03:14:55.680hrs

11. As per Punjab Report:

Element Tripped: - Rajpura (400 kV) – Rajpura (NPL) circuit 1 & 2, Rajpura (400 kV) - 400kV Bhiwani ckt, Rajpura (400 kV) – 400kV Dehar ckt, 400kV Bus-Bar 2 and ICT 3 & 4 tripped at 400 kV Rajpura Sub-Station PSTCL

Ref : Preliminary Report No: NR_GD_GI/1314 Dated 23.07.2018

1.	Confirm the actual load loss.	NIL MW
2.	Reason of bus fault.	-
3.	Action being taken to prevent such incident in future.	-
4.	Reason of delayed clearance of fault as per IEGC.	-

5.	Detailed Report	
a.	Time and date of event (GPS Sync time)	23.July.18 03:15:00 Hrs
b.	Location.	Rajpura (Punjab)
c.	Plant and/or Equipment directly involved.	Rajpura Thermal circuit 1 & 2, 400kV Bhiwani ckt, 400kV Dehar ckt, 400kV Bus-Bar 2 and I CT 3&4 at Rajpura, PSTCL
d.	Single line diagram showing the connection (isolators) of various 220 KV lines, bus coupler, ICT's etc	-
e.	Description and cause of event.	Optical cable broke and fallen on Bus-Bar 2
f.	Antecedent conditions of load and generation, including frequency, voltage and the flows in the affected area.	Generation Loss- Load Loss- NIL MW Frequency – 50.02 Hz Voltage – 415 kV
g.	Time duration of tripping including Weather Condition prior to the event.	Weather Condition - Cloudy
h.	Duration of interruption and Demand and/or Generation (in MW and MWh) interrupted.	Nil
i.	All Relevant system data including copies of records of all recording instruments including Disturbance Recorder, Event Logger, DAS etc of DPR's of affected lines.	Attached
j.	Sequence of tripping with time.	#
k.	Details of Relay Flags.	
l.	Remedial measures.	--

Description and cause of event.	Optical cable broke and fallen on Bus-Bar 2
<p>❖ 400/220kV ICT-3 (Bay 409)</p> <ul style="list-style-type: none"> • Bus-Bar Differential Relay 87BB sensed the fault and picked up at 03:14:55:076 Hrs • 87BB issued the Trip command instantaneously • Tie CBs of Bay 408 was already in open state and Main CBs open detected after 48 msec. <p>❖ 400/220kV ICT-4 (Bay 412)</p> <ul style="list-style-type: none"> • Disturbance was observed at 03:14:55:064 Hrs • Bus-Bar Differential Protection Relay picked up at 03:14:55:076 Hrs • 87BB picked up the fault at 03:14:55:076 and issued the Trip command instantaneously • Main CBs was opened at 03:14:55:105 Hrs and thus clear the Fault at 03:14:55:124 Hrs • Tie CBs also got opened at 03:14:55:129 Hrs and it was found that the address #6201 having function 'Configuration of Signal Relay' was wrongly set to Function No. 7631 'Busbar Protection: Trip in phase L123' which lead to tripping signal being issued to Tie CBs. It is now corrected to Function No. 7639 'Busbar Protection: Intertrip'. <p>❖ 400kV Rajpura Thermal (NPL) ckt-2 (Bay 415)</p> <ul style="list-style-type: none"> • Disturbance was recorded in Distance Protection Relay at 03:14:55:062 Hrs and got picked up for reverse fault of phase Yellow and Blue phase at 03:14:55:104 Hrs • 87BB picked up the fault at 03:14:55:079 and issued the Trip command instantaneously to three phases • Main CBs open detected at 03:14:55:114 Hrs • LBB Relay was operated and Direct Trip was sent to other end due to the wrong addressing of #6201 to Function No. 7631 'Busbar Protection: Trip in phase L123'. This also lead to tripping signal being issued to Tie CBs and opened the Tie CBs at 03:14:55:119 Hrs. It is now corrected to Function No. 7639 'Busbar Protection: Intertrip'. 	
<p>❖ 400kV Rajpura Thermal (NPL) ckt-1 (Bay 418)</p> <ul style="list-style-type: none"> • Disturbance was recorded in Distance Protection Relay at 03:14:55:064 Hrs and got picked up for reverse fault of phase Yellow and Blue phase at 03:14:55:104 Hrs • 87BB picked up the fault at 03:14:55:074 and issued the Trip command instantaneously to three phases • Main CBs open detected at 03:14:55:101 Hrs • LBB Relay was operated and Direct Trip was sent to other end due to the wrong addressing of #6201 to Function No. 7631 'Busbar Protection: Trip in phase L123'. This also lead to tripping signal being issued to Tie CBs and opened the Tie CBs at 03:14:55:116 Hrs. It is now corrected to Function No. 7639 'Busbar Protection: Intertrip'. <p>❖ 400kV Bhiwani (Bay 421)</p> <ul style="list-style-type: none"> • Distance Protection Relay (Main-2) picked the fault in reverse zone at 03:14:55:081 Hrs • Fault current entered in 87BB at 03:14:55:064 Hrs and it got picked after 14 msec and instantly issued the trip command to three phases • Main CBs were detected open at 03:14:55:111 Hrs • Tie CB B phase open detected at 03:14:55:129 Hrs. Tie CB tripped due to the reason mentioned in the above circuits and wrong addressing of #6201 to Function No. 7631 'Busbar Protection: Trip in phase L123' now corrected to Function No. 7639 'Busbar Protection: Intertrip'. 	

❖ **400 kV Dehar (Bay 424)**

- Distance Protection Relay (Main-2) pick the fault in reverse zone at 03:14:55:089 Hrs and 86 Master operated after 5 msec
- Main CBs were open detected within 5msec from 03:14:55:111 Hrs
- Tie CB B phase open detected at 03:14:55:129 Hrs. It is assumed that Tie CB tripped due to the reason mentioned in the above circuits but no 'LBB relay operated' or 'Direct trip send' signal was found in the Event log. The current setting of 87BB is now corrected to Function No. 7639 'Busbar Protection: Intertrip'.

❖ **Tie Bay 411**

- Fault current entered at 03:14:55:059 Hrs as LBB Relay recorded and picked up at 03:14:55:108 Hrs
- TCB of R-Y-B phases opened at 03:14:55:132 due to the LBB protection because Local Trip Time was found 0 msec instead of 200 msec. Now it is corrected.

❖ **Tie Bay 414 & 417**

- After fault detected in 87BB of NPL Bays, issued the trip command to Main CBs and due to the wrong setting parameter of #6201 to Function No. 7631 'Busbar Protection: Trip in phase L123', M1 contact was operated thus issued DT send to remote end and also Trip TCBs of Bay. This opened the Tie CBs. The setting is now corrected to Function No. 7639 'Busbar Protection: Intertrip'.

❖ **Tie Bay 420 & 423**

- 87BB of Main Bay(421,424) issued the trip command to Main CBs and due to the wrong setting parameter of #6201 to Function No. 7631 'Busbar Protection: Trip in phase L123', M1 contact was operated thus issued DT send to remote end and also Trip TCBs of Bay 420 & 423. It is corrected now.

12. Preliminary Report, DR/EL and detailed report has been received from Punjab.

Punjab informed on action Points:

1. DR of 421 (Bhiwani) and 424 (Dehar) bay are yet to be received. The same needs to be provided: DR was not recorded for these bays and DR of BCU already shared.
2. Post fault time in DR of few bays are very less (~100ms only). The same needs to be extended for better analysis of event. (-500ms and +2000ms): DR recording time would be changed. It would also be checked at other 400 kV station of Punjab.
3. Reason for tripping of units at Rajpura TPS to be ascertained and shared: During heavy voltage dip in system, Rajpura generators trip, exact reason of tripping was not shared.
4. Reason for initiation of LBB protection in few of the Tie bays at Rajpura to be shared: Continuous LBB initiation would be checked separately.

Punjab informed about Points for Discussion:

1. It seems from SCADA SoE and BCU Event Log data that CB of 415 and 417 bay opened after 350ms and 680ms of fault occurrence. However, fault got cleared within 100ms: It may be time Synchronization error in DR

2. Reason of rise in frequency first than dip in frequency to be explained:
Stalling of motor was not reported by any of the NR utilities. It may be related to parallel incident in other region.

NRPC raised concern about non-submission of details of state generating companies and IPPs under state control area. STU/SLDC has to take up this matter with state generating stations/company and IPPs.

O. Multiple element tripping at 400/220 kV Panki (UP) at 02:38hrs of 26th July 2018

Event category: GI-2

Generation loss: Nil (As per UP Report)

Loss of load: Nil (As per UP Report)

Energy Loss: __ MU (As per UP Report)

Data Summary received/available at NRLDC:

Description	Reference	Fault Info	Remarks
Fault Clearance Time	PMU data	No fault	
Phase of the fault	PMU data	No fault	

Description	Utilities	Present Status	Remarks
Availability of Digital Data (SCADA Data)	Uttar Pradesh	Available (Partial)	
DR/ EL	Uttar Pradesh	Not Received	
	POWERGRID	Not Received	
Preliminary Report	Uttar Pradesh	Not Received	
	POWERGRID	Not Received	
Detailed Report	Uttar Pradesh	Not Received	

Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for	Uttar Pradesh & POWERGRID	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report not received 3. Correct operation of Protection System 4. Adequately


	Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3) CEA (Technical standard for connectivity to the Grid, Amendment Regulation 2013), part-II, B2	Sectionalized and graded protective relaying system 5. Incorrect/ mis-operation / unwanted operation of Protection system
--	--	--

Based on above information description of the events is:

1. Single Line Diagram:

SLD of 400/220 kV Panki (UP) before the incident

02:38hrs/26-July-18




- 400 kV Panki (UP) is connected with Kanpur (PG) D/C, Unnao (UP) S/C, Aligarh (UP) S/C, Allahabad (UP) S/C. It also have two 400/220 kV ICTs (1*315MVA+1*240MVA).
- 400 kV Panki (UP) has Double Main Transfer Breaker scheme.
- 400/220 kV ICT-2 at Panki (UP) was already under long outage from 17.06.2018 due to blast in the ICT-2.

5. 400/220 kV ICT-1 also tripped at 01:35hrs of 26th July 2018.
6. At 02:38hrs, all 400 kV lines from 400 kV Panki (UP) tripped due to DC earth fault at the station.
7. Name of the tripped elements are as below:
 - 400 kV Panki-Kanpur (PG) ckt-1 & 2
 - 400 kV Panki-Unnao (UP) ckt
 - 400 kV Panki-Aligarh (UP) ckt
 - 400 kV Panki-Allahabad (UP) ckt
8. No report received from UPPTCL.

9. PMU plots:

PMU Plot of frequency of Kanpur (PG) station

02:38hrs/26-July-18




PMU Plot of phase voltage of Kanpur (PG) Bus

02:38hrs/26-July-18




PMU Plot of phase voltage of Unnao(UP) Bus

08:32hrs/26-July-18



PMU Plot of phase voltage of Kanpur(PG)

15:59hrs/26-July-18



10. Sequence of events (As per SCADA data):

Time	S/S Name	Voltage (in kV)	Element Name	Element type	Status	Remarks
02:38:16,385	UNNAO_UP	400kV	F_05(PANK1-1)	Circuit Breaker	Open	UP SoE
02:38:17,397	PANK1_UP	400kV	F_06(OBRAB)	Circuit Breaker	disturbe	UP SoE
02:38:17,434	PANK1_UP	400kV	05MBC	Circuit Breaker	disturbe	UP SoE
02:38:17,437	PANK1_UP	400kV	F_09(KANPR-2)	Circuit Breaker	Open	UP SoE
02:38:17,464	PANK1_UP	400kV	F_01(UNNAO-1)	Circuit Breaker	Open	UP SoE
02:38:17,465	PANK1_UP	400kV	F_10(MUR1N)	Circuit Breaker	Open	UP SoE
02:38:17 ***	KANPUR	400kV	5PAN2FA2	Circuit Breaker	Open	NR SoE
02:38:17,488	PANK1_UP	400kV	F_09(KANPR-1)	Circuit Breaker	Open	UP SoE
02:38:17,748	ALIGR_UP	400	LIPANK1	Protection Trip	App	UP SoE
02:38:17,790	ALIGR_UP	400	04PANK1	Circuit Breaker	Open	UP SoE
02:38:17,792	ALIGR_UP	400	05TIE	Circuit Breaker	Open	UP SoE

Time (in ms)	S/S Name	Voltage (in kV)	Element Name	Element Type	Status	Remarks
08:32:19,988	PANK1_UP	400	F_08(KANPR-1)	Circuit Breaker	Open	UP SoE
08:32:20,251	PANK1_UP	400	F_02(T1)	Circuit Breaker	Open	UP SoE
15:59:06,236	PANK1_UP	400	F_06(OBRAB)	Circuit Breaker	disturbe	UP SoE
15:59:06,238	PANK1_UP	400	F_10(MUR1N)	Circuit Breaker	Open	UP SoE
15:59:06,241	PANK1_UP	400	F_06(OBRAB)	Line Isolator	Open	UP SoE
15:59:06,241	PANK1_UP	400	F_06(OBRAB)	BusBar Isolator 1	Open	UP SoE
15:59:08,246	ALIGR_UP	400	LIPANK1	Protection Trip	App	UP SoE
15:59:08,277	ALIGR_UP	400	05TIE	Circuit Breaker	Open	UP SoE
15:59:08,280	ALIGR_UP	400	04PANK1	Circuit Breaker	Open	UP SoE

11. As per PMU & SCADA data:

- No fault in the system all the time.

- It seems all the connected elements tripped within 100ms from Panki (UP) end.
- It seems all 400 kV connected elements also tripped from remote end of 400 kV Panki (UP).

12. Preliminary Report DR/EL and Detailed Report is still awaited from UPPTCL.

Discussion points

1. Complete station outage due to DC earth fault is serious cause of concern and same needs to be explained.
2. Reason of tripping of connected 400 kV elements from remote end of 400 kV Panki (UP).
3. Exact reason of complete station outage and sequence of tripping needs to be submitted with supporting details from the station end.
4. Remedial measures taken report to be shared.
5. Availability and healthiness of bus bar protection at 400 kV Panki (UP) at the time of tripping to be shared.

UPPTCL representative informed on discussion points:

TRIPPING ANALYSIS AT 400KV S/S Panki , Kanpur On date 26.07.2018 at 01:35 Hrs .

Name of Feeder/TF	Tripping Date Time	Closing Date Time	Type of Relay	C.B. No.	Flags	Other End	Analysis
240MVA ICT-I	26.07.2018 01:35	26.07.2018 07:43	DTH-32		CP:- Nil RP:- 86ITC, 86ITD 220KV Side CP:- Nil RP:- Nil.	On Dated 26.07.2018 , at 01:35 ICT-I tripped due to DC earthing problem, flag observed only 86ITC, 86ITD after that at 02:38 AM, all lines, 400KV Panki-Rewa Road, PGCIL-I, PGCIL-II, Aligarh line, Unnao line & Bus Coupler tripped due to DC earthing problem, Flag observed 96L1,96L2,96L4, 96IT-1, 96IT-2, 96BCA, 96BCB so all feeders tripped due to DC earthing problem.
400KV Unnao Line	26.07.2018 02:38	27.07.2018 09:41	Siprotec		CP:- Trip CT 1/2 Faulty RP:- M-2, GR-A, B/B Trip Unit Opted.	CP:- Ch-I DTR, CH-2 DTR, Group-A Trip relay Optd. CB trip CKT 1/2 Faulty. RP:- No Flag.	
400KV Aligarh Line	26.07.2018 02:38	26.07.2018 08:06	Siprotec		CP:- Nil RP:- Nil.	DT Receive	
400KV Rewa Road Line	26.07.2018 02:38	26.07.2018 08:49	Siprotec		CP:- Nil RP:- Nil.	No Flag	
400KV PGCIL Line-I	26.07.2018 02:38	26.07.2018 07:21	Micom		CP:- Nil RP:- M-I, 195CR, 195CY.	No Flag	
400KV PGCIL Line-II	26.07.2018 02:38	OFF	Siprotec		CP:- Nil RP:- M-II, 96,96X,96B/B Prot. Trip relay 186A,186B.	DT Receive	
400KV Panki - Bus Coupler	26.07.2018 02:38	OFF	EE		CP:- Low pressure CKT breaker. RP:- 96L1, 96L2, 96L4,96IT-1,96IT-2,96TBCX, 96BCA, 96BCB, 95CC, 195CA, 195CB,195CC.	
400KV Panki - Transfer Bus Coupler	26.07.2018	OFF	EE		OFF	

- 5- On dated 25/26 of July 2018 it was raining due to which cable trenches got filled with rainy water. The damaged cables due to damage of ICT-II 240 kv transformer On dated 17-06-18 in at 18:13 hrs created D.C. problem at 400 kv. S/S Panki Kanpur tripping all the feeder & transformer at 02:38 hrs of 26-07-18.
6. Bus-Bar protection operated with the following flags.
96L1, 96L2, 96L4, 96IT1, 96IT2, 96TRCX, 96BCA, 96BCB, 195CA, 195CB, 95CC,
7. Reason of complete outage at 400 kv. S/S Panki Kanpur is only due to D.C. earthing so that bus-bar protection operated tripping all the elements connected to grid. The disturbance recorder was not working. The event logger report in being enclosed herewith of sequence of events of tripping occurred on 26-07-18 at 2:38 hrs.
8. D.C. earthing problem was traced which was due to burnt cable of ICT-II (damaged on 17-06-18/18:13 hrs).

As soon as the problem of D.C. earthing is removed on dated 27-07-18 the following feeders/ transformer charged finally.

- 1- 19:05 hrs- 400 KV Panki Unnao line is charged.
- 2- 20:54 hrs – 240 MVA ICT-I charged.
- 3- 21:34 hrs – 400 Kv. Panki Aligarh line charged.

And on dated 28-07-18 at 11:51 hrs – 400 kv. Panki Kanpur-I could be charged finally.

However due to problem of +ive D.C.earth leak in 400 kv. Panki Kanpur-II & 400 kv Bus-coupler could not be charged.

On dated 09-08-18 at 16:17 hrs Power grid staff taken S/D of 400 kv Panki Kanpur-II circuit for rectification of +ive D.C.earth leak problem in D.C. circuit.

After removing the D.C. fault 400 kv Panki Kanpur-II circuit could be charged on 18:24 hrs of 10-08-18 but due to Problem of +ive D.C. earth leak the 400 kv Bus-coupler could't be charged yet, though the fault of +ive D.C.earth leak was being traced continuously.

Finally on dated 16-08-18 at 13:23hrs after removing fault of +ive D.C. earth leak, 400 K.V. Bus coupler was closed.

9. Bus-bar protection at 400 kv S/S Panki Kanpur at the time of tripping was in healthy condition.

Water logging in cable trench resulted into DC fault and it further resulted into operation of 400 kV bus bar protection for both the 400 kV buses of Panki (UP). Later on, DC earth fault issue has been resolved at 400 kV Panki (UP)

P. Multiple element tripping at 400/220 kV Suratgarh STPS (Raj) at 12:08hrs of 01st Aug 2018

Event category: GD-1

Generation loss: 380 MW (As per Rajasthan report)

Loss of load: Nil

Energy Loss: Nil

Data Summary received/available at NRLDC:

Description	Reference	Fault Info	Remarks
-------------	-----------	------------	---------


Fault Clearance Time	PMU data	100ms	
Phase of the fault	PMU data	Y-N fault	

Description	Utilities	Status	Remarks
Availability of Digital Data (SCADA Data)	Rajasthan	Available	Time Synch Error
DR/EL	Rajasthan	Received (only Event Logger)	Numerical protection was not available
Preliminary Report	Rajasthan	Received	After 24hrs
Detailed Report	Rajasthan	Received	

Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3, 6.4) CEA (Technical standard for connectivity to the Grid, Amendment Regulation 2013), part-II, B2	Rajasthan	1. Detailed Report didn't provide 2. Adequately Sectionalized and graded protective relaying system 3. Incorrect/ mis-operation / unwanted operation of Protection system 4. Non-availability of numerical bus bar protection at 220kV and above station 5. Non availability of DR for 400/220 kV ICTs

Based on above information description of the events is:

1. Connectivity Diagram of 400/220 kV Suratgarh TPS:




2. 220 kV Suratgarh TPS is connected with Ratangarh D/C, Suratgarh(Raj) D/C, Sriganganagar S/C and Bhadra S/C. It also have two 400/220kV ICTs (2*315MVA). Unit-1&2 (250MW) connected at 220 kV station and Unit-3,4,5&6 (250MW) connected at 400 kV Suratgarh TPS. 400kV Suratgarh TPS is further connected with Ratangarh S/C, Bikaner S/C, Suratgarh SCTPS D/C.
3. 400 kV Suratgarh TPS has one an half breaker scheme and 220 kV Suratgarh TPS has DMT (double main transfer breaker) scheme.
4. Antecedent Condition:
 - 400kV Suratgarh TPS unit-3 & 4 (250MW) was running at 190MW. Unit-5 & 6 (250MW) was under shutdown
 - 400 kV and 220 kV all the buses were under charged condition at 400/220 kV Suratgarh TPS
5. Name of the tripped elements are as below:
 - 220 kV Suratgarh TPS-Ratangarh ckt-2
 - 220 kV Suratgarh TPS-Suratgarh ckt-2
 - 220 kV Suratgarh TPS- Bhadra ckt
 - 400/220 kV 315MVA ILT-1 &2
 - 220 kV Station Transformer-4
 - 250MW Unit-3 & 4

6. At 12:08hrs, Y-phase CT of 220 kV Suratgarh TPS (end)-Ratangarh ckt-2 bursted and resulted into bus fault for 220 kV Bus-2 of Suratgarh TPS. Feeders/ Transformers connected to faulted bus immediately tripped due to operation of bus bar protection.

7. PMU plots:



PMU plot of frequency of Sikar (PG)



PMU plot of phase voltages of Sikar (PG)

8. As per PMU data:

- Y-phase to earth fault. Fault started at **12:08:39.360hrs**
- Fault clearance time: within **100ms**

9. As per Rajasthan Report:

- At 12:08hrs, Y-phase CT of 220 kV Suratgarh TPS (end)-Ratangarh ckt-2 bursted and resulted into bus fault for 220 kV Bus-2 of Suratgarh TPS. Feeders/ Transformers connected to faulted bus immediately tripped due to operation of bus bar protection.
- After detailed checking, it was found that B-phase CT of 220 kV Suratgarh TPS-Ratangarh ckt-2 was bursted and caught fire. Fire was immediately controlled with the help of water spraying/ foam jets through fire tender after isolation the feeder from STPS & Remote end.
- It was found that B-phase CT of 220 kV was bursted. Due to bursting of B-phase CT of 220 kV Suratgarh TPS-Ratangarh ckt-2, the splinters of this also damaged Y-phase CT and adjoining isolator 89-C & 89-D of same feeder, which resulted into the bus fault and caused the bus bar protection operation for 220 kV Bus-2.

- The backup earth fault protection of 220 kV side of 400/220 kV ICT-1 was also operated and tripped the ICT-1 immediately. 400 kV side breaker also tripped on inter tripping.
- CDD-31 type Alstom make earth fault protection relay is installed on ILT# 1&2.
- RADSS type ABB make Bus Bar protection relay is installed at 220 KV buses. No facility for DR/ EL is available in these CDD-31 & RADSS relays.
- At STPS, 6 nos. 220/6.6 KV station transformers are installed to fed the auxiliary power to all 6 nos. 250MW units. Each unit has independent 220/6.6 KV station transformer to fed auxiliary power to respective unit like ST#3 for unit#3, ST#4 for unit#4 etc. All the station transformers are connected with 220 KV switchyard. GT#1&2 are connected with 220 kV switchyard & GT#3, 4, 5 & 6 are connected with 400 kV switchyard and 220 kV & 400 kV switchyards are connected through ILT#1&2.
- Due to the operation of Bus bar protection of 220 kV bus-2, the connected station transformer#4 was tripped on bus bar protection. Station Transformer#3 was not tripped as this was connected with 220 KV Bus-1B.
- The auxiliary supply failure of unit#4 was due to tripping of ST#4 resulted in tripping of unit#4. And auxiliaries of unit#3 were tripped due to heavy dip in 220 KV system voltage resulted in tripping of unit#3.
- For Unit#3, heavy voltage dip occurred in 220 KV system voltage and 415 V emergency bus tripped & hence LOPs of main unit auxiliaries (i.e. ID, FD, Mill, PA etc.) tripped which resulted in “boiler trip on all ID fans off”, consequently turbine tripped on MFR & finally Generator tripped on turbine trip.
- For Unit#4, tripping of Station Transformer# 4 occurred due to operation of Bus Bar protection of 220 KV Bus-2, all unit auxiliaries like ID, FD, Mill, PA, BFP, CEP etc. tripped & boiler tripped on “loss of all fuel” resulted in turbine trip on MFR & finally Generator tripped on turbine trip.
- Arrangement of Auxiliary supply:
 - a. In Unit# 3, no UATs are installed. This unit# 3 has independent 50 MVA, 220/6.9 KV station transformer to fed auxiliary power to 6.6 KV unit Buses 3SA& 3SB through 6.6 KV station Bus OSC.
 - b. During running condition of unit, 6.6 KV auxiliary supply fed to 6.6 KV CW switchgear & 6.6 KV/ 415 V compressor transformer from 6.6 KV station Bus OSC only. Hence, on tripping of station transformer# 3, no 6.6 KV supply shall be available to CWP/ ACWP

& compressors as per SLD enclosed even though unit buses 3SA & 3SB fed from respective UATs

10. Extract of Rajasthan report

On dated 01.08.2018, STPS Unit # 3 & 4 were running on approximate 190 MW load on each unit & Unit# 1, 2, 5 & 6 were in de-synchronized condition and connected feeders on 220 kV Buses were as follows:-

Bus-1A:

220 kV STPS-Suratgarh-1
220 kV STPS-Sriganganagar
220 kV STPS-Ratangarh-1
Station Transformer-1

Bus-1B

220 kV side of ILT-1
Station Transformer-3
Station Transformer -5&6

Bus-2

220 kV STPS-Suratgarh-2
220 kV STPS-Ratangarh-2
220 kV STPS-Bhadra
ILT-2
Station Transformer-4

The Bus Coupler Breaker between 220 KV Bus-1A & 220 KV Bus-2 was closed & the Sectionalizer breaker between 220 KV Bus-1A & 220 KV Bus-1B was also closed.

Suddenly at 12:08 hrs on dated 01.08.2018, failure/ bursting of B- phase CT occurred on 220 KV STPS-Ratangarh-2, and further converted into Bus fault. As this feeder was connected on 220 kV Bus-2, all the feeders/transformers connected to this bus immediately tripped due to operation of bus bar protection. The E/F protection of 220 kV side of Interlinking Transformer -1 was operated and this caused the tripping of 400 kV side breaker of Interlinking Transformer -1 on inter tripping.

The details of tripping are as under:-

S. No.	Unit/ Feeder	Time of Tripping	Cause of Tripping
1.	220 KV Bus Coupler	12:08:39.467 hrs	Bus-2 Bus Bar Protection operated
2.	220 KV STPS- Ratangarh-2	12:08:39.468 hrs	Bus-2 Bus Bar Protection operated
3.	220 KV STPS- Suratgarh-2	12:08:39.470 hrs	Bus-2 Bus Bar Protection operated
4.	Station Transformer-4	12:08:39.473 hrs	Bus-2 Bus Bar Protection operated
5.	220 KV STPS- Bhadra	12:08:39.475 hrs	Bus-2 Bus Bar Protection operated
6.	ILT-2 (220 KV side)	12:08:39.480 hrs	Bus-2 Bus Bar Protection operated & Earth Fault Protection Operated
7.	ILT-1 (220 KV side)	12:08:39.488 hrs	Earth Fault Protection Operated
8.	ILT-1 (400 KV side)	12:08:39.493 hrs	Inter Tripping with 220 KV side breaker
9.	ILT-2 (400 KV side)	12:08:39.494 hrs	Inter Tripping with 220 KV side breaker
10.	400 KV side ILT-1 & 2 Tie	12:08:39.496 hrs	Inter Tripping with 400 KV side main breaker of ILT-1 or ILT-2
11.	Unit# 3	12:08:45.573 hrs	Disturbance in auxiliary supply due to tripping of Station Transformer#4
12.	Unit# 4	12:08:51.526 hrs	Aux. power supply failure

Note: - All outgoing feeders connected at 220 KV Bus-1A, 220 KV Bus-1B & 400 KV Bus-1 & 2 were healthy.

SoE as per Rajasthan report:

35 220 kv STPS-SGMR TRIPE from GPS
36 INTERCONNECTOR# 1 (X#14) 18:59:59.990 # 1 Syn Pluse
Auto Deleted from Log Summary

Port status Nov 2017
Port #1 failure
A 19:59:59.990 #

SURATGARH THERMAL POWER STATION

Station number 1

1 Aug 2018 20:26:41 m

List historical buffer

Point numbers (All, or up to ten point numbers)? all

Time (All, or start time)? 12:06:00.00

Enter date MM/DD/YY 08/01/18

Stop time? 12:09:00.00

Enter date MM/DD/YY 08/01/18

Number of historical events (1 to 1999, or All)? all

N 12:08:39.467 # 4 220 kv Bus-Coupler Trip
N 12:08:39.468 # 9 220 kv STPS-Ratangarh-II Breaker Trip
N 12:08:39.470 # 3 220 kv STPS-Suratgarh-II Trip
N 12:08:39.473 # 16 Station Transformer-4 Breaker Trip
N 12:08:39.475 # 34 220 kv STPS-Bhadra Trip
N 12:08:39.480 # 14 220 kv side AT-2 Breaker Trip
N 12:08:39.488 # 12 220 kv side AT-1 Breaker Trip
N 12:08:39.493 # 29 AT-1 400 kv side Breaker Trip
N 12:08:39.494 # 30 AT-2 400 kv side Breaker Trip
N 12:08:39.496 # 33 400 kv Side AT-1&2 Tie Breaker Trip
N 12:08:45.573 # 19 Unit-4 Breaker Trip
N 12:08:51.526 # 18 Unit-3 Breaker Trip

LH complete

>_

11. SCADA Analog data and SoE:

Time	S/S Name	Voltage Level (in kV)	Element Name	Element Type	Status
12:08:38,427	SURAT_THER	220kV	03MBC	Circuit Breaker	disturbe
12:08:38,427	SURAT_THER	220kV	E_13_B2(BHDRA-1)	Circuit Breaker	disturbe
12:08:38,449	SURAT_THER	220kV	E_01_B1(SURAT-2)	Circuit Breaker	disturbe
12:08:38,453	SURAT_THER	220kV	E_07_B2(RATAN-2)	Circuit Breaker	Close
12:08:38,453	SURAT_THER	220kV	E_07_B2(RATAN-2)	Circuit Breaker	disturbe
12:08:38,456	SURAT_THER	220kV	03MBC	Circuit Breaker	Close
12:08:38,456	SURAT_THER	220kV	E_13_B2(BHDRA-1)	Circuit Breaker	Close
12:08:38,456	SURAT_THER	220kV	17ST4	Circuit Breaker	disturbe
12:08:38,479	SURAT_THER	400kV	17TIE	Circuit Breaker	disturbe
12:08:38,480	SURAT_THER	400kV	16AT1	Circuit Breaker	disturbe
12:08:38,482	SURAT_THER	400kV	17TIE	Circuit Breaker	Close
12:08:38,484	SURAT_THER	400kV	F_02_C(U4)	Circuit Breaker	disturbe
12:08:38,451	SURAT_THER	400kV	F_02_C(U4)	Circuit Breaker	Close
12:08:38,885	SURAT_THER	400kV	16AT1	Circuit Breaker	Close
12:08:38,970	SURAT_THER	220kV	17ST4	Circuit Breaker	Close
12:08:39,270	SURATGARH	220kV	E_20(SURTP-1)	Circuit Breaker	disturbe
12:08:39,280	SURATGARH	220kV	E_02(SURTP-2)	Circuit Breaker	Open
12:08:40,072	SURATGARH	220kV	E_20(SURTP-1)	Circuit Breaker	Close
12:08:41,006	SRIGANGAGR	132kV	D_01(SGNGR-1)	Circuit Breaker	disturbe
12:08:44,567	SURAT_THER	400kV	F_02_C(U4)	Circuit Breaker	disturbe
12:08:44,578	SURAT_THER	400kV	F_02_C(U4)	Circuit Breaker	Close

Time Synch error in SCADA SoE

12. As per Remedial Measures Report of Rajasthan:

- a. Setting of back up earth fault protection for ILT#1 & ILT#2 has been checked and revised as suggested by “sub-committee on relay/protection under task force for power system analysis under contingencies” of NRPC.

Name of protection	Earlier setting	Existing setting
Back up earth fault protection (High set) for 400 KV side	2.4 Amp	3.64 Amp
Back up earth fault protection (High set) for 220 KV side	3.6 Amp	6.6 Amp

- b. Tan Delta test of all CTs will be carried out during annual shut down to ascertain their healthiness.

13. Preliminary Report, DR/EL (only event logger details, DR not available as numerical bus bar/ back up earth fault protection is not available) and detailed report has been received from Rajasthan.

Action Points:

1. Reason of non-availability of UAT (unit auxiliary transformer) needs to be looked into.
2. Setting correction in back up earth fault protection of 400/220 kV ICT-1 & 2 needs to be shared along with time delay setting.
3. Time synchronization & status of SCADA SoE needs to be checked and corrected.
4. Phase Sequence error at 220 kV Suratgarh TPS needs to be checked as fault was in Yellow-phase (as per PMU data) but in Rajasthan report it was reported as Blue-phase to earth fault?
5. DR/EL should be available for event analysis, numerical protection to be implemented at 220 kV Suratgarh TPS (Bus Bar and ICT protection).

Tripping couldn't discuss due to non-representation from RRVUNL.

Q. Multiple element tripping and SPS operation at Jhakri/Rampur/Karcham complex at 04:02hrs of 29th Aug 2018

Event category: GD-1

Generation loss: 1230 MW

Loss of load: Nil

Data Summary received/available at NRLDC:

Description	Reference	Fault Info	Remarks
Fault Clearance Time	As per PMU data	100ms	
Phase of the fault	As per PMU data	B-N fault	


Description	Utilities	Present Status	Remarks
Availability of Digital Data (SCADA Data)	NR and UP	Available	
DR/ EL	NJPC	Received	Not received from Jhakri
	JSW	Not Received	
	POWERGRID	Received	
Preliminary Report	NJPC	Received	Not received from Jhakri
	JSW	Not Received	
	POWERGRID	Received	
Detailed Report	NJPC	Not	

		Received	
	JSW	Not Received	

Description	Clauses	Utility	Remarks
Violation of Clauses	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2) 3. 43.4.A & 43.4.D of CEA Technical Standard for Construction of Electrical Plants and Electric Lines; CEA (Technical standards for connectivity to the Grid) Regulation, 2007: Schedule Part 1. (6.1, 6.2, 6.3, 6.4)	NJPC	1. Detailed Report didn't provide 2. Adequately Sectionalized and graded protective relaying system 3. Incorrect/ mis-operation / unwanted operation of Protection system
	1. IEGC 5.2.r & 5.9.6.c (VI) 2. CEA grid Standard 15.3	JSW	1. DR/EL, Preliminary report within 24hrs 2. Detailed Report not received

Based on above information description of the events is:

1. Connectivity Diagram:



2. 400 kV Rampur is connected with Jhakri D/C, Nalagarh D/C. 400 kV Rampur have six unit of 68.67 MW capacity. 400 kV Jhakri is connected with Rampur D/C, Panchkula D/C and Karcham D/C. 400 kV Jhakri have six unit of 250 MW and 400 kV Karcham have four units of 250MW.
3. At 04:02hrs of 29-Aug-18, B-N fault (94km from Rampur end) occurred in both 400kV Rampur–Nalagarh ckt.
4. 400kV Rampur–Nalagarh ckt-1 was successfully auto reclosed at both ends. However, 400kV Rampur–Nalagarh ckt-2 was auto reclosed successfully at Nalagarh (PG) but CB failed to close at Rampur end resulting in tripping of all CBs at Rampur on pole discrepancy.
5. Due to the above incident, SPS operated at Nathpa Jhakri and Rampur causing tripping of 2 units each at Rampur & Nathpa Jhakri hydro station.
6. Due to SPS operation at Karcham, units-2 & 4 went into NLNE mode (No load Not Excited).
7. Name of the tripped elements are as below:
 - 400 kV Rampur(NJPC)–Nalagarh(PG) ckt-2
 - Unit#5 at 400kV Nathpa-Jhakri(NJPC)
 - Unit#6 at 400kV Nathpa-Jhakri(NJPC)
 - Unit#1 at 400kV Rampur(NJPC)


- Unit#2 at 400kV Rampur(NJPC)
- Unit#2 at 400kV Karcham Wangtoo (NLNE mode)
- Unit#4 at 400kV Karcham Wangtoo (NLNE mode)

8. SPS logic for generation (Jhakri/Karcham/Rampur) complex:


Case	Contingency	Action
Case-1	Load on any of the lines at Jhakri or Rampur towards Nalagarh exceeds 850 MW	Trip 1 unit of Wangtoo HPS, 1 unit of Jhakri HEP & 1unit of Rampur HEP
Case-2	400 kV bus voltage at Wangtoo drops below 395 kV	Trip 2 units of Wangtoo HPS
Case-3	Any two lines of Jhakri or Rampur HPS trip	Trip 2 units of Jhakri, 2 units of Rampur HPS and 2 units of Wangtoo HPS
Case-4	Both 400 kV Wangtoo-Abdullapur lines at Wangtoo trip	Trip 2 units of Wangtoo HPS
Case-5	Power Flow of any outgoing line of Rampur or Jhakri exceed by 800MW	Initiate the Alarm to the operators at Jhakri, Rampur & Karcham

9. As per NJPC Report and DR details:


DR: 400kV Rampur(end)-Nallagarh-1




DR: 400kV Rampur-Nalagarh(end)-1



DR: 400kV Rampur(end)-Nalagarh-2




DR: 400kV Rampur-Nalagarh(end)-2



10. PMU plots:


PMU Plot of frequency at Nathpa Jhakri(NJPC)


04:02hrs/29-Aug-18




PMU Plot of frequency at Karcham

04:02hrs/29-Aug-18






11. As per SCADA data:




SLD of 400kV Rampur(NJPC) after the incident

04:03hrs/29-Aug-18




SLD of 400kV Nathpa Jhakri(NJPC) before the incident

04:01hrs/29-Aug-18




SLD of 400kV Nathpa Jhakri(NJPC) after the incident

04:03hrs/29-Aug-18




SLD of 400kV Karcham(JSW) before the incident

04:01hrs/29-Aug-18



SLD of 400kV Karcham (JSW) after the incident

04:04hrs/29-Aug-18



12. As per SCADA SoE:

Time	Station	Voltage	Element	Device	Status
04:00:00,000	KARCHAM	400kV	G2H02	Circuit Breaker	Open
04:00:00,000	KARCHAM	400kV	G4H04	Circuit Breaker	Open
04:00:00,000	KARCHAM	400kV	G2H02	Circuit Breaker	Close
04:00:00,000	KARCHAM	400kV	G4H04	Circuit Breaker	Close
04:01:41,743	RAMPUR	400kV	02G2	Protection Trip	App
04:06:43,652	RAMPUR	400kV	01G1	Protection Trip	App
04:08:49,863	RAMPUR	400kV	01G1	Protection Trip	Disp
04:09:12,782	RAMPUR	400kV	02G2	Protection Trip	Disp

13. As per PMU & SCADA data:


- B-N fault occurred at 04:02:14.440hrs and cleared in 80ms.
- Dip in frequency of around 0.1Hz is observed.

- A sharp dip in frequency observed at 04:02:15.280hrs, indicating tripping of units before auto-reclosure attempt of faulted ckts

14. Preliminary Report, DR/EL has been received from Rampur and POWERGRID within 24hrs however detailed report is still awaited from Rampur. Preliminary Report, DR/EL and detailed report is still awaited from Jhakri and JSW.

Points for Discussion:

1. Non closing of B-phase CB of 400kV Nalagarh-Rampur-2 at Rampur end to be looked into.
2. Tripping of two units each at Karcham, Jhakri and Rampur is as per the case-2 of SPS logic i.e. tripping of any two lines from Jhakri or Rampur. However, only one ckt (400kV Rampur-Nalagarh-2) tripped. Therefore, SPS logic needs to be checked.
3. It seems from PMU frequency data that generating units tripped before auto-reclosing attempt of lines. The following needs to be shared w.r.t. SPS:
 - *Logic calculation time.*
 - *Time in which tripping command sent to units after meeting the condition for SPS.*
 - *Logic for various SPS conditions checking.*
4. On 07th Sep 2018 at 16:20hrs, 400 kV Rampur-Nalagarh ckt-2 tripped on transient nature of fault. At that time also SPS of Jhakri/Karcham/Rampur complex operated (Case-1 operation) although line MW was not beyond 850MW. SCADA data plot is as below:



5. The reporting of SCADA SoE at NRLDC and its time synchronization to be looked into and resolved

NJPC representative informed during the meeting:

1. Non closing of B-phase CB of 400kV Nalagarh-Rampur-2 at Rampur end to be looked into: A/R was send by the relay but A/R was not operated due to improper operation of PoW (Point on Wave)/ CSD (Control Switching Device). This issue would be taken up with OeM Alstom and corrected before 31st Dec 2018.
2. Tripping of two units each at Karcham, Jhakri and Rampur is as per the case-2 of SPS logic i.e. tripping of any two lines from Jhakri or Rampur. However, only one ckt (400kV Rampur-Nallagarh-2) tripped. Therefore, SPS logic needs to be checked: In SPS logic, all three phase input taken in series and it resulted into operation of SPS during opening of any of the phase of both the circuit. During this incident, fault was in 400 kV Rampur-Nalagarh ckt-2 and 400 kV Rampur-Nalagarh ckt-1 was also A/R and it resulted into operation of SPS Case-3. Three phase input to SPS should be taken in parallel so that tripping of all three phase would initiate SPS operation. Modification would be done till 31st Dec 2018.
3. On 07th Sep 2018 at 16:20hrs, 400 kV Rampur-Nalagarh ckt-2 tripped on transient nature of fault. At that time also SPS of Jhakri/Karcham/Rampur complex operated (Case-1 operation) although line MW was not beyond 850MW: Power flow sensed by the relay is 884 MW. SPS may be tripped immediately. SPS logic time would be separately checked and it would be intimated.
4. The reporting of SCADA SoE at NRLDC and its time synchronization to be looked into and resolved: Time synch error of SCADA SoE would be resolved within 15days

POWERGRID informed that PoW/ CSD device used for reactor switching or ICT switching, in general it is not used in 400 kV transmission line. Necessity of PoW on transmission line needs to be relooked.

NRPC suggested SJVNL to resolve the issue of SPS and non-closing of breaker after reclosing command initiation.